UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION III
1650 Arch Street
Philadelphia, Pennsylvania 19103-2029

Via Facsimile and Federal Express

December 3, 2007

Mr. Gene F. Bailey, Managing Partner
Mr. J. R. Griffin, Partner
SGB, LLC
4212 South River Road
South Boston, VA 24592

Mr. Nasser D. Haverim
Managing Partner
SGB, LLC
c/o Mission Dyehouse LLC
764 S. Stanford Ave.
Los Angeles, CA 90021

IMO: EPA Docket No. TSCA-03-2008-0016

Dear Messrs. Bailey, Griffin, Haverim:

I have enclosed a true and correct copy of the final Consent Agreement, the original of which was filed today with the Regional Hearing Clerk. The filing of this Agreement resolves the violations discovered during EPA's June 2005 inspection. We appreciate your efforts to resolve this matter.

As you are aware, EPA remains concerned about the continued presence of the PCB transformer (Serial No. 7028572) at the SGB facility, which, in its current state of disrepair, may render it subject to the requirements for disposal. In addition, in accordance with 40 C.F.R. § 761.30(a)(x), SGB is to have initiated cleanup procedures for the leak that occurred in August no later than 48 hours from discovery of such leak and perform daily inspections to verify containment of the leak. Failure to comply with the PCB regulations may subject SGB, LLC, to additional enforcement proceedings by EPA. Please continue to inform Alizabeth Olhasso as to the status of the transformer. You may reach Ms. Olhasso at 215-814-2165 or olhasso.alizabeth@epa.gov. Of course, you may always contact me at 215-814-2689 or sharke.janet@epa.gov. We look forward to hearing from you.

Sincerely,

Janet E. Sharke (3WC33)
Senior Assistant Regional Counsel

Enclosures

cc: A. Olhasso (3WC33)