SAMPLE_NAME	SAMPLE #	COLLECTDATE	TIME	RECEIVEDATE	MEASUREDDATE	TIME
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	5:43:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	3:39:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	3:39:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	3:39:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	3:39:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	5:43:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	5:43:00 PM
Base Exchange 4514	AD20796	8/11/2016	3:28:00 PM	08/12/2016	8/11/2016	3:39:00 PM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/9/2016	1:39:00 PM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/9/2016	1:39:00 PM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/9/2016	1:39:00 PM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/9/2016	1:39:00 PM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Buikding 4455	AD20255	8/9/2016	1:39:00 PM	08/10/2016	8/9/2016	1:39:00 PM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/23/2016	3:29:00 PM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/23/2016	3:29:00 PM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/23/2016	3:29:00 PM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/23/2016	3:29:00 PM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4455	AD21932	8/23/2016	3:29:00 PM	08/24/2016	8/23/2016	3:29:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/9/2016	1:18:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/9/2016	1:18:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/9/2016	1:18:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/9/2016	1:18:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/9/2016	1:18:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/10/2016	6:56:00 PM
Building 4456	AD20256	8/9/2016	1:18:00 PM	08/10/2016	8/16/2016	6:42:00 PM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/23/2016	3:19:00 PM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/23/2016	3:19:00 PM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/23/2016	3:19:00 PM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/23/2016	3:19:00 PM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/24/2016	9:20:00 AM
Building 4456	AD21933	8/23/2016	3:19:00 PM	08/24/2016	8/23/2016	3:19:00 PM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/10/2016	10:56:00 AM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/9/2016	1:02:00 PM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/9/2016	1:02:00 PM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/9/2016	1:02:00 PM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/9/2016	1:02:00 PM
Building 50	AD20253	8/9/2016	1:02:00 PM	08/10/2016	8/10/2016	10:56:00 AM

Building 50	AD20253	8/9/2016 1:02:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Building 50	AD20253	8/9/2016 1:02:00 PM	08/10/2016	8/9/2016 1:02:00 PM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/23/2016 3:02:00 PM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/23/2016 3:02:00 PM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/23/2016 3:02:00 PM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/23/2016 3:02:00 PM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 50	AD21930	8/23/2016 3:02:00 PM	08/24/2016	8/23/2016 3:02:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/9/2016 12:51:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/9/2016 12:51:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/9/2016 12:51:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/9/2016 12:51:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/9/2016 12:51:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/10/2016 6:31:00 PM
Building 928	AD20254	8/9/2016 12:51:00 PM	08/10/2016	8/16/2016 6:17:00 PM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/23/2016 2:49:00 PM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/23/2016 2:49:00 PM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/23/2016 2:49:00 PM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/23/2016 2:49:00 PM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Building 928	AD21931	8/23/2016 2:49:00 PM	08/24/2016	8/23/2016 2:49:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 5:43:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 3:16:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 3:16:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 3:16:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 3:16:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 5:43:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 5:43:00 PM
CDC I Bldg 4456	AD20794	8/11/2016 3:16:00 PM	08/12/2016	8/11/2016 3:16:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/9/2016 2:50:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/9/2016 2:50:00 PM

Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/9/2016 2:50:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/9/2016 2:50:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/9/2016 2:50:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/10/2016 7:47:00 PM
Clinic Bldg 1300	AD20259	8/9/2016 2:50:00 PM	08/10/2016	8/16/2016 7:31:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Field Blank	AD20260	8/9/2016 8:31:00 AM	08/10/2016	8/10/2016 8:12:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/9/2016 2:28:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/9/2016 2:28:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/9/2016 2:28:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/9/2016 2:28:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/9/2016 2:28:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/10/2016 7:22:00 PM
Honor Guard Bldg 47	AD20258	8/9/2016 2:28:00 PM	08/10/2016	8/16/2016 7:06:00 PM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/9/2016 2:02:00 PM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/9/2016 2:02:00 PM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/9/2016 2:02:00 PM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/9/2016 2:02:00 PM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/10/2016 10:56:00 AM
Moton Ct	AD20257	8/9/2016 2:02:00 PM	08/10/2016	8/9/2016 2:02:00 PM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/23/2016 3:42:00 PM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/23/2016 3:42:00 PM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/23/2016 3:42:00 PM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/23/2016 3:42:00 PM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/24/2016 9:20:00 AM
Moton Ct	AD21934	8/23/2016 3:42:00 PM	08/24/2016	8/23/2016 3:42:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 5:43:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 3:28:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 3:28:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 3:28:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 3:28:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 5:43:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 5:43:00 PM
Skills Devlopment 4472	AD20795	8/11/2016 3:39:00 PM	08/12/2016	8/11/2016 3:28:00 PM

8/12/2016 7:51:00 AM

PARAMETER	RESULT	UNIT	LOCATION	ANALYST	METHOD
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.04	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.74	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	409	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	26.7	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	0.62	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.06	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.62	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	393	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.0	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	0.71	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Free Residual Chlorine	0.04	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.70	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	403	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.9	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	J.PENNELLA
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Total Residual Chlorine	0.79	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Bromoacetic Acid	<1.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromochloroacetic Acid	6.72	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromodichloromethane	15.1	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoform	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroacetic Acid	1.03	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroform	39.9	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromoacetic Acid	1.35	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromochloromethane	4.47	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dichloroacetic Acid	21.5	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.07	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Internal Standard	5.00	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Internal Standard	100	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
pH	7.60	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	396	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Surrogate	5.03	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate	9.63	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate1	5.03	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Temperature	26.8	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	P	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Haloacetic Acids	43.68	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Total Residual Chlorine	1.10	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Total Trihalomethanes	59.5	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Trichloroacetic Acid	18.8	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Free Residual Chlorine	0.20	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.73	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	398	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.5	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	J.PENNELLA
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Total Residual Chlorine	1.41	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.18	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.71	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	393	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	24.6	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL

Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	2.19	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Free Residual Chlorine	0.11	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.87	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	394	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.6	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	J.PENNELLA
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Total Residual Chlorine	2.7	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Bromoacetic Acid	<1.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromochloroacetic Acid	4.75	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromodichloromethane	15.9	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoform	<1.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroacetic Acid	1.34	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroform	41.3	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromoacetic Acid	<1.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromochloromethane	4.46	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dichloroacetic Acid	16.4	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.06	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Internal Standard	5.00	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Internal Standard	100	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
pH	7.59	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	396	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Surrogate	5.08	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate	9.64	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate1	4.95	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Temperature	26.2	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Haloacetic Acids	37.74	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Total Residual Chlorine	0.36	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Total Trihalomethanes	62.7	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Trichloroacetic Acid	18.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Free Residual Chlorine	0.03	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.61	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	399	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.4	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	J.PENNELLA
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Total Residual Chlorine	0.43	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.06	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.65	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	408	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	27.2	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	0.90	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Bromoacetic Acid	<1.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromochloroacetic Acid	7.39	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromodichloromethane	18.0	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoform	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroacetic Acid	1.38	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroform	44.3	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromoacetic Acid	1.42	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromochloromethane	4.78	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dichloroacetic Acid	24.3	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Free Residual Chlorine	0.12	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Internal Standard	5.00	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Internal Standard	100	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
pH	7.60	unit	Bioenviromental Engineering Element	C	R.SIBERT

Specific Conductance	393	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Surrogate	5.15	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate	9.77	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate1	5.03	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Temperature	26.2	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Total Haloacetic Acids	47.50	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Total Residual Chlorine	1.36	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Total Trihalomethanes	67.1	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Trichloroacetic Acid	19.4	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromodichloromethane	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoform	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroform	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromochloromethane	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Internal Standard	5.00	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate	4.91	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate1	4.82	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Total Trihalomethanes	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoacetic Acid	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromochloroacetic Acid	5.05	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromodichloromethane	13.3	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Bromoform	ND	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroacetic Acid	1.08	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Chloroform	34.6	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromoacetic Acid	1.05	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dibromochloromethane	3.77	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Dichloroacetic Acid	17.4	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Free Residual Chlorine	0.06	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Internal Standard	100	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Internal Standard	5.00	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
pH	7.70	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	394	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Surrogate	9.50	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate	4.89	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Surrogate1	4.91	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Temperature	26.0	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Total Haloacetic Acids	37.93	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Total Residual Chlorine	0.58	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Total Trihalomethanes	51.7	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Trichloroacetic Acid	18.4	ug/L	Bioenviromental Engineering Element	C	M.INAMDAR
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.03	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.71	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	392	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	24.7	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	0.18	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Free Residual Chlorine	0.03	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.79	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	412	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	26.1	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	J.PENNELLA
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	J.PENNELLA
Total Residual Chlorine	0.21	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
Escherichia coli	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Free Residual Chlorine	0.05	mg/L	Bioenviromental Engineering Element	C	R.SIBERT
pH	7.64	unit	Bioenviromental Engineering Element	C	R.SIBERT
Specific Conductance	406	umhos/cm	Bioenviromental Engineering Element	C	R.SIBERT
Temperature	26.9	Degree C	Bioenviromental Engineering Element	C	R.SIBERT
Thiosulfate	P		Bioenviromental Engineering Element	C	B.HALL
Total Coliforms	A	/100 mL	Bioenviromental Engineering Element	C	B.HALL
Total Residual Chlorine	0.27	mg/L	Bioenviromental Engineering Element	C	R.SIBERT

S
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
EPA 552.3 Rev 1.
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 9223B,22nd ed
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 4500-H B
SM 2510B
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
SM 2550B
IODINE
SM 9223B,22nd ed
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE

SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
EPA 552.3 Rev 1.
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 9223B,22nd ed
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 4500-H B
SM 2510B
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
SM 2550B
IODINE
SM 9223B,22nd ed
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
EPA 552.3 Rev 1.
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 4500-H B

SM 2510B
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
SM 2550B
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
SM 4500-H B
SM 2510B
EPA 552.3 Rev 1.
EPA 524.2 Rev4.1
EPA 524.2 Rev4.1
SM 2550B
EPA 552.3 Rev 1.
SM 4500-Cl G
EPA 524.2 Rev4.1
EPA 552.3 Rev 1.
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G
SM 9223B,22nd ed
SM 4500-Cl G
SM 4500-H B
SM 2510B
SM 2550B
IODINE
SM 9223B,22nd ed
SM 4500-Cl G