Devon Energy Corporation
333 West Sheridan Avenue
Oklahoma City, OK 73102

405 235 3611 Phone
www.devonenergy.com

October 29, 2019

US EPA Region 8
1595 Wynkoop Street
Denver, CO 80202-1129

Attn: EPA Administrator

As required by the Code of Federal Regulations Title 40 §60.4, please find enclosed copies of the Title 40 §60.5360 (NSPS OOOO) and Title 40 §60.5360a (NSPS OOOOa) Annual Report provided to the Wyoming Department of Environmental Quality.

Sincerely,
(b) (6) [redacted]

Jason Robison
EHS Supervisor
(405) 552-2314
Jason.Robison@dvn.com

Devon Energy Corporation
333 West Sheridan Avenue
Oklahoma City, OK 73102

405 235 3611 Phone
www.devonenergy.com

October 28, 2019

Wyoming Department of Environmental Quality
Air Quality Division
200 West 17th Street, 3rd Floor
Cheyenne, WY 82002

Dear Sir or Madam:

As required by the Code of Federal Regulations Title 40 §60.5360 (NSPS OOOO) and Title 40 §60.5360a (NSPS OOOOa), Devon Energy is submitting the annual compliance report. The attached OOOO/OOOOa report is for the following timeframe: August 3, 2018 – August 2, 2019.

Please note Devon previously requested to align the reporting date for all annual reports required by both of these NSPS and submit concurrently on October 31.

Devon is including the following information:

- Table 1 – LDAR Survey Data
- Table 2 – Hydraulically Fractured Well Flowback Data
- Table 3 – Storage Tanks

Devon did not have NSPS OOOO and/or NSPS OOOOa applicable Pneumatic Controllers, Pneumatic Pumps, Centrifugal Compressors or Reciprocating Compressor affected facilities during this reporting period. Therefore, tables for these equipment types are not provided.

In accordance with Title 40 §60.5360 and §60.5360a I, _____ Marty Summers, Manager of Production Engineering (Responsible Official) certify based on information and belief formed after reasonable inquiry, the statements and information in the attached NSPS OOOO/NSPS OOOOa documents are true, accurate, and complete.

Sincerely,
(b) (6) [redacted]

Marty Summers
Manager Production Engineering
(405)552-1486

NSPS OOOO and OOOOa Annual Report
Devon Energy
333 West Sheridan Avenue
Oklahoma City, OK 73102
Reporting Period: NSPS OOOOa August 2, 2018-August 3, 2019
Wyoming

Table 1 – LDAR Survey Data

SURVEY ID / WO	INSPECTION TYPE	FACILITY NAME	WELL LIST	LATITUDE (NAD 83)	LONGITUDE (NAD 83)	START DATE	FINISH DATE	PERFORMED BY	TRAINING/EXPERIENCE	AMBIENT TEMPERATURE	SKY CONDITION	MAXIMUM WIND SPEED	MONITORING INSTRUMENT USED	DEVIATION	SURVEY OUTCOME	COMPONENT	COUNT COMPONENT(S) WITH FUGITIVES DETECTED [1,2]	REPAIR METHOD [3]	SUCCESSFUL REPAIR DATE [4]	Comments
20698481	LDAR	BONER BROS 37-71 28 PAD 3	SDU BONER BROS FED 28-333771-4XPH - 4900930326, SDU BONER BROS FED 23-333771-2XPH - 4900930328, SDU BONER BROS FED 22-333771-1XPH - 4900930327, SDU BONER BROS FED 2128-333771-2XPH - 4900934953, SDU BONER BROS FED 21-173771-4XPH - 4900930325	(b) (9) [redacted]		2/20/19 7:36 AM	2/20/19 9:04 AM	(b) (6) [redacted]	Received IR Camera Operations & Functionality Training	0	Clear	12	IR Camera	No	Repaired During Initial	CON	1	TA	2/20/2019	
20546001	LDAR	BONER BROTHERS 32 BATTERY	BONER BROTHERS 37-71 32 3PH - 4900929706, BONER BROTHERS 37-71 32 4PH - 4900929709, SDU BONER BROS FED 29-203771-3XPH - 4900933697, SDU BONER BROS FED 29-203771-4XPH - 4900933696			8/8/2018 10:15	8/8/2018 11:49		Received IR Camera Operations & Functionality Training	79	Clear	2	IR Camera	No	Repaired During Initial	TTH	8	CS	8/8/2018	
20594206	LDAR	BONER BROTHERS 32 BATTERY	BONER BROTHERS 37-71 32 3PH - 4900929706, BONER BROTHERS 37-71 32 4PH - 4900929709, SDU BONER BROS FED 29-203771-3XPH - 4900933697, SDU BONER BROS FED 29-203771-4XPH - 4900933696			2/20/19 10:13 AM	2/20/19 12:03 AM		Received IR Camera Operations & Functionality Training	10	Clear	11	IR Camera	No	Repaired During Initial	CON	1	TA	2/20/2019	
20625453	LDAR	BSD TENSLEEP CO2 FACILITY	BIG SAND DRAW UNIT 47 - 4901323426, BIG SAND DRAW UNIT 10 - 4901305496, BIG SAND DRAW UNIT 3-34 - 4901305478, BSDU 55 - 4901323446, BIG SAND DRAW UNIT 48 - 4901323439, BIG SAND DRAW UNIT 49 - 4901323427, BIG SAND DRAW UNIT 50 - 4901323428, BIG SAND DRAW			10/12/18 11:15 AM	10/12/18 2:10 PM		Received IR Camera Operations & Functionality Training	47	Clear	11	IR Camera	No	Repaired During Initial	TTH	1	CS	10/12/2018	
20719236	LDAR	BSD TENSLEEP CO2 FACILITY	BIG SAND DRAW UNIT 47 - 4901323426, BIG SAND DRAW UNIT 10 - 4901305496, BIG SAND DRAW UNIT 3-34 - 4901305478, BSDU 55 - 4901323446, BIG SAND DRAW UNIT 48 - 4901323439, BIG SAND DRAW UNIT 49 - 4901323427, BIG SAND DRAW UNIT 50 - 4901323428, BIG SAND DRAW			6/5/19 7:30 AM	6/5/19 12:20 PM		Received IR Camera Operations & Functionality Training	49	Partly Cloudy	4	IR Camera	No	No Repair Required					
20645796	LDAR	CONLEY DRAW 09-043870-1XNH	CONLEY DRAW 09-043870-1XNH - 4900932896			11/19/18 9:19 AM	11/19/18 9:56 AM		Received IR Camera Operations & Functionality Training	36	Overcast	4	IR Camera	No	No Repair Required					
20741286	LDAR	CONLEY DRAW 09-043870-1XNH	CONLEY DRAW 09-043870-1XNH - 4900932896			5/28/19 7:41 AM	5/28/19 8:39 AM		Received IR Camera Operations & Functionality Training	41	Mostly Cloudy	7	IR Camera	No	No Repair Required					
20525442	LDAR	COSNER 22-15 1&2XPH & 7COSNER 27 BATTERY	COSNER FED 22-154372-1XPH - 4900562830, COSNER FED 22-154372-2XPH - 4900562210, T COSNER FED 274372-1PH - 4900562617, Y COSNER FED 274372-2PH - 4900562716			10/24/18 9:30 AM	10/24/18 10:30 AM		Received IR Camera Operations & Functionality Training	63	Clear	2	IR Camera	No	No Repair Required					
20719225	LDAR	COSNER 22-15 1&2XPH & 7COSNER 27 BATTERY	COSNER FED 22-154372-1XPH - 4900562830, COSNER FED 22-154372-2XPH - 4900562210, T COSNER FED 274372-1PH - 4900562617, Y COSNER FED 274372-2PH - 4900562716			4/25/19 3:10 PM	4/25/19 3:45 PM		Received IR Camera Operations & Functionality Training	52	Mostly Cloudy	18	IR Camera	No	No Repair Required					
20625443	LDAR	COSNER FED 10-034372-3XPH/4XPH BATTERY	COSNER FED 10-034372-3XPH - 4900562844, COSNER FED 10-034372-4XPH - 4900562170			10/17/18 7:30 AM	10/17/18 8:30 AM		Received IR Camera Operations & Functionality Training	38	Clear	2	IR Camera	No	No Repair Required					
20719226	LDAR	COSNER FED 10-034372-3XPH/4XPH BATTERY	COSNER FED 10-034372-3XPH - 4900562844, COSNER FED 10-034372-4XPH - 4900562170			4/30/19 1:28 PM	4/30/19 2:30 PM		Received IR Camera Operations & Functionality Training	80	Overcast	19	IR Camera	No	No Repair Required					
20625444	LDAR	COTTONWOOD DRAW 38-71 9 BATTERY	COTTONWOOD DRAW UNIT 38-71 9-1FH - 4900930571, COTTONWOOD DRAW UNIT 38-71 9-2FH - 4900930573, COTTONWOOD DRAW UNIT 38-71 9-1PH - 4900929876, COTTONWOOD DRAW UNIT 38-71 9-2PH - 4900929878			10/2/18 10:06 AM	10/2/18 10:29 AM		Received IR Camera Operations & Functionality Training	64	Mostly Cloudy	2	IR Camera	No	Repaired During Initial	TTH	3	CS	10/2/2018	
20719227	LDAR	COTTONWOOD DRAW 38-71 9 BATTERY	COTTONWOOD DRAW UNIT 38-71 9-1FH - 4900930571, COTTONWOOD DRAW UNIT 38-71 9-2FH - 4900930573, COTTONWOOD DRAW UNIT 38-71 9-1PH - 4900929876, COTTONWOOD DRAW UNIT 38-71 9-2PH - 4900929878			4/12/19 10:03 AM	4/12/19 11:01 AM		Received IR Camera Operations & Functionality Training	12	Overcast	27	IR Camera	No	Repaired During Initial	CON	2	TA	4/12/2019	
20600675	LDAR	CROW UNIT 37-69 16-4TH - 4900929587	CROW UNIT 37-69 16-4TH - 4900929587, CU DOWNS FED 15-223769-2XTPH - 4900933547, CU DOWNS FED 09-043769-CXTPH - 4900933550, CU DOWNS FED 15-223769-1XTPH - 4900933545, CROW UNIT 37-69 16 1TH - 4900929318			3/30/19 10:45 AM	3/30/19 11:30 AM		Received IR Camera Operations & Functionality Training	14	Clear	9	IR Camera	No	No Repair Required					
20725590	LDAR	CROW UNIT 37-69 16 BATTERY	CROW UNIT 37-69 16-4TH - 4900929587, CU DOWNS FED 15-223769-2XTPH - 4900933547, CU DOWNS FED 09-043769-CXTPH - 4900933550, CU DOWNS FED 15-223769-1XTPH - 4900933545, CROW UNIT 37-69 16 1TH - 4900929318			6/27/19 11:22 AM	6/27/19 1:19 PM		Received IR Camera Operations & Functionality Training	77	Mostly Cloudy	12	IR Camera	No	Repaired During Initial	TTH	6	CS	6/27/2019	
20684441	LDAR	CU DOWNS FED 35-263769-1XTPH	DOWNS FED 02-113669-2XTPH - 4900934798, CU DOWNS FED 35-263769-3XTPH - 4900934799, CU DOWNS FED 35-263769-1XTPH - 4900934915, CU DOWNS FED 35-263769-2XTPH - 4900934914			1/17/19 10:00 AM	1/17/19 11:00 AM		Received IR Camera Operations & Functionality Training	43	Mostly Cloudy	3	IR Camera	No	Repaired During Initial	VAL	1	TA	Jan 17, 2019	
20684441	LDAR	CU DOWNS FED 35-263769-1XTPH	DOWNS FED 02-113669-2XTPH - 4900934798, CU DOWNS FED 35-263769-3XTPH - 4900934799, CU DOWNS FED 35-263769-1XTPH - 4900934915, CU DOWNS FED 35-263769-2XTPH - 4900934914			1/17/19 10:00 AM	1/17/19 11:00 AM		Received IR Camera Operations & Functionality Training	43	Mostly Cloudy	3	IR Camera	No	Repaired During Initial	TTH	1	CS	Jan 17, 2019	
20748226	LDAR	CU DOWNS FED 35-263769-1XTPH	DOWNS FED 02-113669-2XTPH - 4900934798, CU DOWNS FED 35-263769-3XTPH - 4900934799, CU DOWNS FED 35-263769-1XTPH - 4900934915, CU DOWNS FED 35-263769-2XTPH - 4900934914			6/6/19 7:28 AM	6/6/19 8:13 AM		Received IR Camera Operations & Functionality Training	62	Clear	9	IR Camera	No	No Repair Required					
20690476	LDAR	CWDU T-55 FED 31-063871-3XPH	RU T-55 FED 303872-1TUH - 4900941626, RU T-55 FED 30-103973-CXTUH - 4900945449, RU T-55 FED 30-293971-4XTUH - 4900945450, CWDU T-55 FED 31-063871-3XPH - 4900929763			1/25/19 1:28 PM	1/25/19 1:50 PM		Received IR Camera Operations & Functionality Training	31	Clear	14	IR Camera	No	Repaired During Initial	FLA	1	TA	1/25/2019	
20755983	LDAR	CWDU T-55 FED 31-063871-3XPH	RU T-55 FED 303872-1TUH - 4900941626, RU T-55 FED 30-103973-CXTUH - 4900945449, RU T-55 FED 30-293971-4XTUH - 4900945450, CWDU T-55 FED 31-063871-3XPH - 4900929763			6/27/19 6:40 AM	6/27/19 7:38 AM		Received IR Camera Operations & Functionality Training	61	Clear	8	IR Camera	No	Repaired During Initial	CON	2	TA	6/27/2019	
20625445	LDAR	DAVIS FAMILY FED 09-044672-1XPH	DAVIS FAMILY FED 09-044672-1XPH - 4900562220			10/18/18 10:45 AM	10/18/18 12:00 PM		Received IR Camera Operations & Functionality Training	52	Clear	2	IR Camera	No	No Repair Required					
20719228	LDAR	DAVIS FAMILY FED 09-044672-1XPH	DAVIS FAMILY FED 09-044672-1XPH - 4900562220			4/25/19 9:20 AM	4/25/19 9:50 AM		Received IR Camera Operations & Functionality Training	53	Clear	6	IR Camera	No	No Repair Required					
20625446	LDAR	DILTS FED 08-054271-4XPH	DILTS FED 08-054271-4XPH - 4900562351			10/17/18 12:00 PM	10/17/18 1:30 PM		Received IR Camera Operations & Functionality Training	60	Clear	2	IR Camera	No	No Repair Required					
20719229	LDAR	DILTS FED 08-054271-4XPH	DILTS FED 08-054271-4XPH - 4900562351			4/25/19 10:40 AM	4/25/19 11:10 AM		Received IR Camera Operations & Functionality Training	55	Mostly Cloudy	12	IR Camera	No	No Repair Required					
20625791	LDAR	DILTS RANCH STATE 38-71 16 BATTERY	DILTS RANCH STATE 38-71 16 1PH - 4900929544, DILTS RANCH STATE 38-71 16 2PH - 4900930491, DILTS RANCH STATE 38-71 16 3PH - 4900929704, DILTS RANCH STATE 38-71 16 4PH - 4900930492			10/2/18 9:15 AM	10/2/18 9:53 AM		Received IR Camera Operations & Functionality Training	64	Mostly Cloudy	4	IR Camera	No	Repaired During Initial	TTH	3	CS	10/2/2018	
20719567	LDAR	DILTS RANCH STATE 38-71 16 BATTERY	DILTS RANCH STATE 38-71 16 1PH - 4900929544, DILTS RANCH STATE 38-71 16 2PH - 4900930491, DILTS RANCH STATE 38-71 16 3PH - 4900929704, DILTS RANCH STATE 38-71 16 4PH - 4900930492			4/12/19 8:00 AM	4/12/19 9:42 AM		Received IR Camera Operations & Functionality Training	21	Overcast	9	IR Camera	No	Repaired During Initial	CON	2	TA	4/12/2019	
20684442	LDAR	DOWNS 02-3669 PAD 2	CU DOWNS FED 35-263769-4XTPH - 4900934981, DOWNS FED 02-113669-1XTPH - 4900941586, DOWNS FED 02-113669-3XTPH - 4900934796, DOWNS FED 02-113669-4XTPH - 4900934793			1/24/19 11:00 AM	1/24/19 11:00 PM		Received IR Camera Operations & Functionality Training	18	Clear	8	IR Camera	No	No Repair Required					
20750289	LDAR	DOWNS 02-3669 PAD 2	CU DOWNS FED 35-263769-4XTPH - 4900934981, DOWNS FED 02-113669-1XTPH - 4900941586, DOWNS FED 02-113669-3XTPH - 4900934796, DOWNS FED 02-113669-4XTPH - 4900934793			6/26/19 2:32 PM	6/26/19 3:25 PM		Received IR Camera Operations & Functionality Training	82	Partly Cloudy	11	IR Camera	No	Repaired During Initial	TTH	3	CS	6/26/2019	
20758760	LDAR	DOWNS FED 07-183668-4XTPH	DOWNS FED 07-183668-4XTPH - 4900938356			7/17/19 11:30 AM	7/17/19 12:40 PM		Received IR Camera Operations & Functionality Training	80	Clear	11	IR Camera	No	No Repair Required					
20640472	LDAR	DOWNS FED 12-133669-3XTPH	DOWNS FED 12-133669-3XTPH - 4900930002, DOWNS FED 12-133669-4XTPH - 4900929967			11/15/18 10:25 AM	11/15/18 10:58 AM		Received IR Camera Operations & Functionality Training	49	Mostly Cloudy	5	IR Camera	No	No Repair Required					
20736353	LDAR	DOWNS FED 12-133669-3XTPH	DOWNS FED 12-133669-3XTPH - 4900930002, DOWNS FED 12-133669-4XTPH - 4900929967			5/8/19 9:21 AM	5/8/19 11:02 AM		Received IR Camera Operations & Functionality Training	46	Mostly Cloudy	5	IR Camera	No	Repaired During Initial	TTH	3	CS	5/8/2019	
20625447	LDAR	DURHAM RANCHES FED 32-134572-4XPH	DURHAM RANCHES FED 12-134572-4XPH - 4900562406			10/18/18 1:45 PM	10/18/18 3:00 PM		Received IR Camera Operations & Functionality Training	61	Clear	2	IR Camera	No	No Repair Required					
20719230	LDAR	DURHAM RANCHES FED 32-134572-4XPH	DURHAM RANCHES FED 12-134572-4XPH - 4900562406			4/24/19 2:40 PM	4/24/19 4:00 PM		Received IR Camera Operations & Functionality Training	64	Mostly Cloudy	10	IR Camera	No	No Repair Required					
20632720	LDAR	LEAVITT TRUST FED 334372-1PH	LEAVITT TRUST FED 334372-1PH - 4900563082			10/31/18 10:30 AM	10/31/18 11:45 AM		Received IR Camera Operations & Functionality Training	44	Clear	13	IR Camera	No	No Repair Required					
20719664	LDAR	LEAVITT TRUST FED 334372-1PH	LEAVITT TRUST FED 334372-1PH - 4900563082			4/30/19 10:20 AM	4/30/19 11:00 AM		Received IR Camera Operations & Functionality Training	28	Overcast	20	IR Camera	No	No Repair Required					
20631868	LDAR	LEAVITT TRUST FED 334372-2PH/3PH BATTERY	LEAVITT TRUST FED 334372-2PH - 4900563084, LEAVITT TRUST FED 334372-3PH - 4900563083			10/31/18 12:00 PM	10/31/18 1:30 PM		Received IR Camera Operations & Functionality Training	45	Clear	13	IR Camera	No	No Repair Required					
20719528	LDAR	LEAVITT TRUST FED 334372-2PH/3PH BATTERY	LEAVITT TRUST FED 334372-2PH - 4900563084, LEAVITT TRUST FED 334372-3PH - 4900563083			4/30/19 9:15 AM	4/30/19 10:00 AM		Received IR Camera Operations & Functionality Training	28	Overcast	17	IR Camera	No	No Repair Required					
20697537	LDAR	MADSEN STATE FED 21-36-1 FH	MADSEN STATE FED 21-36-1 FH - 4900934419			1/31/19 11:30 AM	1/31/19 12:30 PM		Received IR Camera Operations & Functionality Training	42	Clear	16	IR Camera	No	No Repair Required					
20759001	LDAR	MLT FED 20-173668-2XTPH	MLT FED 20-173668-2XTPH - 4900935553			7/17/19 1:35 PM	7/17/19 2:55 PM		Received IR Camera Operations & Functionality Training	89	Clear	12	IR Camera	No	Repaired During Initial	TTH	3	CS	7/17/2019	
20625452	LDAR	MOORE LAND TRUST 36-58 21 BATTERY	MLT FED 213668-2TPH - 4900929651, SSU MLT 16-093668-2XNH - 4900941633, MLT FED 213668-1TPH - 4900929595			10/26/18 10:40 AM	10/26/18 11:23 AM		Received IR Camera Operations & Functionality Training	44	Mostly Cloudy	2	IR Camera	No	No Repair Required					
20719235	LDAR	MOORE LAND TRUST 36-58 21 BATTERY	MLT FED 213668-2TPH - 4900929651, SSU MLT 16-093668-2XNH - 4900941633, MLT FED 213668-1TPH - 4900929595			5/10/19 11:39 AM	5/10/19 1:01 PM		Received IR Camera Operations & Functionality Training	46	Mostly Cloudy	11	IR Camera	No	Repaired During Initial	TTH	2	CS	5/10/2019	
20593814	LDAR	PDU WJ RANCH FED 22-153772-1XNH	PDU WJ RANCH FED 22-153772-1XNH - 4900936416			8/28/18 8:45 AM	8/28/18 9:30 AM		Received IR Camera Operations & Functionality Training	65	Mostly Cloudy	4	IR Camera	No	No Repair Required					
20698848	LDAR	PDU WJ RANCH FED 22-153772-1XNH	PDU WJ RANCH FED 22-153772-1XNH - 4900936416			2/20/19 11:54 AM	2/20/19 12:45 PM		Received IR Camera Operations & Functionality Training	25	Clear	11	IR Camera	No	Repaired Later	Body/Shell	1	Rope packing leaking	3/8/2019	
20698848	LDAR	PDU WJ RANCH FED 22-153772-1XNH	PDU WJ RANCH FED 22-153772-1XNH - 4900936416			2/20/19 11:54 AM	2/20/19 12:45 PM		Received IR Camera Operations & Functionality Training	25	Clear	11	IR Camera	No	Repaired Later	Body/Shell	1	Leaking threads	3/8/2019	
20655202	LDAR	PRCC FED 04-334071 BATTERY	PRCC FED 04-334071-4XTUH - 4900930869, PRCC FED 04-334071-4XTUH - 4900930882, PRCC FED 04-334071-3XTUH - 4900930883, PRCC FED 04-334071-3XTUH - 4900930884			12/10/18 1:15 PM	12/10/18 2:30 PM		Received IR Camera Operations & Functionality Training	79	Mostly Cloudy	8	IR Camera	No	No Repair Required					
20748507	LDAR	PRCC FED 08-334071 BATTERY	PRCC FED 04-334071-4XTUH - 4900930869, PRCC FED 08-334071-4XTUH - 4900930882, PRCC FED 04-334071-3XTUH - 4900930883, PRCC FED 04-334071-3XTUH - 4900930884			6/5/19 9:00 AM	6/5/19 10:11 AM		Received IR Camera Operations & Functionality Training	68	Clear	8	IR Camera	No	Repaired During Initial	CON	2	CS	6/5/2019	
20753223	LDAR	PRCC FED 274071 BATTERY	PRCC FED 274071-1TH - 4900929354, PRCC FED 274071-2TH - 4900929357, PRCC FED 274071-4TH - 4900929342, PRCC FED 274071-3TH - 4900929340			4/23/19 9:00 AM	4/23/19 10:24 AM		Received IR Camera Operations & Functionality Training	4	Clear	11	IR Camera	No	No Repair Required					
20610654	LDAR	ROBBINS UNIT 39-72 15 CTB 1	RU DILTS FED 15-103972-3XMH - 4900935602, RU DILTS FED 22-273972-1XTH - 4900935600, RU STATE FED 16-093972-4XTH - 4900935873, RU STATE FED 16-093972-2XTH - 4900935616, RU DILTS FED 22-273972-3XTH - 4900935601			10/11/18 10:15 AM	10/11/18 10:59 AM		Received IR Camera Operations & Functionality Training	31	Overcast	1	IR Camera	No	No Repair Required					

20733946	LDAR	ROBBINS UNIT 39-72 15 CTB 1	RU DILTS FED 15-103972-3KMH - 4900935602, RU DILTS FED 22-273972-1XTH - 4900935800, RU STATE FED 16-093972-4XTH - 4900935873, RU STATE FED 16-093972-2XTH - 4900935656, RU DILTS FED 22-273972-3XTH - 4900935601	(b) (9)	4/23/19 1:01 PM	4/23/19 2:27 PM	(b) (6)	Received IR Camera Operations & Functionality Training	66	Partly Cloudy	20	IR Camera	No	No Repair Required					
20733948	LDAR	ROBBINS UNIT 39-72 16 PAD 1	ROBBINS UNIT 39-72 16-1PH - 4900928855, RU STATE FED 16-093972-4XTH - 4900935873		4/15/19 1:28 PM	4/15/19 1:51 PM		Received IR Camera Operations & Functionality Training	4	Overcast	3	IR Camera	No	No Repair Required				
20744870	LDAR	ROBBINS UNIT DILTS 35-4072 PAD 1	RU DILTS FED 35-023972-1XTLH - 4900938601, RU DILTS FED 35-023972-2XTUH - 4900937998, RU DILTS FED 35-023972-4XTLH - 4900938003, RU DILTS FED 35-023972-CXTUH - 4900937999		6/26/19 9:48 AM	6/26/19 10:17 AM		Received IR Camera Operations & Functionality Training	61	Partly Cloudy	9	IR Camera	No	Repaired During Initial	CON	6	YA	6/26/2019	
20758777	LDAR	ROBBINS UNIT JFW 10-3972 PAD 1	RU JFW FED 10-153972-3XTH - 4900935650, RU JFW FED 10-113872-1XTH - 4900935649, RU JFW FED 10-083972-3XTH - 4900935654, RU JFW FED 10-083872-2XTH - 4900935653		7/8/19 7:26 AM	7/8/19 9:16 AM		Received IR Camera Operations & Functionality Training	68	Mostly Cloudy	8	IR Camera	No	Repaired During Initial	CON	1	TA	7/8/2019	
20685078	LDAR	ROBBINS UNIT JFW 13-3972 PAD 1	RU JFW FED 13-243972-3XTLH - 4900936306, RU JFW FED 13-243972-3XTUH - 4900938412, RU JFW FED 13-243972-4XTUH - 4900936309		8/8/2018 7:18	8/8/2018 7:52		Received IR Camera Operations & Functionality Training	64	Clear	0	IR Camera	No	No Repair Required				8/8/2018	
20689987	LDAR	ROBBINS UNIT JFW 13-3972 PAD 3	RU JFW FED 13-243972-3XTLH - 4900936308, RU JFW FED 13-243972-3XTUH - 4900938412, RU JFW FED 13-243972-4XTUH - 4900936309		1/25/19 11:30 AM	1/25/19 11:50 AM		Received IR Camera Operations & Functionality Training	25	Clear	14	IR Camera	No	No Repair Required					
20684220	LDAR	ROBBINS UNIT JFW 14-3972 PAD 1	RU JFW FED 14-113872-1XTH - 4900940385, RU JFW FED 14-113872-3XPH - 4900940342, RU JFW FED 14-113872-4XTH - 4900935016, RU JFW FED 14-113872-CXTH - 4900935015		1/25/19 12:50 PM	1/25/19 1:00 PM		Received IR Camera Operations & Functionality Training	27	Clear	14	IR Camera	No	No Repair Required					
20751536	LDAR	ROBBINS UNIT JFW 14-3972 PAD 1	RU JFW FED 14-113872-1XTH - 4900940385, RU JFW FED 14-113872-3XPH - 4900940342, RU JFW FED 14-113872-4XTH - 4900935016, RU JFW FED 14-113872-CXTH - 4900935015		6/24/19 9:01 AM	6/24/19 10:05 AM		Received IR Camera Operations & Functionality Training	61	Clear	13	IR Camera	No	Repaired Later	Body/Shell	1	1/4" leak on fuel gas scrubber	6/26/2019	
20742915	LDAR	ROBBINS UNIT PACC 1-3972 PAD 1	RU PACC FED 36-254072-4XTUH - 4900941636, RU PACC FED 36-254072-2XTUH - 4900941635		6/6/19 11:50 AM	6/6/19 1:40 PM		Received IR Camera Operations & Functionality Training	72	Mostly Cloudy	8	IR Camera	No	Repaired During Initial	CON	5	YA	6/4/2019	
20682201	LDAR	RU DILTS FED 04-093972-4XTH	RU DILTS FED 04-093872-3XTH - 4900935212, RU DILTS FED 04-093872-4XTH - 4900935213		2/5/19 10:09 AM	2/5/19 10:45 AM		Received IR Camera Operations & Functionality Training	10	Mostly Cloudy	13	IR Camera	No	No Repair Required				
20752523	LDAR	RU DILTS FED 04-093972-4XTH	RU DILTS FED 04-093872-3XTH - 4900935212, RU DILTS FED 04-093872-4XTH - 4900935213		6/24/19 12:47 PM	6/24/19 1:47 PM		Received IR Camera Operations & Functionality Training	73	Clear	12	IR Camera	No	No Repair Required				
20651594	LDAR	SDU 37-71 16 & SDU TILLARD 09-04 BATTERY	SDU TILLARD FED 09-043771-1XPH - 4900929979, SHELDEN DRAW UNIT 37-71 16-1PH - 4900928700, SDU TILLARD FED 09-043771-1XTH - 4900929980		12/14/18 9:35 AM	12/14/18 11:45 AM		Received IR Camera Operations & Functionality Training	45	Clear	12	IR Camera	No	No Repair Required					
20741349	LDAR	SDU 37-71 16 & SDU TILLARD 09-04 BATTERY	SDU TILLARD FED 09-043771-1XPH - 4900929979, SHELDEN DRAW UNIT 37-71 16-1PH - 4900928700, SDU TILLARD FED 09-043771-1XTH - 4900929980		5/29/19 9:18 AM	5/29/19 10:52 AM		Received IR Camera Operations & Functionality Training	45	Mostly Cloudy	7	IR Camera	No	No Repair Required					
20594796	LDAR	SDU TILLARD FED 09-043771-2XTH BATTERY	SDU TILLARD FED 09-043771-2XTH - 4900929980		9/17/18 10:30 AM	9/17/18 10:53 AM		Received IR Camera Operations & Functionality Training	76	Mostly Cloudy	7	IR Camera	No	No Repair Required				
20599346	LDAR	SDU TILLARD FED 09-043771-2XTH BATTERY	SDU TILLARD FED 09-043771-2XTH - 4900929980		2/13/19 11:54 AM	2/13/19 12:40 PM		Received IR Camera Operations & Functionality Training	40	Overcast	27	IR Camera	No	No Repair Required				
20690477	LDAR	SDU TILLARD FED 29-323871-1XPH	SDU TILLARD FED 29-323871-1XPH - 4900940541		1/30/19 1:50 PM	1/30/19 2:20 PM		Received IR Camera Operations & Functionality Training	38	Clear	15	IR Camera	No	No Repair Required				
20757895	LDAR	SDU TILLARD FED 29-323871-1XPH	SDU TILLARD FED 29-323871-1XPH - 4900940541		6/27/19 8:01 AM	6/27/19 8:46 AM		Received IR Camera Operations & Functionality Training	61	Clear	2	IR Camera	No	Repaired Later	Battery/Battery Pack	1	Combustible is in fault	7/8/2019	
20626264	LDAR	SHELDEN DRAW UNIT 37-71 17B 1PH/2PH	SDU TILLARD 17-203771-1XNH - 4900935217, SDU TILLARD FED 083771-1PH - 4900943868, SDU TILLARD FED 083771-2PH - 4900943869, SHELDEN DRAW UNIT 37-71 17B-1PH - 4900929564, SHELDEN DRAW UNIT 37-71 17B-2PH - 4900929563		10/3/18 11:30 AM	10/3/18 11:45 AM		Received IR Camera Operations & Functionality Training	51	Mostly Cloudy	14	IR Camera	No	No Repair Required					
20717629	LDAR	SHELDEN DRAW UNIT 37-71 17B 1PH/2PH	SDU TILLARD 17-203771-1XNH - 4900935217, SDU TILLARD FED 083771-1PH - 4900943868, SDU TILLARD FED 083771-2PH - 4900943869, SHELDEN DRAW UNIT 37-71 17B-1PH - 4900929564, SHELDEN DRAW UNIT 37-71 17B-2PH - 4900929563		4/12/19 2:15 PM	4/12/19 3:24 PM		Received IR Camera Operations & Functionality Training	80	Mostly Cloudy	14	IR Camera	No	Repaired During Initial	TTH	4	CS	4/12/2019	
20625448	LDAR	STATE PACC 364071-4TH	STATE PACC 364071-4TH - 4900929972		10/15/18 8:35 AM	10/15/18 9:13 AM		Received IR Camera Operations & Functionality Training	27	Clear	1	IR Camera	No	No Repair Required				
20719231	LDAR	STATE PACC 364071-4TH	STATE PACC 364071-4TH - 4900929972		4/23/19 7:53 AM	4/23/19 8:43 AM		Received IR Camera Operations & Functionality Training	39	Clear	9	IR Camera	No	Repaired During Initial	TTH	1	CS	4/23/2019	
20625449	LDAR	STATE TLE RANCH FED 36-254372 BATTERY	STATE TLE RANCH FED 36-254372-1XPH - 4900562721, STATE TLE RANCH FED 36-254372-2XPH - 4900562722, STATE TLE RANCH FED 36-254372-3XPH - 4900562724, STATE TLE RANCH FED 36-254372-4XPH - 4900562725		10/17/18 10:45 AM	10/17/18 11:45 AM		Received IR Camera Operations & Functionality Training	36	Clear	3	IR Camera	No	No Repair Required					
20719232	LDAR	STATE TLE RANCH FED 36-254372 BATTERY	STATE TLE RANCH FED 36-254372-1XPH - 4900562721, STATE TLE RANCH FED 36-254372-2XPH - 4900562722, STATE TLE RANCH FED 36-254372-3XPH - 4900562724, STATE TLE RANCH FED 36-254372-4XPH - 4900562725		4/25/19 11:25 AM	4/25/19 12:15 PM		Received IR Camera Operations & Functionality Training	55	Mostly Cloudy	12	IR Camera	No	No Repair Required					
20625450	LDAR	T COSNER FED 204372-2PH	T COSNER FED 204372-2PH - 4900562629		10/23/18 12:15 PM	10/23/18 1:00 PM		Received IR Camera Operations & Functionality Training	60	Clear	16	IR Camera	No	No Repair Required				
20719233	LDAR	T COSNER FED 204372-2PH	T COSNER FED 204372-2PH - 4900562629		4/25/19 12:35 PM	4/25/19 1:00 PM		Received IR Camera Operations & Functionality Training	54	Mostly Cloudy	12	IR Camera	No	No Repair Required				
20625451	LDAR	T COSNER FED 204372-4PH	T COSNER FED 204372-4PH - 4900562627		10/24/18 10:45 AM	10/24/18 12:20 PM		Received IR Camera Operations & Functionality Training	62	Clear	2	IR Camera	No	Repaired During Initial	TTH	1	CS	10/24/2018	
20719234	LDAR	T COSNER FED 204372-4PH	T COSNER FED 204372-4PH - 4900562627		4/25/19 1:05 PM	4/25/19 1:35 PM		Received IR Camera Operations & Functionality Training	54	Mostly Cloudy	12	IR Camera	No	No Repair Required					
20625513	LDAR	T COSNER FED 29 PAD 3	T COSNER FED 29-324372-4XPH - 4900562941, T COSNER FED 29-324372-3XPH - 4900562940		10/25/18 9:30 AM	10/25/18 11:00 AM		Received IR Camera Operations & Functionality Training	60	Clear	2	IR Camera	No	No Repair Required				
20719316	LDAR	T COSNER FED 29 PAD 3	T COSNER FED 29-324372-4XPH - 4900562941, T COSNER FED 29-324372-3XPH - 4900562940		4/30/19 11:40 AM	4/30/19 12:30 PM		Received IR Camera Operations & Functionality Training	30	Overcast	19	IR Camera	No	No Repair Required				
20625515	LDAR	T COSNER FED 29-324372-1XPH	T COSNER FED 29-324372-1XPH - 4900562947		10/24/18 12:40 PM	10/24/18 1:40 PM		Received IR Camera Operations & Functionality Training	64	Clear	2	IR Camera	No	No Repair Required				
20719318	LDAR	T COSNER FED 29-324372-1XPH	T COSNER FED 29-324372-1XPH - 4900562947		4/25/19 2:30 PM	4/25/19 3:00 PM		Received IR Camera Operations & Functionality Training	53	Mostly Cloudy	12	IR Camera	No	No Repair Required				
20625516	LDAR	T COSNER FED 29-324372-2XPH	T COSNER FED 29-324372-2XPH - 4900562939		10/24/18 2:00 PM	10/24/18 3:00 PM		Received IR Camera Operations & Functionality Training	64	Clear	2	IR Camera	No	No Repair Required				
20719317	LDAR	T COSNER FED 29-324372-2XPH	T COSNER FED 29-324372-2XPH - 4900562939		4/25/19 1:45 PM	4/25/19 2:20 PM		Received IR Camera Operations & Functionality Training	54	Mostly Cloudy	12	IR Camera	No	No Repair Required				
20640478	LDAR	T-55 FED 35-023872-1XTH/2XTH BATTERY	RU T-55 FED 26-233972-1XTH - 4900933674, RU T-55 FED 26-233972-2XTH - 4900933677, T-55 FED 35-023872-1XTH - 4900933675, T-55 FED 35-023872-2XTH - 4900933676		11/6/18 12:04 PM	11/6/18 12:40 PM		Received IR Camera Operations & Functionality Training	33	Overcast	2	IR Camera	No	Repaired During Initial	FLA	1	YA	11/6/2018	
20736959	LDAR	T-55 FED 35-023872-1XTH/2XTH BATTERY	RU T-55 FED 26-233972-1XTH - 4900933674, RU T-55 FED 26-233972-2XTH - 4900933677, T-55 FED 35-023872-1XTH - 4900933675, T-55 FED 35-023872-2XTH - 4900933676		5/4/19 1:10 PM	5/4/19 3:23 PM		Received IR Camera Operations & Functionality Training	48	Mostly Cloudy	22	IR Camera	No	Repaired During Initial	FO	1	CS	5/4/2019	
20736958	LDAR	T-55 FED 35-023872-1XTH/2XTH BATTERY	RU T-55 FED 26-233972-1XTH - 4900933674, RU T-55 FED 26-233972-2XTH - 4900933677, T-55 FED 35-023872-1XTH - 4900933675, T-55 FED 35-023872-2XTH - 4900933676		5/4/19 1:10 PM	5/4/19 3:23 PM		Received IR Camera Operations & Functionality Training	48	Mostly Cloudy	22	IR Camera	No	Repaired During Initial	TTH	1	CS	5/4/2019	
20633689	LDAR	T-55 FED 35-023872-3XTH/4XTH BATTERY	T-55 FED 35-023872-3XTH - 4900933672, T-55 FED 35-023872-4XTH - 4900933673		10/15/18 9:50 AM	10/15/18 10:43 AM		Received IR Camera Operations & Functionality Training	28	Mostly Cloudy	2	IR Camera	No	Repaired During Initial	TTH	1	CS	10/15/2018	
20733940	LDAR	T-55 FED 35-023872-3XTH/4XTH BATTERY	T-55 FED 35-023872-3XTH - 4900933672, T-55 FED 35-023872-4XTH - 4900933673		4/19/19 10:40 AM	4/19/19 12:05 PM		Received IR Camera Operations & Functionality Training	59	Clear	11	IR Camera	No	Repaired During Initial	CON	1	TA	4/19/2019	
20733940	LDAR	T-55 FED 35-023872-3XTH/4XTH BATTERY	T-55 FED 35-023872-3XTH - 4900933672, T-55 FED 35-023872-4XTH - 4900933673		4/19/19 10:40 AM	4/19/19 12:05 PM		Received IR Camera Operations & Functionality Training	59	Clear	11	IR Camera	No	Repaired Later		1		4/19/2019	
20733940	LDAR	T-55 FED 35-023872-3XTH/4XTH BATTERY	T-55 FED 35-023872-3XTH - 4900933672, T-55 FED 35-023872-4XTH - 4900933673		4/19/19 10:40 AM	4/19/19 12:05 PM		Received IR Camera Operations & Functionality Training	59	Clear	11	IR Camera	No	Repaired Later	LVE_CONTROL_SUCTION_COMPRESSOR	1	Control Valve has ruptured diaphragm	4/24/2019	
20690481	LDAR	WERNER FED 13-123669-1XTPH	WERNER FED 13-123669-1XTPH - 4900935214, WERNER FED 13-123669-2XTPH - 4900935215		2/25/19 12:24 PM	2/25/19 1:04 PM		Received IR Camera Operations & Functionality Training	10	Overcast	5	IR Camera	No	No Repair Required				
20763758	LDAR	WERNER FED 13-123669-1XTPH	WERNER FED 13-123669-1XTPH - 4900935214, WERNER FED 13-123669-2XTPH - 4900935215		7/18/19 1:55 PM	7/18/19 3:02 PM		Received IR Camera Operations & Functionality Training	80	Clear	22	IR Camera	No	No Repair Required				
20629546	LDAR	WERNER FED 32-293668 BATTERY	WERNER FED 32-293668-2XTPH - 4900929707, WERNER FED 32-293668-3XTPH - 4900929123		9/24/18 10:25 AM	9/24/18 11:53 AM		Received IR Camera Operations & Functionality Training	60	Mostly Cloudy	2	IR Camera	No	Repaired During Initial	TTH	1	CS	9/24/2018	
20713439	LDAR	WERNER FED 32-293668 BATTERY	WERNER FED 32-293668-2XTPH - 4900929707, WERNER FED 32-293668-3XTPH - 4900929123		3/19/19 8:35 AM	3/19/19 9:28 AM		Received IR Camera Operations & Functionality Training	27	Mostly Cloudy	10	IR Camera	No	Repaired During Initial	TTH	2	CS	3/19/2019	
20713439	LDAR	WERNER FED 32-293668 BATTERY	WERNER FED 32-293668-2XTPH - 4900929707, WERNER FED 32-293668-3XTPH - 4900929123		3/19/19 8:35 AM	3/19/19 9:28 AM		Received IR Camera Operations & Functionality Training	27	Mostly Cloudy	10	IR Camera	No	Repaired During Initial	CON	1	TA	3/19/2019	

NSPS OOOO and OOOOa Annual Report
Devon Energy
333 West Sheridan Avenue
Oklahoma City, OK 73102
Reporting Period: August 2, 2018-August 3, 2019
Wyoming

Table 2 - Hydraulically Fractured Well Flowback Data

US WELL ID	WELL NAME	WDEQ FACILITY ID	WDEQ AIR QUALITY PERMIT	LATITUDE (NAD 83)	LONGITUDE (NAD 83)	ONSET OF FLOWBACK	DATE/TIME DIRECTED TO SEPARATOR	DATE/TIME RETURNING TO INITIAL FLOWBACK STAGE	EQUIPMENT DISCONNECTED/STARTUP OF PRODUCTION	DURATION OF FLOWBACK (hrs)	DURATION OF RECOVERY TO FLOWLINE (hrs)	DISPOSITION OF RECOVERY	DURATION OF COMBUSTION (hrs)	DURATION OF VENTING (hrs)	REASON FOR VENTING	DEVIATIONS (i.e lack of flowback controls)	COMMENTS
4900934418	MADSEN STATE FED 21-86-1 FH	F029147	P0025703	(b) (9)	[redacted]	1/24/19 10:00 AM	1/24/19 1:00 PM	N/A	1/24/19 1:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900934418	PDU WJ RANCH FED 22-153772-1XNH	F028962	P0025187			8/7/18 9:00 AM	8/7/18 1:00 PM	N/A	8/7/18 1:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900938001	RU DILTS FED 35-023972-1XTLH	F029329	P0026114			5/30/19 1:00 PM	5/30/19 2:00 PM	N/A	5/30/19 2:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900938003	RU DILTS FED 35-023972-4XTLH	F029329	P0026114			5/30/19 5:00 PM	5/30/19 6:00 PM	N/A	5/30/19 6:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900937999	RU DILTS FED 35-023972-CXTUH	F029329	P0026114			5/30/19 2:00 PM	5/30/19 2:00 PM	N/A	5/30/19 2:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935653	RU JFW FED 10-033972-1XTH	F029404	P0026402			6/18/19 3:00 PM	6/18/19 3:00 PM	N/A	6/18/19 3:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935654	RU JFW FED 10-033972-3XTH	F029404	P0026402			6/18/19 3:00 PM	6/18/19 3:00 PM	N/A	6/18/19 3:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935649	RU JFW FED 10-153972-1XTH	F029404	P0026402			6/18/19 3:00 PM	6/18/19 3:00 PM	N/A	6/18/19 3:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935650	RU JFW FED 10-153972-3XTH	F029404	P0026402			6/18/19 3:00 PM	6/18/19 3:00 PM	N/A	6/18/19 3:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935016	RU JFW FED 14-113972-4XTH	F029103	P0025486			12/15/18 11:00 AM	12/15/18 12:00 PM	N/A	12/15/18 12:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900935015	RU JFW FED 14-113972-CXTH	F029103	P0025486			12/15/18 10:00 AM	12/15/18 8:00 PM	N/A	12/15/18 8:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900941635	RU PRCC FED 36-254072-2XTUH	F029323	P0026202			5/16/19 11:00 AM	5/16/19 12:00 PM	N/A	5/16/19 12:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900941634	RU PRCC FED 36-254072-4XTUH	F029323	P0026202			5/16/19 10:00 AM	5/16/19 7:00 PM	N/A	5/16/19 7:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900929980	SDU TILLARD FED 09-043771-2XTH	F025986	P0022342			8/9/18 10:00 AM	8/9/18 11:00 AM	N/A	8/9/18 11:00 AM	0	0	Sales	0	0	N/A	N/A	N/A
4900941633	SSU MLT 16-093868-2XNH	F027755	P0026234			5/21/19 11:00 AM	5/21/19 10:00 PM	N/A	5/21/19 10:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900933550	CU Downs Fed 09-043769-CXTPH	F026390	P0025593			12/9/2018	12/11/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900933547	CU Downs Fed 15-223769-2XTPH	F026390	P0025593			12/3/2018	12/8/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900934915	CU Downs Fed 35-263769-1XTPH	F026390	P0025593			11/20/2018	11/23/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900929763	CWDU T-55 Fed 31-063871-3XPH	F029127	P0025592			12/13/2018	12/19/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900934798	Downs Fed 02-113669-1XTPH	F029137	P0025591			11/25/2018	11/27/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900934796	Downs Fed 02-113669-3XTPH	F029137	P0025591			11/28/2018	11/30/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900933556	Downs Fed 07-183668-4XTPH	F029137	P0025591			6/2/2019	6/3/2019	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900933553	MLT FED 20-178668-2XTPH	F029445	P0026483			5/29/2019	5/31/2019	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900940385	RU JFW Fed 14-113972-1XTH	F029103	P0025486			6/18/19 3:00 PM	6/18/19 3:00 PM	N/A	6/18/19 3:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900940342	RU JFW Fed 14-113972-3XPH	F029103	P0025486			11/16/2018	11/17/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900941590	SDU Tillard 25-363771-1XTH	F029591	P0026697			8/8/19 11:00 AM	8/8/19 12:00 PM	N/A	8/8/19 12:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900944198	SDU Tillard 25-363771-CXTH	F029591	P0026697			8/7/19 12:00 PM	8/7/19 2:00 PM	N/A	8/7/19 2:00 PM	0	0	Sales	0	0	N/A	N/A	N/A
4900943888	SDU Tillard FED 083771-1PH	F026436	P0009142			5/24/2019	5/26/2019	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900943889	SDU Tillard FED 083771-2PH	F026436	P0009142			5/24/2019	5/26/2019	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900944185	SDU Tillard Fed 25-363771-4X	F029591	P0026697			6/16/2019	6/20/2019	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Well was hydraulically fractured but did not have flowback
4900940541	SDU Tillard Fed 29-323871-1XPH	F029140	P0025890			12/17/2018	12/20/2018	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

NSPS OOOO and OOOOa Annual Report

Devon Energy

333 West Sheridan Avenue

Oklahoma City, OK 73102

Reporting Period: August 2, 2018-August 3, 2019

Wyoming

Table 3 - Storage Vessels

WDEQ FACILITY ID	WDEQ AIR QUALITY PERMIT	FACILITY NAME	LATITUDE (NAD 83)	LONGITUDE (NAD 83)	CONTROL TYPE	REMOVED FROM SERVICE	REMOVAL DATE	RESUMED SERVICE	DATE SERVICE RESUMED	DEVIATIONS (method 22's, AVOs, flare downtime)	NUMBER OF TANKS	VOC PTE TPY	VOC PTE (per tank)	POST CONTROL VOC RATE
F026261	P0022717	DILTS RANCH STATE 38-71-16-2FH	(b) (9) [redacted]		Continuous Pilot Flame Combustor	N/A	N/A	N/A	N/A	N/A	--	--	--	--
F026626	P0022527	ROBBINS UNIT 39-72 26-2FH			Continuous Pilot Flame Combustor	N/A	N/A	N/A	N/A	N/A	--	--	--	--
F026626	P0022527	ROBBINS UNIT 39-72 26-3FH			Continuous Pilot Flame Combustor	N/A	N/A	N/A	N/A	N/A	--	--	--	--
F026626	P0022527	ROBBINS UNIT 39-72 26-4FH			Continuous Pilot Flame Combustor	N/A	N/A	N/A	N/A	N/A	--	--	--	--