DATE RETURNED _____
REASON _____

☐ ACKNOWLEDGEMENT SENT

INTERNAL CHECKLIST ID # NYD05 7722019

comp

1. Interim Regulatory Requirements

A. (1) FORM 1 MISSING ☐

(2) FORM 3 MISSING ☐

B. POSTMARK after NOVEMBER 19, 1980 ☐ Valid ☐

C. (1) DATE of OPERATION MISSING ☐

(2) DATE of OPERATION after NOVEMBER 19, 1980 ☐

D. (1) NON-NOTIFIER ☐
(2) NOTIFIED after AUGUST 18, 1980 ☐ Valid ☐

E. (1) FORM 1, ~~X~~III B SIGNATURE MISSING ☐

(2) FORM 3, IX B SIGNATURE MISSING ☐

2. A. HANDLER ☐

B. NONREGULATED ☐

C. UNSURE ☐

D. UNKNOWN FACILITY ☐
(missing name and address on Form 3)

E. NEW FACILITY > NOV. 19, 1980 ☐

F. CORE ITEM(S) MISSING ☐

G. NON-CORE ITEM(S) MISSING ☐

H. OTHER ☐

MISSING:
MAP ☐
DRAWING ☐
PHOTO ☐

AOK

NYD057722019 DEUTSCH RELAY



PLOT PLAN
SCALE: 1" = 250'-0"

FOR: DEUTSCH RELAYS, INC.
BY: DONNELLY ENGINEERING
DATE: NOV 18, 1980 DWG NO DR-$5



SCALE: 1" = 2000'-0"

FACILITY LOCATION:

LATITUDE: N 40° 50' 12", LONGITUDE W 73° 19' 10"

TAKEN FROM:

USGS 7.5 MIN. SERIES TOPOGRAPHICAL MAP
GREENLAWN QUADRANGLE, NEW YORK

FOR:

DEUTSCH RELAYS, INC.

BY:

DONNELLY ENGINEERING

DATE NOV 17, 1980
DWG NO. DR-01
FIG NO. 1



UTM GRID AND 1967 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET



PLOT PLAN
SCALE: 1" = 250'-0"

FOR: DEUTSCH RELAYS, INC.
BY: DONNELLY ENGINEERING
DATE: NOV 18, 1980 DWG NO DR-$5