To: Myers, Craig[Myers.Craig@epa.gov]
From: Merritt, Steven
Sent: Thur 9/11/2014 6:53:33 PM
Subject: FW: Viper

Here's the info on the viper.

Steven B. Merritt
Federal On-Scene Coordinator
U.S. Environmental Protection Agency Region 8
1595 Wynkoop ST (8EPR-ER)
Denver, CO 80202-1129
303-312-6146 - Work
303-775-7226 - Mobile
303-312-7203 - Fax
Merritt.Steven@epa.gov

-----Original Message-----
From: Robinson, David [mailto:David.Robinson@WestonSolutions.com]
Sent: Thursday, September 04, 2014 6:22 AM
To: Merritt, Steven
Subject: FW: Viper

Steve:

During our 8/12/14 visit to the Warehouse, we evaluated several issues with the Viper hardware and software that surfaced when we attempted to deploy a set of datarams with Viper at the Red River Supply ER in Williston, ND recently. Megan Adamczyk and Jeff Bryniarski looked at all of the lincs and gateways to see what the problems were. See Megan's summary below.

To summarize, all viper lincs delployed on the ER truck are working (communication with the host computer and publishing to the online database) with the exception of the SAM 940 linc. Megan and Jeff were not able to get that issue resolved with ERT assistance.

All of the dataram lincs are working with the host computer, but four of the lincs have not been configured to get through the ERT firewall. They are apparently newer ones and this was never done. ERT recommended that we upgrade the gateway firmware, then complete the configuration to solve the firewall issue.

To do's still on the list:
Update the gateway firmware on all of the gateways at the Warehouse Work with ERT to add the remaining lincs to the firewall table so they can publish to the online database.

Another topic for Monday's meeting I think.

Thanks,

Dave Robinson

WESTON Solutions, Inc.
1435 Garrison Street, #100
Lakewood, CO 80215
303-729-6181 (office)
937-572-3630 (cell)

www.westonsolutions.com

"Think you can, think you can't, either way you're right" Henry Ford

-----Original Message-----
From: Adamczyk, Megan
Sent: Wednesday, August 13, 2014 2:10 PM
To: Robinson, David
Subject: Viper

Dave,

You can add to the checkout list that we successfully got the Rae and data ram lincs from the ER truck working.

We identified the issue with the data ram lincs (improper baud rate) and reconfigured and tested all data ram lincs. We checked all the data ram lincs and they connect properly.

We did a test run with two of the lincs to the viper.ert website. They both work and the remaining 4 lincs need to have the firewall settings updated to allow them to push to the server. ERT can do this, but suggested we wait until after we update the gateway firmware. The ER truck linc is one of the lincs working for server publishing.

Success!!!
The SAM issue is still tbd.

Sent from my iPhone
CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.