To: Peronard, Paul[Peronard.Paul@epa.gov]
From: Robinson, David
Sent: Tue 7/29/2014 7:57:25 PM
Subject: Full lab report
removed.txt
D60160-full.PDF

Here is the complete lab report for the GRO/DRO from the Broadway to Railroad section of the ditch.

I just got a call from Jeff Keller/USACE wondering if he could get these results. I told him I would pass that request along to you but I couldn't release them without your permission.

The DO is up a little in the north section of the ditch with the addition of two more compressor/aerators. Very few readings below 1 now. A third compressor / aerator has been added to the south section of the ditch (south of railroad), located just north of the dam.

Dave

Dave Robinson

WESTON Solutions, Inc.

1435 Garrison Street, #100

Lakewood, CO 80215

303-729-6181 (office)

937-572-3630 (cell)

www.westonsolutions.com

"Think you can, think you can't, either way you're right" Henry Ford

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you. --