Message

From: McDougal, Jason S [Jason.S.McDougal@wv.gov]
Sent: 6/5/2018 12:37:44 PM
To: Bleiler, Justin [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=466a8c6a7305405187c162239ea54e8e-Bleiler, Ju]
Subject: RE: Fayetteville Machine Shop
Attachments: ATT00001.txt

I will see what I can do. I will get back to you soon.
Jake

From: Bleiler, Justin <Bleiler.Justin@epa.gov>
Sent: Monday, June 4, 2018 2:31 PM
To: McDougal, Jason S <Jason.S.McDougal@wv.gov>
Subject: RE: Fayetteville Machine Shop

Hi Jake,

This former machine shop is approximately 9 miles from the Shaffer site, so it is too far away to be included in our Arbuckle Creek investigation. Is there anything that can be done by WVDEP?

Below I have included some more background information. It doesn't seem to support the resident's claim that a tank filled with PCBs was buried beneath the barn, but maybe there is something WVDEP can do to address the resident's concerns. Please let me know your thoughts.

Background: The resident claims that a tank filled with PCBs was buried in approximately 1997 by Bill Shaffer. She also claims that her husband saw several inches of oil on the floor of the machine shop. However, Bill Shaffer passed away in 1982. Additionally, the Shaffer Equipment Company received relief of liability in 1994, so it seems there would not have been an incentive to remove contamination from the Shaffer site at that time.

Thanks,

Justin Bleiler
Site Assessment Manager, HSCD
Environmental Protection Agency, Region 3
1650 Arch St., 3HS12
Philadelphia, PA 19103
215-814-3308
bleiler.justin@epa.gov

From: McDougal, Jason S [mailto:Jason.S.McDougal@wv.gov]
Sent: Wednesday, May 30, 2018 2:49 PM
To: Bleiler, Justin <Bleiler.Justin@epa.gov>
Subject: RE: Fayetteville Machine Shop

I don't believe they were. (The UST)

From: Bleiler, Justin <Bleiler.Justin@epa.gov>
Sent: Wednesday, May 30, 2018 2:41 PM

To: McDougal, Jason S <Jason.S.McDougal@wv.gov>
Subject: RE: Fayetteville Machine Shop

Thanks Jake! Do you know whether your UST program ever got involved? The son of the machine shop owner, who lives next door, said that WVDEP knew about the UST beneath the barn, but he said that WVDEP would have needed to move his trailer to get the tank out, so it was never done. Would you be able to verify any of this information? If they knew the tank was there, maybe they sampled its contents.

Thanks,

Justin Bleiler
Site Assessment Manager, HSCD
Environmental Protection Agency, Region 3
1650 Arch St., 3HS12
Philadelphia, PA 19103
215-814-3308
bleiler.justin@epa.gov

From: McDougal, Jason S [mailto:Jason.S.McDougal@wv.gov]
Sent: Friday, May 25, 2018 11:34 AM
To: Bleiler, Justin <Bleiler.Justin@epa.gov>
Subject: FW: Fayetteville Machine Shop

FYI. Machine Shop

From: Rogers, Sandra D
Sent: Wednesday, May 23, 2018 11:45 AM
To: McDougal, Jason S <Jason.S.McDougal@wv.gov>
Subject: FW: Fayetteville Machine Shop

Here is the information that I could gather.

Take care.

Sandy R.

Sandy Rogers
REAP Manager
West Virginia Department of Environmental Protection
Rehabilitation Environmental Action Plan (REAP)
601 57th St. SE
Charleston, WV 25304
Phone: (304) 926-0499 ext. 1004
Cell: 389-2292
Fax: (304) 926-0457
sandra.d.rogers@wv.gov



From: Stalnaker, Samuel R
Sent: Monday, May 21, 2018 3:56 PM
To: Rote, Gregory A <Gregory.A.Rote@wv.gov>
Cc: Rogers, Sandra D <Sandra.D.Rogers@wv.gov>
Subject: RE: Fayetteville Machine Shop

Greg,

The REAP Program cleaned up the area during the time period of May 7, 2006 thru July 12, 2006. During that time we had two contractors involved. One cleanup was for trash and scrap metal which netted 114.46 tons and the other involved tire pickup which netted 49.63 tons of tires (approximately 500). This was an old mine rebuild shop that had been abandoned. Lots of heavy items. But we were not involved in any remediation of soil. I don't remember any oily spots, but that's been 12 years ago. I'm not even sure how we got involved-maybe EE. If you need anything further, I'll try to gather that info.

Thanks,

SAM

From: Rote, Gregory A
Sent: Monday, May 21, 2018 3:07 PM
To: Stalnaker, Samuel R <Samuel.R.Stalnaker@wv.gov>
Subject: Fwd: Fayetteville Machine Shop

Gregory Rote
WVDEP. REAP
Cell 304-389-8181
Office 304-926-0499 ext 1270
Fax 304-926-0457
601 57th Street SE. Charleston WV 25304

Begin forwarded message:

> **From:** "Rogers, Sandra D" <Sandra.D.Rogers@wv.gov>
> **Date:** May 21, 2018 at 3:04:27 PM EDT
> **To:** "McDougal, Jason S" <Jason.S.McDougal@wv.gov>
> **Cc:** "Rote, Gregory A" <Gregory.A.Rote@wv.gov>
> **Subject: RE: Fayetteville Machine Shop**
>
> I'll have Greg Rote see if it was one of his folks.
>
> Thanks
>
> Sandy
>
> **From:** McDougal, Jason S
> **Sent:** Monday, May 21, 2018 1:57 PM
> **To:** Rogers, Sandra D <Sandra.D.Rogers@wv.gov>
> **Subject:** FW: Fayetteville Machine Shop

Long time! Hey, I saw in the following e-mail something about tire removal. Could you take a look at the e-mail below would this be your group or someone else?
Thanks
Jake

From: Bleiler, Justin [mailto:Bleiler.Justin@epa.gov]
Sent: Friday, May 18, 2018 9:52 AM
To: McDougal, Jason S <Jason.S.McDougal@wv.gov>
Cc: Linden, Melissa <linden.melissa@epa.gov>
Subject: Fayetteville Machine Shop

Hi Jake,

During our tour the other day, Personal Matters / Ex. 6 identified an area of concern at 8148 Gatewood Road Fayette, WV. She alleges that a tank containing PCBs was transported from the Shaffer site in Minden to a machine shop at this address, previously owned by Kim Oneal (sp?). She alleges that the tank was buried beneath the barn still on-site and also alleges that her husband worked there from time to time and saw several inches of oil on the floor.

We spoke to Personal Matters / Ex. 6 who lives in the trailer next door to the west. He said that WVDEP removed tires from his property and conducted a remediation of "hydrocarbons" by putting fertilizer on top or something along those lines. If this is the case, WVDEP would probably have had some knowledge of the machine shop next door and may have done some assessment. Mrs. Jenkins does not have concrete evidence/documentation of this buried tank, as far as I know. So I was hoping you could review WVDEP files to see if any assessment was done at that machine shop. Please let me know if you have any questions.

Thank you,

Justin Bleiler
Site Assessment Manager, HSCD
Environmental Protection Agency, Region 3
1650 Arch St., 3HS12
Philadelphia, PA 19103
215-814-3308
bleiler.justin@epa.gov