	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7		Enterprises Shipping & Trading S.A.	SA Altius	Bahamas	9221205	6/3/2015

	G	H	I	J	K
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	Off Kashima Japan	Roberts Bank	Kashima	Kashima	Brilliant Maritime Services (Cyprus) Ltd - BMS United Bunkers

	L	M	N	O	P	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	2	21/03/2015	6:00	2.44	48	Roberts Bank

	R	S	T	U	V
1					
2					
3	18	19	20	21	22
4					
5					
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
7	Yes	Yes	3	n/a	n/a

	W	X	Y	Z
1				
2				
3	23	24	25	26
4				
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7	n/a	n/a	3/4/2015	12:00

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4					
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
7	NO	n/a	n/a	No	0

	AF	AG	AH
1			
2			
3	32	33	34
4			
5			
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	Konstantinos Angelaras	operations@ensh.com	3.02109E+11

	AI
1	
2	
3	35
4	
5	
6	Description of Actions to Achieve Compliance
7	When vessel was off Kahsima, applied to local bunker suppliers but confirmed unavailability of low sulfuer fuel. Approached Bunker Suppliers in first and sole Canadian port of call (Roberts Bank) and arranged delivery of low sulfur fuels compliant to