	A	B	C	D	E	F	G
1	## North America Emission Control Area Fuel Oil Non-Availability Report						
2	## ECA0100						
3	## 1	2	3	4	5	6	7
4	##						
5	##(Include Double Pound for comments, not form fields)						
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice
7							
8		CAPT. CHOO JEE LIM	MV KN FOREST	SINGAPORE	9558268	9-Jan-15	CHENNAI, INDIA

	H	I	J	K	L
1					
2					
3	8	9	10	11	12
4					
5					
6	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted
7					
8	NEWARK, NJ. USA	CHENNAI, INDIA	CHENNAI, INDIA	CHEM OIL	2

	M	N	O	P	Q	R
1						
2						
3	13	14	15	16	17	18
4						
5						
6	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC	Compliance Fuel Oil Available at First POC?
7						
8	25-Feb-15	0400LT	3.40%	about 34 hrs	NEWARK, NJ	YES

	S	T	U	V	W
1					
2					
3	19	20	21	22	23
4					
5					
6	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?	Plan to Bunker Compliance Fuel Oil at Second POC?
7					
8	YES	2	UNKNOWN	UNKNOWN	NO

	X	Y	Z	AA	AB
1					
2					
3	24	25	26	27	28
4					
5					
6	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA
7					
8	NO	8-Mar-15	0800LT	YES	3

	AC	AD	AE	AF	AG
1					
2					
3	29	30	31	32	33
4					
5					
6	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail
7					
8	3	NO	NIL	CAPT. CHOO JEE LIM	ops.handymax@pacificcarriers.com.sg

	AH	AI
1		
2		
3	34	35
4		
5		
6	Designated Corporate Official Phone Number	Description of Actions to Achieve Compliance
7		
8	00 65 90083581	BUNKER HAS BEEN ARRANGE ON VESSEL ALONGSIDE. AGENT HAS BEEN ADVISED.