	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7	ECA0100	Hanjin Shipping America, LLC	MV E.R. Bordeaux	Liberia	9483229	13th Jan 2015

	G	H	I	J	K
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	LAT 17 48.5N, LON 033 18.7.0W	New York	Lome,	NA	NA

	L	M	N	O	P	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	NA	20th Jan. 2015	2:00	2.69%	20 hours	New York

	R	S	T	U
1				
2				
3	18	19	20	21
4				
5				
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC
7	Y	Y	Tel: 212-430-1104, Cell: 917-891-1840 (PIC Mr. Frank Flizack)	NA

	V	W	X	Y	Z
1					
2					
3	22	23	24	25	26
4					
5					
6	Compliant Fuel Oil at Second POC?	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7	NA	NA	NA	1/30/2015	20:00 (estimated)

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4					
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
7	Y	1	1	N	1

	AF	AG	AH	AI
1				
2				
3	32	33	34	35
4				
5				
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number	Description of Actions to Achieve Compliance
7	Xin Dai	operation-usa@us.hanjin.com	201-291-4686 or 4600	Arranged LSFO supply upon vessel arriving New York anchorage