	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments	not form fields)				
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7	ECA0100	Enterprises Shipping and Trading SA	Gladiator	Bahamas	9605853	3/4/2017

	G	H	I	J	K
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	1828N09422W	NewOrleans	Coatzacoalcos	NA	NA

	L	M	N	O	P	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	NA	3/6/2017	23:00	2.91	5MyrtleGrove	Y

	R	S	T	U	V
1					
2					
3	18	19	20	21	22
4					
5					
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
7	Y	NA	NA	NA	NA

	W	X	Y	Z
1				
2				
3	23	24	25	26
4				
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7	3/9/2017	12:00	Y	1

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4					
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
7	1	N	1	Mr.K.Angelaras	operations@ensh.com

	AF	AG	AH
1			
2			
3	32	33	34
4			
5			
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	0030-210-891-0111	Vessel has sufficient low sulphur MGO 0	09% to enter the river

	AI
1	
2	
3	35
4	
5	
6	Description of Actions to Achieve Compliance
7	but not enough to stay the port. Owners arranged already supply on entering port and awaiting barge to arrive.