Message

From: Dan Johnson [DanJohnson@florencecopper.com]
Sent: 10/19/2018 10:39:16 PM
To: Rumrill, Nancy [Rumrill.Nancy@epa.gov]
CC: Maribeth E. Greenslade [Greenslade.Maribeth@azdeq.gov]; Albright, David [Albright.David@epa.gov]
Subject: RE: Plugging & Abandonment Plan
Attachments: ATT00001.txt

Hi Nancy,

We weren't aware that these figures were required but will have them to you on Monday. Have a great weekend!

Cheers,

Dan Johnson VP | General Manager

Florence Copper Inc.
1575 W. Hunt Highway Florence AZ USA 85132
C 520-233-1930 **T** 520-374-3984 **F** 520-374-3999
E danjohnson@florencecopper.com **Web** florencecopper.com

From: Rumrill, Nancy [mailto:Rumrill.Nancy@epa.gov]
Sent: October-19-18 3:11 PM
To: Dan Johnson
Cc: Maribeth E. Greenslade; Albright, David
Subject: RE: Plugging & Abandonment Plan

Hi Dan,

I also need an updated final plugging and abandonment diagram for these wells and the corehole that differed from the proposed. Please provide the final diagrams for each one or confirm that final diagrams are provided in the Appendix of the PTF Well and Corehole Abandonment Summary report.

Thanks, Nancy

~~~~~~

Nancy Rumrill (rumrill.nancy@epa.gov)
Drinking Water Protection Section (WTR-3-2)
US EPA, Region IX
75 Hawthorne St.
San Francisco, CA 94105
Phone (415) 972-3293
~~~~~~

From: Dan Johnson [mailto:DanJohnson@florencecopper.com]
Sent: Friday, October 19, 2018 2:37 PM
To: Albright, David <Albright.David@epa.gov>
Cc: Rumrill, Nancy <Rumrill.Nancy@epa.gov>; Maribeth E. Greenslade <Greenslade.Maribeth@azdeq.gov>
Subject: Plugging & Abandonment Plan

Mr. Albright,

The below statement is to satisfy the requirement listed in Appendix C Section Q.4.3 of the above referenced permit:

Besides the four attached EPA 75200-14 Forms for Well DM-B, Well WW-3, Well O-05 and Core hole 133S, which was submitted to you back on 10/19/18, all other wells and core holes within the Area of Review (AOR) for UIC Permit No. R9UIC-AZ3-FY11-1 were plugged and abandoned per the plan submitted to the Regional Administrator. FCI's Final Plugging & Abandonment Report was submitted to you on 9/13/18 as part of FCI's Pre-Operational Report. This report describes the details of all the wells and core holes plugged and abandoned in the AOR.

If you have any questions or need additional clarification on this correspondence, please do hesitate to contact me at (520) 374-3984, ext. 3710.

Best Regards,

Dan Johnson VP | General Manager

Florence Copper Inc.
1575 W. Hunt Highway Florence AZ USA 85132
C 520-233-1930 **T** 520-374-3984 **F** 520-374-3999
E danjohnson@florencecopper.com **Web** florencecopper.com

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."