Table 2

Indoor Air Sample Results After Final Cleaning - PCBs in Vapors
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California
June 24 through 26, 2015 (a)

	Location:
	Sample ID:
Analyte (µg/m^3)	
Aroclor 1016	
Aroclor 1221	
Aroclor 1232	
Aroclor 1242	
Aroclor 1248	
Aroclor 1254	
Aroclor 1260	
Aroclor 1262	
Aroclor 1268	
Total PCBs (b)	

a/ PCBs = polychlorinated biphenyls; µg/m^3 = micrograms per cubic meter; U = analyte not detected.

b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.

c/ Duplicate sample of PUF-17-062415.

Table 2

Indoor Air Sample Results After Final Cleaning - PCBs in Vapors
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California
June 24 through 26, 2015 (a)

Western Office Area	Northwest Portion of Warehouse	Northeast Portion of Warehouse		Southeast Portion of Warehouse	Southwest Portion of Warehouse	Inside Break Room
PUF-14-062415	**PUF-15-062415**	**PUF-17-062415**	**PUF-400-062415 (c)**	**PUF-18-062415**	**PUF-19-062415**	**PUF-20-062415**
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	***0.087***	***0.074***	***0.077***	***0.044***	***0.043***	***0.098***
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	0.0039 U	0.0039 U	0.0040 U	0.0050 U	0.0040 U	0.0041 U
0.0079 U	***0.087***	***0.074***	***0.077***	***0.044***	***0.043***	***0.098***

Table 3

Indoor Air Sample Results After Final Cleaning - PCBs in Particulates
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California
June 24 through 26, 2015 (a)

	Location:
	Sample ID:
Analyte (µg/m^3)	
Aroclor 1016	
Aroclor 1221	
Aroclor 1232	
Aroclor 1242	
Aroclor 1248	
Aroclor 1254	
Aroclor 1260	
Aroclor 1262	
Aroclor 1268	
Total PCBs (b)	

a/ PCBs = polychlorinated biphenyls; µg/m^3 = micrograms per cubic meter; U = analyte not detected.
b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.
c/ Duplicate sample of QUARTZ-17-062415.

Table 3

Indoor Air Sample Results After Final Cleaning - PCBs in Particulates
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California
June 24 through 26, 2015 (a)

Western Office Area	Northwest Portion of Warehouse	Northeast Portion of Warehouse		Southeast Portion of Warehouse	Southwest Portion of Warehouse	Inside Break Room
QUARTZ-14-062415	QUARTZ-15-062415	QUARTZ-17-062415	QUARTZ-400-062415 (c)	QUARTZ-18-062415	QUARTZ-19-062415	QUARTZ-20-062415
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	0.0039 U	0.0078 U	0.0079 U	0.0099 U	0.0079 U	0.0082 U
0.0040 U	***0.0039 U***	***0.0078 U***	***0.0079 U***	***0.0099 U***	***0.0079 U***	***0.0082 U***

Table 4

Wipe Sample Results After Final Cleaning for High Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

	Sample ID:
	Feature:
	Height above Floor (ft):
	Date:
Analyte (µg/100 cm^2)	
Aroclor 1016	
Aroclor 1221	
Aroclor 1232	
Aroclor 1242	
Aroclor 1248	
Aroclor 1254	
Aroclor 1260	
Aroclor 1262	
Aroclor 1268	
Total PCBs (b)	

	Sample ID:
	Feature:
	Height above Floor (ft):
	Date:
Analyte (µg/100 cm^2)	
Aroclor 1016	
Aroclor 1221	
Aroclor 1232	
Aroclor 1242	
Aroclor 1248	
Aroclor 1254	
Aroclor 1260	
Aroclor 1262	
Aroclor 1268	
Total PCBs (b)	

a/ High frequency of contact areas are wipe sample locations collected 8 feet or lower from the floor (excluding samples collected from ducts, drains, toe rails, and pits) and samples where the height above the floor was not specified in the field (i.e., "unknown").
PCBs = polychlorinated biphenyls; µg/100 cm^2 = micrograms per 100 square centimeters; ft = feet; U = analyte not detected; J = estimated concentration.

b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.

Table 4

Wipe Sample Results After Final Cleaning for High Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-08	**WP-09**	**WP-29**	**WP-30-POST SG**	**WP-62**	**WP-71**	**WP-72**	**WP-75**	**WP-76**	**WP-77**	**WP-MO-01**	**WP-MO-02**	**WP-52-POST**	**WP-53-POST**	**WP-93**
East Window	Electrical Box	Column	Beam	Beam	Sheet Metal	Electrical Box	Pipe	Pipe	Column	Cabinet	Cabinet	Cabinet	Cabinet	Door
7	2	unknown	4	4	unknown	6	3	5.5	1	5	5	3.5	5.5	3
3/26/2015	3/26/2015	4/7/2015	4/8/2015	4/28/2015	4/29/2015	4/29/2015	4/30/2015	4/30/2015	4/30/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/2/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***2.2***	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***2.2***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***

WP-94	**WP-95**	**WP-96-POSTSG**	**WP-104**	**WP-105**	**WP-106**	**WP-107**	**WP-111**	**WP-112**	**WP-113**	**WP-116**	**WP-103-POST**	**WP-124**	**WP-128**
Door	Pipe	Light Fixture	Stairs	Stairs	Railing	Sink Pipe	Column	West Wall	Floor Rail	Railing	Fence Post	HVAC Unit	Pipe
2	unknown	8	5	2	3 (mezz. lev.)	2.5 (mezz. lev.)	3	6	0	4	5	3 (mezz. lev.)	2 (mezz. lev.)
5/2/2015	5/2/2015	5/5/2015	5/7/2015	5/7/2015	5/7/2015	5/7/2015	5/8/2015	5/8/2015	5/8/2015	5/8/2015	5/9/2015	5/9/2015	5/12/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***0.98 J***	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	***1.2 J***	2.0 U	***1.1 J***	2.0 U	2 U	***0.78 J***	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***0.98***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***1.2***	***2.0 U***	***1.1***	***2.0 U***	***2.0 U***	***0.78***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**WP-01**	**WP-02**	**WP-03**	**WP-04**
Feature:	East Wall	North Wall	Roll-up Door	Heating Unit
Height above Floor (ft):	29	26	27	13
Date:	3/25/2015	3/25/2015	3/25/2015	3/25/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***2.8***	***1.6 J***	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***2.8***	***1.6***	***2.0 U***

Sample ID:	**WP-16-POST**	**WP-17-POST**	**WP-18-POST SG**	**WP-19**
Feature:	Column	Duct	Column	Ceiling
Height above Floor (ft):	24	25	29	Ceiling
Date:	3/31/2015	3/31/2015	4/2/2015	4/2/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	***0.61 J***	2.0 U	***0.93 J***	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	***4.4***	***0.54 J***	***3.5***	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***5.01***	***0.54***	***4.43***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**WP-35**	**WP-36**	**WP-37**	**WP-38**
Feature:	Light Fixture	Metal Plate	Beam	Divider Wall
Height above Floor (ft):	near ceiling	~20	~20	~25
Date:	4/11/2015	4/13/2015	4/13/2015	4/13/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	***0.73 J***	***2.3***	2.0 U	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***0.73***	***2.3***	***2.0 U***	***2.0 U***

Sample ID:	**WP-50**	**WP-51**	**WP-54**	**WP-55**
Feature:	Duct	Duct	Beam	Crane Beam
Height above Floor (ft):	20	25	30	~20
Date:	4/24/2015	4/24/2015	4/28/2015	4/28/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	***3.5***	2.0 U	2.0 U	***0.64 J***
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***3.5***	***2.0 U***	***2.0 U***	***0.64***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**WP-65**	**WP-66**	**WP-67**	**WP-68**
Feature:	Sheet Metal	Beam	Light Fixture	Beam
Height above Floor (ft):	~25	~25	near ceiling	20
Date:	4/29/2015	4/29/2015	4/29/2015	4/29/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***3.2***	2.0 U	***0.75 J***
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***3.2***	***2.0 U***	***0.75***

Sample ID:	**WP-82**	**WP-83**	**WP-84**	**WP-85**
Feature:	Pipe	Crane Track	Beam	Beam
Height above Floor (ft):	~25	~20	~20	25
Date:	4/30/2015	4/30/2015	4/30/2015	4/30/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***0.69 J***	***0.74 J***	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***0.69***	***0.74***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**WP-98**	**WP-99**	**WP-100**	**WP-101**
Feature:	Light Fixture	Light Fixture	Light Fixture	Pipe
Height above Floor (ft):	near ceiling	near ceiling	near ceiling	~25
Date:	5/6/2015	5/6/2015	5/6/2015	5/6/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***0.72 J***	2.0 U	***0.62 J***
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***0.72***	***2.0 U***	***0.62***

Sample ID:	**WP-119**	**WP-120**	**WP-121**	**WP-122**
Feature:	East Wall	South Wall	West Wall	South Wall
Height above Floor (ft):	12	17	10	24
Date:	5/8/2015	5/8/2015	5/8/2015	5/9/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***0.52 J***	2.0 U	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***0.52***	***2.0 U***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**WP-130-R**	**WP-131**	**WP-132**	**WP-133-R**
Feature:	Crane	Beam	Beam	Crane
Height above Floor (ft):	~20	30	30	~20
Date:	5/12/2015	5/12/2015	5/12/2015	5/12/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	***0.62 J***	2.0 U	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***0.62***	***2.0 U***	***2.0 U***

Sample ID:	**WP-24-R**	**WP-90-R**	**WP-32-R**	**WP-139**
Feature:	Mobile Crane	Crane Hoist	Crane Track	Stairs (TP)
Height above Floor (ft):	~20	~20	~20	Pit (below floor)
Date:	5/21/2015	5/21/2015	5/21/2015	5/22/2015
Analyte (µg/100 cm^2)				
Aroclor 1016	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1221	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1232	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1242	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1248	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1254	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1260	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1262	2.0 U	2.0 U	2.0 U	2.0 U
Aroclor 1268	2.0 U	2.0 U	2.0 U	2.0 U
Total PCBs (b)	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***

a/ Low contact frequency areas are wipe sample locations collected higher than 8 feet from the floor and samples collected from ducts, drains, pits, and toe rails.
PCBs = polychlorinated biphenyls; µg/100 cm^2 = micrograms per 100 square centimeters; ft = feet; U = analyte not detected; J = estimated concentration.

b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-05	**WP-06**	**WP-10**	**WP-11**	**WP-12**	**WP-13**	**WP-14**	**WP-15**
Crane Track	Light Fixture	Beam	Beam	Crane Track	Mobile Crane	Column	Beam
27	near ceiling	near ceiling	31	22	~20	26	~20
3/25/2015	3/25/2015	3/26/2015	3/26/2015	3/27/2015	3/27/2015	3/27/2015	3/30/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.73 J	2.0 U	2.0 U	***1.8 J***	***0.58 J***	2.0 U	***1.0 J***	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.73	***2.0 U***	***2.0 U***	***1.8***	***0.58***	***2.0 U***	***1.0***	***2.0 U***

WP-22	**WP-23**	**WP-25**	**WP-26**	**WP-27**	**WP-28**	**WP-33**	**WP-34**
Crane	Wall	Duct	Duct	Duct	Beam	Column	Pipe
~20	13	22	22	Ceiling	~20	25	~20
4/6/2015	4/6/2015	4/6/2015	4/6/2015	4/7/2015	4/7/2015	4/9/2015	4/11/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***0.71 J***	***0.51 J***	***1.1 J***	***0.82 J***	***2.3***	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***0.71***	***0.51***	***1.1***	***0.82***	***2.3***	***2.0 U***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-42	**WP-43**	**WP-44**	**WP-45**	**WP-46**	**WP-47**	**WP-48**	**WP-41POST**
Duct	Duct	Duct	Duct	Duct	Duct	Duct	Duct
Ceiling	Ceiling	~20	~20	~20	~25	~25	20
4/16/2015	4/16/2015	4/20/2015	4/20/2015	4/20/2015	4/20/2015	4/20/2015	4/23/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	***0.65 J***	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***0.65***	***2.0 U***	***2.0 U***

WP-56	**WP-57**	**WP-58**	**WP-59**	**WP-60**	**WP-61**	**WP-63**	**WP-64**
Column	Crane Track	Beam	Beam	Beam Plate	Pipe	Pipe	Crane Track
25	25	10	33	30	30	23	20
4/28/2015	4/28/2015	4/28/2015	4/28/2015	4/28/2015	4/28/2015	4/29/2015	4/29/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	***0.59 J***	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
1.7 J	2.0 U	***1.6 J***	2.0 U	2.0 U	2.0 U	***5.1***	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
1.7	***2.0 U***	***1.6***	***2.0 U***	***2.0 U***	***2.0 U***	***5.69***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-69	**WP-70**	**WP-73**	**WP-74**	**WP-78**	**WP-79**	**WP-80**	**WP-81**
Electrical Box	Ceiling	Crane Track	Column	Light Fixture	Beam	Column	Pipe
19	Ceiling	20	25	near ceiling	~20	20	25
4/29/2015	4/29/2015	4/30/2015	4/30/2015	4/30/2015	4/30/2015	4/30/2015	4/30/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.54 J	2.0 U	2.0 U	2.0 U	2.0 U	***0.67 J***	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.54	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***	***0.67***	***2.0 U***	***2.0 U***

WP-86	**WP-IS-01**	**WP-87**	**WP-88**	**WP-89**	**WP-91**	**WP-92**	**WP-97**
Pipe	Light Fixture	Beam	Light Fixture	Beam	Crane Hoist	Crane Track	Pipe
~20	near ceiling	near ceiling	near ceiling	near ceiling	~20	20	~25
4/30/2015	4/30/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/5/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.64 J	2.0 U	***1.9 J***	2.0 U	***0.81 J***	***1.8 J***	***5.7***	***1.1 J***
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.64	***2.0 U***	***1.9***	***2.0 U***	***0.81***	***1.8***	***5.7***	***1.1***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-102	**WP-108**	**WP-109**	**WP-110**	**WP-114**	**WP-115**	**WP-117**	**WP-118**
Beam	North Wall	Light Fixture	Ceiling	North Wall	East Wall	East Wall	East Wall
23	16	near ceiling	Ceiling	13	12	30	27
5/6/2015	5/8/2015	5/8/2015	5/8/2015	5/8/2015	5/8/2015	5/8/2015	5/8/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	***2.4***	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***2.0 U***	***2.0 U***	***2.4***	***2.0 U***	***2.0 U***	***2.0 U***	***2.0 U***

WP-123	**WP-125**	**FDWP-N213-E155**	**FDWP-N219-E146-1**	**WP-126-R**	**FDWP-N217-E202**	**FDWP-N197-E209**	**WP-129**
North Wall	Toe Rail	Floor Drain	Floor Drain	Grate Top	Floor Drain	Floor Drain	Wall Beam
21	0	0	0	0	0	0	10
5/9/2015	5/9/2015	5/12/2015	5/12/2015	5/12/2015	5/12/2015	5/12/2015	5/12/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	***2.2***	***0.81 J***	***2.4***	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	***2.0 U***	***2.0 U***	***2.0 U***	***2.2***	***0.81***	***2.4***	***2.0 U***

Table 5

Wipe Sample Results After Final Cleaning for Low Frequency of Contact Areas
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

WP-134	**WP-135**	**FDWP-N184-E265**	**FDWP-N278-E160-R**	**WP-127-R2**	**WP-136-R**	**WP-137-R**	**WP-138-R**
Beam	South Wall	Floor Drain	Floor Drain	Grate Side	Crane	Crane	Crane
20	18	0	0	0	~20	~20	~20
5/12/2015	5/13/2015	5/21/2015	5/21/2015	5/21/2015	5/21/2015	5/21/2015	5/21/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.78 J	2.0 U	2.0 U	***0.67 J***	***2.4***	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U
0.78	***2.0 U***	***2.0 U***	***0.67***	***2.4***	***2.0 U***	***2.0 U***	***2.0 U***

WP-141	**WP-142**
Ladder (TP)	Grate (TP)
Pit (below floor)	Pit (below floor)
5/22/2015	5/22/2015
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	***1.0 J***
2.0 U	2.0 U
2.0 U	2.0 U
2.0 U	***1.0***

Table 6

Bulk Sample Results After Final Cleaning - Transformer Pit Floor and Walls and Northeast Loading Dock Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**CC-TPSW-01**	**CC-TPWW-01**	**CC-N370-E240**	**CC-N310-E240**
Type:	wall	wall	concrete floor	concrete floor
Location:	Transformer Pit	Transformer Pit	Transformer Pit	Transformer Pit
Date:	4/13/2015	4/13/2015	4/14/2015	4/14/2015
Analyte (mg/kg)				
Aroclor 1016	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1221	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1232	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1242	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1248	***3.4***	***2.0***	1.0 U	***55***
Aroclor 1254	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1260	***1.3***	***1.9***	***510***	***41***
Aroclor 1262	0.99 U	1.0 U	1.0 U	10 U
Aroclor 1268	0.99 U	1.0 U	1.0 U	10 U
Total PCBs (b)	***4.7***	***3.9***	***510***	***96***

a/ PCBs = polychlorinated biphenyls; mg/kg = milligrams per kilogram; U = analyte not detected; J = estimated concentration.

b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.

Table 6

Bulk Sample Results After Final Cleaning - Transformer Pit Floor and Walls and Northeast Loading Dock Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-N330-E238	**CC-N350-E240**	**CC-TP-EW-01**	**CC-TPNW-01**	**CC-LDNE-EW01**	**CC-LDNE-WW01**	**CC-LDNE-SW01**	**CC-TPEW-02**	**CC-TPWW-02**
concrete floor	concrete floor	wall	wall	wall	wall	wall	wall	wall
Transformer Pit	Transformer Pit	Transformer Pit	Transformer Pit	NE Loading Dock	NE Loading Dock	NE Loading Dock	Transformer Pit	Transformer Pit
4/14/2015	4/14/2015	4/14/2015	4/14/2015	4/16/2015	4/16/2015	4/16/2015	5/1/2015	5/1/2015
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
4.1 U	***14 J***	***1.1 J***	***0.44***	1.0 U	20 U	140 U	0.97 U	390 U
60	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	***0.83 J***	390 U
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
27	***300***	***14***	***1.9***	***2.2***	***62***	***390***	***3.1***	***4,500***
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
4.1 U	20 U	2.0 U	0.2 U	1.0 U	20 U	140 U	0.97 U	390 U
87	***314***	***15.1***	***2.34***	***2.2***	***62***	***390***	***3.93***	***4,500***

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-EW-01	CC-NW-01	CC-SELD-01	CC-SELD-02	CC-EW-02
Type:	wall	wall	wall	wall	wall
Date:	3/26/2015	3/27/2015	4/10/2015	4/10/2015	4/10/2015
Analyte (mg/kg)					
Aroclor 1016	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Aroclor 1221	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Aroclor 1232	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Aroclor 1242	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Aroclor 1248	0.2 U	0.2 U	0.2 U	0.2 U	***17***
Aroclor 1254	0.2 U	0.2 U	0.2 U	***0.11 J***	3.9 U
Aroclor 1260	***1.2***	***1.2***	***0.28***	0.2 U	***34***
Aroclor 1262	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Aroclor 1268	0.2 U	0.2 U	0.2 U	0.2 U	3.9 U
Total PCBs (b)	***1.2***	***1.2***	***0.28***	***0.11***	***51***

Sample ID:	CC-OSEW-02	CC-NW-04	CC-WW-04	CC-WW-06	CC-WW-07
Type:	wall	wall	wall	wall	wall
Date:	4/14/2015	4/17/2015	4/17/2015	4/17/2015	4/17/2015
Analyte (mg/kg)					
Aroclor 1016	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Aroclor 1221	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Aroclor 1232	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Aroclor 1242	***0.28 J***	0.96 U	0.26 U	***0.22***	***0.14 J***
Aroclor 1248	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Aroclor 1254	0.4 U	0.96 U	0.26 U	***0.92***	0.2 U
Aroclor 1260	***0.57***	***1.7***	***0.45***	0.2 U	***0.81***
Aroclor 1262	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Aroclor 1268	0.4 U	0.96 U	0.26 U	0.2 U	0.2 U
Total PCBs (b)	***0.85***	***1.7***	***0.45***	***1.14***	***0.95***

Sample ID:	CC-CRNW-01	CC-CRSW-01	CC-CRSW-02	CC-CRWW-01	CC-CRWW-02
Type:	wall	wall	wall	wall	wall
Date:	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015
Analyte (mg/kg)					
Aroclor 1016	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1221	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1232	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1242	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1248	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1254	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1260	***2.9***	***5.4***	***0.47***	***0.16 J***	***0.32***
Aroclor 1262	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U
Aroclor 1268	0.99 U	0.2 U	0.2 U	0.19 U	0.2 U

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Total PCBs (b)	*2.9*	*5.4*	*0.47*	*0.16*	*0.32*

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-BRMWW-02	CC-BRMWW-01	CC-OSWW-03	CC-BRWW-02	CC-BRMEW-01
Type:	wall	wall	wall	wall	wall
Date:	5/5/2015	5/5/2015	5/5/2015	5/5/2015	5/6/2015
Analyte (mg/kg)					
Aroclor 1016	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1221	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1232	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1242	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1248	***0.52***	***0.6***	***0.082 J***	***0.15 J***	***1.0***
Aroclor 1254	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1260	***0.9***	***1.4***	***0.21***	***0.42***	***2.6***
Aroclor 1262	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Aroclor 1268	0.19 U	0.2 U	0.2 U	0.23 U	1.0 U
Total PCBs (b)	***1.42***	***2.0***	***0.292***	***0.57***	***3.6***

Sample ID:	CC-BREW-04	CC-BRSW-01	CC-NW-02	CC-OSEW-03	CC-SW-03
Type:	wall	wall	wall	wall	wall
Date:	5/12/2015	5/12/2015	5/13/2015	5/13/2015	5/14/2015
Analyte (mg/kg)					
Aroclor 1016	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Aroclor 1221	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Aroclor 1232	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Aroclor 1242	***0.35***	0.2 U	***0.69***	***0.095 J***	0.2 U
Aroclor 1248	0.2 U	0.2 U	0.19 U	0.2 U	***0.057 J***
Aroclor 1254	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Aroclor 1260	***1.2***	***0.61***	***1.0***	***0.46***	***0.63***
Aroclor 1262	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Aroclor 1268	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U
Total PCBs (b)	***1.55***	***0.61***	***1.69***	***0.555***	***0.687***

a/ PCBs = polychlorinated biphenyls; mg/kg = milligrams per kilogram; U = analyte not detected; J = estimated concentration.
b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.
c/ Duplicate sample of CC-CREW-01.
d/ Duplicate sample of CC-OSWW-01.
e/ Duplicate sample of CC-BRMEW-01.
f/ Duplicate sample of CC-SWLD-02.

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-SELD-03	**CC-WW-01**	**CC-EW-03**	**CC-EW-05**	**CC-WW-02**	**CC-WW-03**	**CC-BREW-01**	**CC-EW-04**	**CC-OSEW-01**
wall	wall	wall	wall	wall	wall	wall	wall	wall
4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/14/2015	4/14/2015	4/14/2015
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	0.98 U	0.97 U	1.0 U
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	0.98 U	0.97 U	1.0 U
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	0.98 U	0.97 U	1.0 U
0.16 J	***0.73 J***	***0.82 J***	***0.13 J***	***0.58 J***	***0.17 J***	***1.0***	0.97 U	***0.97 J***
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	9.8 U	0.97 U	1.0 U
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	9.8 U	0.97 U	1.0 U
2.2	***4.1***	***2.7***	***1.7***	***2.5***	***1.2***	***2.8***	***2.2***	***2.4***
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	9.8 U	0.97 U	1.0 U
0.2 U	2.0 U	1.0 U	0.2 U	1.0 U	0.2 U	9.8 U	0.97 U	1.0 U
2.36	***4.83***	***3.52***	***1.83***	***3.08***	***1.37***	***3.8***	***2.2***	***3.37***

CC-WW-09	**CC-WW-05**	**CC-WW-08**	**CC-NW-05**	**CC-SRNW-01**	**CC-SRSW-01**	**CC-SRWW-01**	**CC-CREW-01**	**CC-DUP-10 (c)**
wall	wall	wall	wall	wall	wall	wall	wall	wall
4/17/2015	4/17/2015	4/17/2015	4/21/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.11 J	***0.49***	***0.15 J***	***0.12 J***	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.85	***1.0***	***0.42***	***0.58***	***0.39***	***0.25***	***0.56***	***0.41***	***0.47***
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.2 U	0.2 U	210 U	0.19 U	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
0.96	***1.49***	***0.57***	***0.70***	***0.39***	***0.25***	***0.56***	***0.41***	***0.47***

CC-SREW-01	**CC-BREW-03**	**CC-BRWW-01**	**CC-OSNW-01**	**CC-OSWW-01**	**CC-DUP-11 (d)**	**CC-OSWW-02**	**CC-BRMEW-02**	**CC-BRMSW-01**
wall	wall	wall	wall	wall	wall	wall	wall	wall
5/1/2015	5/2/2015	5/2/2015	5/2/2015	5/2/2015	5/2/2015	5/2/2015	5/5/2015	5/5/2015
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.19 U	***0.39***	***0.58***	***0.41***	0.2 U	0.2 U	0.2 U	***0.78 J***	***0.58 J***
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.57	***1.0***	***1.0***	***0.76***	***0.078 J***	***0.073 J***	***0.085 J***	***1.8***	***1.7***
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U
0.19 U	0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U	0.99 U	0.99 U

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

0.57	*1.39*	*1.58*	*1.17*	*0.078*	*0.073*	*0.085*	*2.58*	*2.28*

Table 7

Bulk Sample Results After Final Cleaning - Building Walls
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-DUP-12 (e)	CC-BRWW-04	CC-BRWW-03	CC-BRNW-01	CC-BRMNW-01	CC-OSSW-01	CC-OSMNW-01	CC-BREW-02	CC-NW-03
wall	wall	wall	wall	wall	wall	wall	wall	wall
5/6/2015	5/6/2015	5/6/2015	5/6/2015	5/6/2015	5/7/2015	5/7/2015	5/12/2015	5/12/2015
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	***0.22***	***0.14 J***
0.95 J	***0.17 J***	***0.9 J***	***0.9 J***	***0.42***	0.2 U	0.2 U	0.2 U	0.2 U
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
2.1	***0.54***	***2.3***	***2.1***	***0.96***	***0.3***	***0.14 J***	***1.1***	***0.96***
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
0.97 U	0.2 U	0.97 U	1.0 U	0.2 U	0.2 U	0.2 U	0.2 U	0.2 U
3.05	***0.71***	***3.2***	***3.0***	***1.38***	***0.3***	***0.14***	***1.32***	***1.1***

CC-WW-10	CC-SWLD-01	CC-SWLD-02	CC-DUP-14 (f)	CC-SW-01	CC-SW-02
wall	wall	wall	wall	wall	wall
5/14/2015	5/14/2015	5/14/2015	5/14/2015	5/14/2015	5/14/2015
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.11 J	***0.11 J***	0.19 U	***0.068 J***	0.2 U	0.2 U
0.2 U	0.2 U	0.19 U	0.2 U	***0.082 J***	***0.28***
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.58	***0.44***	***0.66***	***0.51***	***0.29***	***1.2***
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.2 U	0.2 U	0.19 U	0.2 U	0.2 U	0.2 U
0.69	***0.55***	***0.66***	***0.578***	***0.372***	***1.48***

Table 8

Bulk Floor Sample Results After Final Cleaning - North of Grid Line N220
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-N310-E260	CC-N350-E220	CC-270-E260	CC-N270-E240	CC-290-E240
Type:	concrete	concrete	concrete	concrete	concrete
Date:	3/27/2015	3/27/2015	3/28/2015	3/28/2015	3/28/2015
Analyte (mg/kg)					
Aroclor 1016	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1221	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1232	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1242	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1248	10 U	***1.3***	***42***	20 U	20 U
Aroclor 1254	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1260	***41***	***5.2***	***42***	***110***	***84***
Aroclor 1262	10 U	1.0 U	10 U	20 U	20 U
Aroclor 1268	10 U	1.0 U	10 U	20 U	20 U
Total PCBs (b)	***41***	***6.5***	***84***	***110***	***84***

Sample ID:	CC-N270-E180	CC-N270-E200	CC-N330-E220	CC-N350-E260	CC-N370-E220
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/7/2015	4/7/2015	4/7/2015	4/7/2015	4/7/2015
Analyte (mg/kg)					
Aroclor 1016	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1221	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1232	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1242	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1248	20 U	20 U	2.1 U	***0.12 J***	2.0 U
Aroclor 1254	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1260	***72***	***60***	***7.8***	***0.27***	***8.9***
Aroclor 1262	20 U	20 U	2.1 U	0.2 U	2.0 U
Aroclor 1268	20 U	20 U	2.1 U	0.2 U	2.0 U
Total PCBs (b)	***72***	***60***	***7.8***	***0.39***	***8.9***

Sample ID:	CC-E57-N270	CC-E77-N230	CC-E77-N250	CC-DUP-05 (c)	CC-E100-N250
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/14/2015	4/14/2015	4/14/2015	4/14/2015	4/21/2015
Analyte (mg/kg)					
Aroclor 1016	10 U	2.0 U	2.0 U	2.0 U	20 U
Aroclor 1221	10 U	2.0 U	2.0 U	2.0 U	20 U
Aroclor 1232	10 U	2.0 U	2.0 U	2.0 U	20 U
Aroclor 1242	10 U	2.0 U	***2.2***	2.0 U	20 U
Aroclor 1248	***35***	2.0 U	2.0 U	***3.5***	***190***
Aroclor 1254	10 U	2.0 U	2.0 U	2.0 U	20 U
Aroclor 1260	***9.5 J***	***5.7***	***12***	***8.7***	***20***
Aroclor 1262	10 U	2.0 U	2.0 U	2.0 U	20 U
Aroclor 1268	10 U	2.0 U	2.0 U	2.0 U	20 U

Table 8

Bulk Floor Sample Results After Final Cleaning - North of Grid Line N220
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Total PCBs (b)	***44.5***	***5.7***	***14.2***	***12.2***	***210***

Sample ID:	**CC-N290-E180**	**CC-DUP-09 (d)**	**CC-N290-E208**	**CC-N310-E180**	**CC-N315-E208**
Type:	concrete	concrete	concrete	concrete	concrete
Date:	5/1/2015	5/1/2015	5/1/2015	5/1/2015	5/1/2015
Analyte (mg/kg)					
Aroclor 1016	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1221	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1232	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1242	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1248	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1254	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1260	***27***	***28***	***1***	***45***	***60***
Aroclor 1262	4.0 U	4.0 U	0.2 U	10 U	20 U
Aroclor 1268	4.0 U	4.0 U	0.2 U	10 U	20 U
Total PCBs (b)	***27***	***28***	***1***	***45***	***60***

a/ PCBs = polychlorinated biphenyls; mg/kg = miligrams per kilogram; U = analyte not detected; J = estimated concentration.
b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.
c/ Duplicate sample of CC-E77-N250.
d/ Duplicate sample of CC-N290-E180.

Table 8

Bulk Floor Sample Results After Final Cleaning - North of Grid Line N220
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-N290-E260	CC-N310-E220	CC-N230-E220	CC-N230-E240	CC-N250-E220	CC-N250-E240	CC-N250-E260	CC-N230-E260	CC-N250-E180
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
3/28/2015	3/28/2015	3/30/2015	3/30/2015	3/30/2015	3/30/2015	3/30/2015	3/31/2015	4/7/2015
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	***5.8***	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
21	***5.6***	***1.2***	***14***	***6.4***	***18***	***17***	***8.6***	***21***
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
4.1 U	2.0 U	0.2 U	2.0 U	0.98 U	2.0 U	2.0 U	1.0 U	4.0 U
21	***11.4***	***1.2***	***14***	***6.4***	***18***	***17***	***8.6***	***21***

CC-N250-E200	CC-N330-E245	CC-N310-E236	CC-N346-E235	CC-N230-E180	CC-N230-E200	CC-E57-N230	CC-E77-N270	CC-E57-N250
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/7/2015	4/7/2015	4/7/2015	4/7/2015	4/8/2015	4/8/2015	4/14/2015	4/14/2015	4/14/2015
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
2.0 U	20 U	0.2 U	***1.7***	4.0 U	4.1 U	***1.1 J***	9.8 U	20 U
2.0 U	20 U	***0.68***	1.0 U	4.0 U	4.1 U	2.0 U	***72***	20 U
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
12	***81***	***0.83***	***3.6***	***21***	***14***	***12***	***51***	***150***
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
2.0 U	20 U	0.2 U	1.0 U	4.0 U	4.1 U	2.0 U	9.8 U	20 U
12	***81***	***1.51***	***5.3***	***21***	***14***	***13.1***	***123***	***150***

CC-E100-N270	CC-E120-N230	CC-E120-N270	CC-E140-N230	CC-E140-N270	CC-E100-N230	CC-E120-N250	CC-E140-N250
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/21/2015	4/21/2015	4/21/2015	4/21/2015	4/21/2015	4/21/2015	4/21/2015	4/21/2015
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	***1.5 J***	***3.5 J***	1.0 U
7.2	2.0 U	***2.9***	1.0 U	***2.8***	1.9 U	3.9 U	1.0 U
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U
8.3	***7.8***	***6.1***	***3.7***	***15***	***9.8***	***20***	***2.4***
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U
2.0 U	2.0 U	1.0 U	1.0 U	2.1 U	1.9 U	3.9 U	1.0 U

Table 8

Bulk Floor Sample Results After Final Cleaning - North of Grid Line N220
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

15.5	***7.8***	***9***	***3.7***	***17.8***	***11.3***	***23.5***	***2.4***

CC-E160-N270	**CC-E160-N250**	**CC-E160-N230**	**CC-N300-E190-R**	**CC-N270-E222**	**CC-N290-E220**	**CC-N370-E245**
concrete	concrete	concrete	concrete	concrete	concrete	concrete
5/12/2015	5/12/2015	5/12/2015	5/13/2015	5/13/2015	5/13/2015	4/7/2015
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
1.2	***25***	***11***	***25***	***36***	***4.8***	***130***
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
0.2 U	4.0 U	2.0 U	4.0 U	9.7 U	0.99 U	20 U
1.2	***25***	***11***	***25***	***36***	***4.8***	***130***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-N190-E220	CC-N190-E240	CC-N210-E220	CC-N210-E240	CC-N213-E262
Type	concrete	concrete	concrete	concrete	concrete
Date:	3/31/2015	3/31/2015	3/31/2015	3/31/2015	3/31/2015
Analyte (mg/kg)					
Aroclor 1016	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1221	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1232	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1242	1.0 U	***0.45 J***	0.98 U	1.0 U	***0.073 J***
Aroclor 1248	***3.4***	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1254	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1260	***10***	***5.5***	***12***	***6.2***	***3***
Aroclor 1262	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Aroclor 1268	1.0 U	1.0 U	0.98 U	1.0 U	0.2 U
Total PCBs (b)	***13.4***	***5.95***	***12***	***6.2***	***3.073***

Sample ID:	CC-N150-E240	CC-N150-E260	CC-N190-E262	CC-N110-E260	CC-N130-E240
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/1/2015	4/1/2015	4/1/2015	4/2/2015	4/2/2015
Analyte (mg/kg)					
Aroclor 1016	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1221	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1232	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1242	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1248	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1254	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1260	***4.9***	***0.56***	***0.32***	***16***	***9.5***
Aroclor 1262	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Aroclor 1268	0.96 U	0.2 U	0.19 U	2.0 U	1.9 U
Total PCBs (b)	***4.9***	***0.56***	***0.32***	***16***	***9.5***

Sample ID:	CC-N90-E240	CC-N10-E221	CC-N50-E220	CC-N10-E240	CC-N10-E260
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/3/2015	4/3/2015	4/3/2015	4/4/2015	4/4/2015
Analyte (mg/kg)					
Aroclor 1016	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1221	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1232	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1242	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1248	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1254	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1260	***4.9***	***2.5***	***0.54***	***1.1***	***2.2***
Aroclor 1262	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Aroclor 1268	0.98 U	0.99 U	0.2 U	0.2 U	0.99 U
Total PCBs (b)	***4.9***	***2.5***	***0.54***	***1.1***	***2.2***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-N150-E180	CC-N150-E200	CC-N170-E180	CC-N50-E180	CC-DUP-03 (e)
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/9/2015	4/9/2015	4/9/2015	4/9/2015	4/9/2015
Analyte (mg/kg)					
Aroclor 1016	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1221	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1232	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1242	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1248	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1254	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1260	***7.3***	***6.3***	***3.1***	***1.9***	***2.1***
Aroclor 1262	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Aroclor 1268	2.0 U	2.0 U	1.0 U	1.0 U	0.99 U
Total PCBs (b)	***7.3***	***6.3***	***3.1***	***1.9***	***2.1***

Sample ID:	CC-N10-E180	CC-N10-E200	CC-N30-E200	CC-N70-E200	CC-E60-N150
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/11/2015	4/11/2015	4/11/2015	4/11/2015	4/15/2015
Analyte (mg/kg)					
Aroclor 1016	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1221	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1232	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1242	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1248	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1254	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1260	***3***	***2.7***	***5***	***5.1***	***2.2***
Aroclor 1262	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Aroclor 1268	0.99 U	0.2 U	1.0 U	2.0 U	0.98 U
Total PCBs (b)	***3***	***2.7***	***5***	***5.1***	***2.2***

Sample ID:	CC-E80-N110	CC-E80-N130	CC-E60-N130	CC-E80-N90	CC-E60-N70
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/16/2015	4/16/2015	4/16/2015	4/16/2015	4/16/2015
Analyte (mg/kg)					
Aroclor 1016	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1221	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1232	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1242	***0.97 J***	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1248	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1254	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1260	***3.1***	***1.3***	***1.5***	***0.19 J***	***0.5***
Aroclor 1262	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Aroclor 1268	1.0 U	1.0 U	0.99 U	0.2 U	0.2 U
Total PCBs (b)	***4.07***	***1.3***	***1.5***	***0.19***	***0.5***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	CC-E120-N210	CC-E140-N170	CC-E140-N190	CC-E140-N210	CC-E100-N190
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/21/2015	4/21/2015	4/21/2015	4/21/2015	4/21/2015
Analyte (mg/kg)					
Aroclor 1016	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1221	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1232	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1242	2.0 U	1.0 U	1.0 U	***1.1 J***	***0.61 J***
Aroclor 1248	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1254	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1260	***8.9***	***3.1***	***2.5***	***3.9***	***1.7***
Aroclor 1262	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Aroclor 1268	2.0 U	1.0 U	1.0 U	2.1 U	1.0 U
Total PCBs (b)	***8.9***	***3.1***	***2.5***	***5***	***2.31***

Sample ID:	CC-E120-N130	CC-E120-N150	CC-E120-N90	CC-E140-N110	CC-E140-N150
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/22/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015
Analyte (mg/kg)					
Aroclor 1016	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1221	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1232	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1242	0.38 U	0.95 U	***0.53***	0.93 U	1.9 U
Aroclor 1248	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1254	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1260	***0.86***	***5.1***	***1.4***	***3.1***	***14***
Aroclor 1262	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Aroclor 1268	0.38 U	0.95 U	0.19 U	0.93 U	1.9 U
Total PCBs (b)	***0.86***	***5.1***	***1.93***	***3.1***	***14***

Sample ID:	CC-E120-N10	CC-E120-N30	CC-E120-N50	CC-E120-N70	CC-E140-N90
Type:	concrete	concrete	concrete	concrete	concrete
Date:	4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015
Analyte (mg/kg)					
Aroclor 1016	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Aroclor 1221	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Aroclor 1232	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Aroclor 1242	0.2 U	0.2 U	0.2 U	***0.29***	***0.33***
Aroclor 1248	0.2 U	0.2 U	***0.2***	0.19 U	0.19 U
Aroclor 1254	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Aroclor 1260	***0.19 J***	***0.49***	***0.64***	***1.3***	***2.9***
Aroclor 1262	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Aroclor 1268	0.2 U	0.2 U	0.2 U	0.19 U	0.19 U
Total PCBs (b)	***0.19***	***0.49***	***0.84***	***1.59***	***3.23***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**CC-N170-E160-M**	**CC-N147-E160-M**	**CC-N190-E160-M**	**CC-N128-E160-M**	**CC-N110-E160-M**
Type:	concrete	concrete	concrete	concrete	concrete
Date:	5/6/2015	5/6/2015	5/6/2015	5/7/2015	5/7/2015
Analyte (mg/kg)					
Aroclor 1016	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Aroclor 1221	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Aroclor 1232	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Aroclor 1242	1.0 U	0.98 U	0.99 U	0.19 U	***0.12 J***
Aroclor 1248	***0.61 J***	0.98 U	***0.33 J***	0.19 U	0.2 U
Aroclor 1254	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Aroclor 1260	***5.7***	***2.7***	***3.5***	***0.18 J***	***1.3***
Aroclor 1262	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Aroclor 1268	1.0 U	0.98 U	0.99 U	0.19 U	0.2 U
Total PCBs (b)	***6.31***	***2.7***	***3.83***	***0.18***	***1.42***

a/ PCBs = polychlorinated biphenyls; mg/kg = milligrams per kilogram; U = analyte not detected; J = estimated concentration.
b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.
c/ Duplicate sample of CC-N170-E240.
d/ Duplicate sample of CC-N210-E200.
e/ Duplicate sample of CC-N50-E180.
f/ Duplicate sample of CC-N130-E180.
g/ Duplicate sample of CC-E60-N70.
h/ Duplicate sample of CC-E100-N50.
i/ Duplicate sample of CC-E160-N5.
j/ Duplicate sample of CC-N110-E160-M.

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-N170-E240	CC-DUP-01 (c)	CC-N170-E220	CC-N170-E260	CC-N110-E220	CC-N130-E240	CC-N134-E220	CC-N150-E220
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/1/2015	4/1/2015	4/1/2015	4/1/2015	4/1/2015	4/1/2015	4/1/2015	4/1/2015
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
2.0 U	2.0 U	1.0 U	***0.12 J***	2.0 U	2.0 U	***0.066 J***	2.0 U
2.0 U	2.0 U	***1.5***	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
17	***17***	***5***	***0.51***	***11***	***15***	***1.3***	***9.1***
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
2.0 U	2.0 U	1.0 U	0.2 U	2.0 U	2.0 U	0.2 U	2.0 U
17	***17***	***6.5***	***0.63***	***11***	***15***	***1.366***	***9.1***

CC-N130-E260	CC-N90-E260	CC-N30-E221	CC-N50-E240	CC-N50-E260	CC-N70-E220	CC-N70-E240	CC-N70-E260	CC-N90-E221
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/2/2015	4/2/2015	4/3/2015	4/3/2015	4/3/2015	4/3/2015	4/3/2015	4/3/2015	4/3/2015
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
8.4	***9.3***	***9.9***	***8.7***	***8***	***0.81***	***7.6***	***1.1***	***11***
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	0.2 U	1.9 U	0.2 U	1.9 U
8.4	***9.3***	***9.9***	***8.7***	***8***	***0.81***	***7.6***	***1.1***	***11***

CC-N30-E235	CC-N30-E260	CC-N190-E180	CC-N190-E200	CC-N210-E200	CC-DUP-02 (d)	CC-N50-E200	CC-N210-E180	CC-N130-E200
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/4/2015	4/4/2015	4/8/2015	4/8/2015	4/8/2015	4/8/2015	4/8/2015	4/8/2015	4/9/2015
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	***0.39 J***	***0.62 J***	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
7	***11***	***3.6***	***6.2***	***8.3***	***11***	***0.98***	***4.5***	***0.27***
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
2.0 U	2.0 U	0.98 U	2.0 U	2.0 U	2.0 U	0.2 U	1.0 U	0.21 U
7	***11***	***3.99***	***6.82***	***8.3***	***11***	***0.98***	***4.5***	***0.27***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-N170-E200	CC-N110-E180	CC-N110-E200	CC-N90-E180	CC-N130-E180	CC-DUP-04 (f)	CC-N90-E200	CC-N30-E181	CC-N70-E180
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/9/2015	4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/10/2015	4/11/2015	4/11/2015
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	***0.068 J***	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
3	***13***	***0.61***	***6.8***	***3.3***	***3.9***	***0.41***	***1.4***	***2***
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
0.99 U	2.0 U	0.2 U	2.0 U	0.99 U	0.99 U	0.2 U	0.2 U	1.0 U
3	***13***	***0.61***	***6.8***	***3.3***	***3.9***	***0.41***	***1.468***	***2***

CC-E60-N190	CC-E60-N210	CC-E80-N150	CC-E80-N190	CC-E80-N210	CC-E60-N170	CC-E80-N170	CC-E60-N110	CC-E60-N90
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/15/2015	4/15/2015	4/15/2015	4/15/2015	4/15/2015	4/15/2015	4/15/2015	4/16/2015	4/16/2015
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
0.58 J	9.8 U	1.0 U	***1.7 J***	***1.1 J***	20 U	1.0 U	3.9 U	1.0 U
1.0 U	***58***	1.0 U	4.0 U	2.0 U	20 U	1.0 U	***29***	1.0 U
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
5.3	***4.1 J***	***3.6***	***18***	***7.3***	***130***	***1.9***	***2.9 J***	***1.7***
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
1.0 U	9.8 U	1.0 U	4.0 U	2.0 U	20 U	1.0 U	3.9 U	1.0 U
5.88	***62.1***	***3.6***	***19.7***	***8.4***	***130***	***1.9***	***31.9***	***1.7***

CC-DUP-06 (g)	CC-E60-N30	CC-E60-N50	CC-E80-N30	CC-E80-N50	CC-E80-N70	CC-E60-N10	CC-E80-N10	CC-E120-N190
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/16/2015	4/17/2015	4/17/2015	4/17/2015	4/17/2015	4/17/2015	4/18/2015	4/18/2015	4/21/2015
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	***0.37 J***	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.37	***2.5***	***4.7***	***0.93***	***2.7***	***0.76***	***3.3***	***1.5***	***6.5***
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.21 U	0.99 U	0.99 U	0.28 U	0.99 U	0.2 U	1.0 U	0.98 U	2.0 U
0.37	***2.5***	***5.07***	***0.93***	***2.7***	***0.76***	***3.3***	***1.5***	***6.5***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-E100-N210	CC-E100-N170	CC-E120-N170	CC-E100-N150	CC-E100-N90	CC-E120-N110	CC-E140-N130	CC-E100-N110	CC-E100-N130
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/21/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015	4/22/2015
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.0 U	***0.18 J***	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.0 U	0.2 U	2.0 U	3.9 U	***0.64***	0.2 U	1.0 U	***0.25***	***0.11 J***
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.3	***0.52***	***4.8***	***12***	***0.56***	***0.93***	***3.1***	***1***	***0.41***
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.0 U	0.2 U	2.0 U	3.9 U	0.2 U	0.2 U	1.0 U	0.18 U	0.2 U
1.3	***0.7***	***4.8***	***12***	***1.2***	***0.93***	***3.1***	***1.25***	***0.52***

CC-E140-N10	CC-E140-N30	CC-E140-N50	CC-E140-N70	CC-E100-N10	CC-E100-N30	CC-E100-N50	CC-DUP-08 (h)	CC-E100-N70
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015	4/23/2015
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	***0.36***
0.19 U	0.2 U	0.19 U	***0.49 J***	0.2 U	***0.062 J***	0.19 U	0.19 U	0.18 U
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.15 J	***0.44***	***0.88***	***1.2***	***0.11 J***	***0.35***	***0.33***	***0.084 J***	***0.98***
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.19 U	0.2 U	0.19 U	0.97 U	0.2 U	0.19 U	0.19 U	0.19 U	0.18 U
0.15	***0.44***	***0.88***	***1.69***	***0.11***	***0.412***	***0.33***	***0.084***	***1.34***

CC-E160-N50	CC-DUP-07 (i)	CC-E160-N10	CC-E160-N150	CC-E160-N190	CC-E160-N210	CC-E160-N30	CC-E160-N70
concrete	concrete	concrete	concrete	concrete	concrete	concrete	concrete
4/23/2015	4/23/2015	4/24/2015	4/24/2015	4/24/2015	4/24/2015	4/24/2015	4/24/2015
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.37	***0.25***	***0.072 J***	***8.5***	***2.3***	***56***	***0.41***	***0.92***
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.2 U	0.2 U	0.2 U	2.0 U	1.0 U	9.9 U	0.2 U	0.2 U
0.37	***0.25***	***0.072***	***8.5***	***2.3***	***56***	***0.41***	***0.92***

Table 9

Bulk Floor Sample Results After Final Cleaning - South of Grid Line N220 and Mezzanine Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

CC-DUP-13 (j)	**CC-N90-E190-M**	**CC-N168-E160**	**CC-N130-E158**	**CC-N110-E160**	**CC-N89-E160**
concrete	concrete	concrete	concrete	concrete	concrete
5/7/2015	5/7/2015	5/12/2015	5/14/2015	5/14/2015	5/14/2015
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.11 J	0.97 U	0.2 U	***0.41***	***0.47***	***0.36***
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.99	***2.3***	***0.54***	***0.3***	***0.96***	***1.3***
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
0.2 U	0.97 U	0.2 U	0.19 U	0.2 U	0.2 U
1.1	***2.3***	***0.54***	***0.71***	***1.43***	***1.66***

Table 10

Bulk Dust Sample Results from HVAC System in Western Office Area
Former Westinghouse Apparatus Repair Facility
Rancho Dominguez, California (a)

Sample ID:	**HVACBK-01**	**BK-MO-01**
Type:	bulk dust	bulk dust
Date:	4/13/2015	4/30/2015
Analyte (mg/kg)		
Aroclor 1016	0.77 U	0.48 U
Aroclor 1221	0.77 U	0.48 U
Aroclor 1232	0.77 U	0.48 U
Aroclor 1242	***0.36 J***	***2.2***
Aroclor 1248	0.77 U	0.48 U
Aroclor 1254	0.77 U	0.48 U
Aroclor 1260	***3.4***	***1.7***
Aroclor 1262	0.77 U	0.48 U
Aroclor 1268	0.77 U	0.48 U
Total PCBs (b)	***3.76***	***3.9***

a/ PCB = polychlorinated biphenyls; mg/kg = milligrams per kilogram; U = analyte not detected; J = estimated concentration.

b/ Total PCBs are the sum of detected individual Aroclor concentrations. Aroclors not detected (i.e., flagged "U") are assumed to not contribute to the total PCB concentration.