COUNTY OF LOS ANGELES • FIRE DEPARTMENT
FIRE PREVENTION, PREPAREDNESS, AND CONSERVATION BUREAU
HAZARDOUS MATERIALS CONTROL PROGRAM

SEMS-RM
DOCID #
1166054

CASE UPDATE / PHONE LOG

Company / Case Name | Log #

DATE	HMS INIT.	FINDINGS / REMARKS
3/19/96	JW	FU to how waste was disposed of. TC: Chris Bonds, ENCON 818-846-9280. He said he did not receive letter dated 12/8/94. It was faxed to him. He stated waste was analyzed & non HW. He also stated Jenny Au of RWQCB was providing oversight w/ the GW impact.
3/19/96	JW	TC: Left message for Jenny Au (RWQCB) @ 213-266-7576.
5/96	JW	TC: Jenny Au (on vacation for ~2 wks)
6/12/96	JW	TC: Jenny Au - confirmed RWQCB is lead agency
7/30/96	JW	FU letter to RP, RWQCB, consultant

MCP • 8/91 rv 2.0

Page

COUNTY OF LOS ANGELES • FIRE DEPARTMENT
FIRE PREVENTION, PREPAREDNESS, AND CONSERVATION BUREAU
HAZARDOUS MATERIALS CONTROL PROGRAM

CASE UPDATE / PHONE LOG

Company / Case Name		Log #

DATE	HMS INIT.	FINDINGS / REMARKS
9/28/94	JW	Site visit w/ Tom Klinger, Judy Watkins from this Dept + Mike Flak from Emcon representing Dial Corp. Meeting/visit set up by JW to discuss which agency is overseeing clean up. Mike Flak explained he has been sending reports to RWQCB as a Quarterly Summary + also to DPW. Site visit revealed. 1. Cooper Drum (DTSC Clean up site) is located across the street. This company may have impacted GW w/ TCE 2. Full site closure of facility has not been done. Residual wastes must be removed. These include paints cyclone wastes, bag house wastes, sludges, clarifier sludge, waste oil. 3. Parking lot area (south side of facility) has not always been a parking lot. It was a former cleaning room area + a former foundry. Monitoring wells have chlorinated solvents (not found in soils). There is a perched GW @ 20' Soil Samples show TRPH + BTEX 4. Site has identified the following contaminants so far: dodecylbenzene (8015M) PH = 7-8 or 9.2 Monitoring Well #6 shows low-const BTEX + VOC's
9/29/96	JW/TK	TC: Discussed site w/ Miguel Monroy of DTSC. This site if not a GW threat will ~~[illegible]~~ have oversight by DTSC

HMCP • 8/91 • v 2.0

Page

COUNTY OF LOS ANGELES • FIRE DEPARTMENT
FIRE PREVENTION, PREPAREDNESS, AND CONSERVATION BUREAU
HAZARDOUS MATERIALS CONTROL PROGRAM

CASE UPDATE / PHONE LOG

Company / Case Name	The Dial Corp	Log #	

DATE	HMS INIT.	FINDINGS / REMARKS
10/13/93	LR	TC with Scott Sankey, Planning to excavate TPH contamination from South Parking lot - cleaning up to 100 ppm TPH, 1 ppm EB and 1 ppm X. Discussed letter sent to Jim Nishida - advised him Title 23 does not apply to us and no Statutory Requirement for HHMD Review - Site would be low priority and long review time. He stated his client wanted closure letter from Reg agency. Advised him to process with cleanup and sent final report to me - will see about closure letter - No promise made - Recommended 6-12 confirmation samples (every 20' on so on side walls and bottom of excavation. He will sent after remediation report and call me.
9/15/94	JW	Review of File TC to Emcon Assoc. (Project H93) the project Mgr. is now Mike Flak. I left a message on his voice mail to call me.
9/20/94	JW	Called + Mike Flak not available
9/20/94	JW	TC Mike Flak. This site is still looking for regulatory oversight. There are UGST removal + GW has "mildly been impacted". I will discuss case w/ TK re: GW + UGST + on site appointment has been made for 9:30 AM 9/28/94.
9/22/94	JW	advised Mike Flak that Tom Klinger will attend Meeting on 9/28/94.

MCP • 8/91 ~ 2.0

COUNTY OF LOS ANGELES • FIRE DEPARTMENT
PREVENTION BUREAU
HAZARDOUS WASTE CONTROL PROGRAM

CASE UPDATE / PHONE LOG

Company / Case Name	The Dial Corp / former Purex Corp	Log #

DATE	HMS INIT.	FINDINGS / REMARKS
		9300 Rayo Ave
		South Gate 90280
		TG 59 D-3
3/31/93	TWK	TC w/ Scott Sankey of Emcon Assoc 818 841-1160 representing Dial Corp. He sent 7 pg "report letter re above site. Facility closed 7 15 months & DPW overseeing UGT removal. 7 monitoring wells on site. Letter indicates concern about allegedly non-haz dodecylbenzene in an area designated "alkylate area" apparently this comes up on 8018 M, but RP/asserts is non-haz detergent ingredient. Discussed the matter w/ Sankey @ length. I advised that all appropriate Haz waste testing should be done, including bioassay on the source waste and in contaminated soil (He said not done) TPH in this area max 22,000 @ 5-15' bgs. GW in site @ 53' bgs. I advised that if this is a non-haz waste, only the RWQCB could approve it's being left in place. I suggested it be disposed unless RWQCB concurrence w/ no action proposal. Advised Closure oversight not statutorily reqd by HHMD. He was concerned about a parking lot area w/ TPH @ 3000 ppm max w/ X @ 19 ppm and EB @ 8.2 ppm. I advised it be removed to < 100 ppm TPH and appropriate BTEX cleanup per DPW standards. Suggested he review issues w/ RP & agreed to meet in multi-agency meeting to clarify, if needed. Hold - No action @ this time.
7/1/93	TWK	No further correspondence or calls on site issues. Since RWQCB & DPW actively involved, and no RP request, will file NFA. TWK

HWCP • 5/92 • v 2.1