| | A | B | C | D | E | F | G | H | I | J |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | **LabNumber** | **Analysis** | **Sampled** | **Status** | **Project** | **SampleName** | **SampleType** | **SampleComments** | **Canister ID** | **SampleInfo2** |
| 2 | 8111508-01 | TO-15 2018 | 11/14/18 10:22 | Invalid | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | VOID Col 1 Start 10:22 11/13/18 Probe #10314 - >3" difference from field to lab | 5079 | 3.50" Hg |
| 3 | 8111508-03 | TO-15 2018 | 11/14/18 10:00 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Start 10:00 11/13/18 Probe #10315 | A21028 | 2.00" Hg |
| 4 | 8111508-04 | TO-15 2018 | 11/14/18 10:00 | Reported | EtO Region 5 | WB Trip Blank | Field Sample | Trip Blank | 5037 | 29.50" Hg |
| 5 | 8111508-02 | TO-15 2018 | 11/14/18 10:23 | Invalid | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | VOID Col 2 Start 10:23 11/13/18 Probe #10313 - >3" difference between field and lab | SAT057 | 1.00" Hg |
| 6 | 8112012-01 | TO-15 2018 | 11/17/18 10:07 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Start 10:24 11/16/18 Probe #10313 | A21096 | 2.00" Hg |
| 7 | 8112012-02 | TO-15 2018 | 11/17/18 09:57 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Start 10:09 11/16/18 Probe #10314 | SAT085 | 2.50" Hg |
| 8 | 8112012-03 | TO-15 2018 | 11/17/18 09:57 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 10:09 11/16/18 Probe #10315 | SAT114 | 3.50" Hg |
| 9 | 8112113-01 | TO-15 2018 | 11/20/18 09:30 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Start 09:32 11/19/18 Probe #10315 | A21102 | 2.00" Hg |
| 10 | 8112113-03 | TO-15 2018 | 11/20/18 09:21 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Start 09:20 11/19/18 Probe #10314 | 5077 | 3.50" Hg |
| 11 | 8112113-04 | TO-15 2018 | 11/20/18 10:36 | Reported | EtO Region 5 | Gower ES | Field Sample | Start 10:36 11/19/18 Probe #10293 | SAT092 | 3.50" Hg |
| 12 | 8112113-05 | TO-15 2018 | 11/20/18 09:39 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:46 11/19/18 Probe #10311 | 18879 | 2.00" Hg |
| 13 | 8112113-06 | TO-15 2018 | 11/20/18 10:10 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Start 10:10 11/19/18 Probe #10294 | SAT089 | 2.50" Hg |
| 14 | 8112113-07 | TO-15 2018 | 11/20/18 09:54 | Reported | EtO Region 5 | Watertower | Field Sample | Start 09:59 11/19/18 Probe #10312 | SAT169 | 2.00" Hg |
| 15 | 8112113-08 | TO-15 2018 | 11/20/18 10:25 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:25 11/19/18 Probe #10076 | A21051 | 4.00" Hg |
| 16 | 8112113-09 | TO-15 2018 | 11/20/18 10:45 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Start 10:45 11/19/18 Probe #10310 | SAT025 | 3.00" Hg |
| 17 | 8112113-02 | TO-15 2018 | 11/20/18 09:29 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C1 | Col 2 Start 09:33 11/19/18 Probe #10315 | SAT013 | 3.50" Hg |
| 18 | 8112702-04 | TO-15 2018 | 11/24/18 10:35 | Reported | EtO Region 5 | Gower ES | Field Sample | Start 10:35 11/23/18 Probe #10293 | SAT097 | 4.50" Hg |
| 19 | 8112702-03 | TO-15 2018 | 11/24/18 09:41 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:36 11/23/18 Probe #10311 | SAT135 | 3.00" Hg |
| 20 | 8112702-08 | TO-15 2018 | 11/24/18 10:23 | Invalid | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:23 11/23/18 Probe #10076 | SAT143 | 5.00" Hg |
| 21 | 8112702-01 | TO-15 2018 | 11/24/18 09:57 | Reported | EtO Region 5 | Watertower | Field Sample | Start 09:57 11/23/18 Probe #10312 | 18877 | 3.50" Hg |
| 22 | 8112702-06 | TO-15 2018 | 11/24/18 09:34 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Start 09:34 11/23/18 Probe #10313 | 5094 | 4.00" Hg |
| 23 | 8112702-07 | TO-15 2018 | 11/24/18 09:23 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Start 09:21 11/23/18 Probe #10314 | 22327 | 3.00" Hg |
| 24 | 8112702-02 | TO-15 2018 | 11/24/18 10:44 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Start 10:44 11/23/18 Probe #10310 | 5015 | 5.00" Hg |
| 25 | 8112702-05 | TO-15 2018 | 11/24/18 10:09 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Start 10:09 11/23/18 Probe #10294 | SAT131 | 3.50" Hg |
| 26 | 8112702-09 | TO-15 2018 | 11/24/18 09:25 | Invalid | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 09:25 11/23/18 Probe #10315 | 3225 | 4.50" Hg |
| 27 | 8112702-15 | TO-15 2018 | 11/26/18 10:21 | Reported | EtO Region 5 | Gower ES | Field Sample | Start 10:15 11/25/18 Probe #10293 | 5056 | 4.00" Hg |
| 28 | 8112702-14 | TO-15 2018 | 11/26/18 09:42 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:27 11/25/18 Probe #10311 | 5127 | 2.00" Hg |
| 29 | 8112702-16 | TO-15 2018 | 11/26/18 10:16 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:14 11/25/18 Probe #10076 | 5033 | 5.00" Hg |
| 30 | 8112702-10 | TO-15 2018 | 11/26/18 09:52 | Invalid | EtO Region 5 | Watertower VOID | Field Sample | Void per site operator Start 09:39 11/25/18 Probe #10312 | SAT004 | 18.50" Hg |
| 31 | 8112702-13 | TO-15 2018 | 11/26/18 09:34 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Start 09:15 11/25/18 Probe #10314 | 5133 | 3.00" Hg |
| 32 | 8112702-11 | TO-15 2018 | 11/26/18 09:27 | Invalid | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Start 09:04 11/25/18 Probe #10315 | SAT123 | 3.00" Hg |
| 33 | 8120701-10 | TO-15 2018 | 11/26/18 10:30 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:25 11/25/18 | 5034 | 4.50" Hg |
| 34 | 8112702-17 | TO-15 2018 | 11/26/18 10:03 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Start 09:50 11/25/18 Probe #10294 | SAT037 | 1.90" Hg |
| 35 | 8112702-12 | TO-15 2018 | 11/26/18 09:25 | Invalid | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 09:05 11/25/18 Probe #10313 | 5146 | 2.00" Hg |
| 36 | 8120321-06 | TO-15 2018 | 11/29/18 10:09 | Reported | EtO Region 5 | Gower ES | Field Sample | Start 10:45 11/28/18 Probe #10293 | SAT074 | 3.00" Hg |
| 37 | 8120321-08 | TO-15 2018 | 11/29/18 09:27 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:53 11/28/18 Probe #10311 | 5083 | 2.00" Hg |
| 38 | 8120321-03 | TO-15 2018 | 11/29/18 09:59 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:31 11/28/18 Probe #10076 | SAT054 | 4.00" Hg |
| 39 | 8120321-04 | TO-15 2018 | 11/29/18 09:37 | Reported | EtO Region 5 | Watertower | Field Sample | Start 10:05 11/28/18 Probe #10312 | SAT023 | 2.50" Hg |
| 40 | 8120321-09 | TO-15 2018 | 11/29/18 09:18 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Start 09:40 11/28/18 Probe #10313 | 18873 | 2.10" Hg |
| 41 | 8120321-01 | TO-15 2018 | 11/29/18 09:10 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Start 09:29 11/28/18 Probe #10314 | 5102 | 2.50" Hg |
| 42 | 8120321-07 | TO-15 2018 | 11/29/18 10:17 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Start 10:55 11/28/18 Probe #10310 | 19654 | 3.00" Hg |
| 43 | 8120321-05 | TO-15 2018 | 11/29/18 09:46 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Start 10:17 11/28/18 Probe #10294 | SAT173 | 3.00" Hg |
| 44 | 8120321-02 | TO-15 2018 | 11/29/18 09:09 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 09:29 11/28/18 Probe #10315 | SAT094 | 3.00" Hg |
| 45 | 8120701-07 | TO-15 2018 | 12/02/18 10:03 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:31 12/1/18 | 061 | 5.50" Hg |
| 46 | 8120701-01 | TO-15 2018 | 12/02/18 09:29 | Reported | EtO Region 5 | Grover MS | Field Sample | Probe #10311 Start 09:33 12/01/18 | A22244 | 3.50" Hg |
| 47 | 8120701-03 | TO-15 2018 | 12/02/18 09:55 | Reported | EtO Region 5 | Hindale South HS | Field Sample | Probe # 10076 Start 10:18 12/1/18 | 5135 | 7.00" Hg |
| 48 | 8120701-06 | TO-15 2018 | 12/02/18 09:37 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 09:45 12/1/18 | 406 | 3.50" Hg |
| 49 | 8120701-08 | TO-15 2018 | 12/02/18 09:17 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:21 12/1/18 | SAT079 | 3.50" Hg |
| 50 | 8120701-02 | TO-15 2018 | 12/02/18 09:12 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Probe # 10314 Start 09:11 12/1/18 | 161 | 3.50" Hg |
| 51 | 8120701-05 | TO-15 2018 | 12/02/18 10:10 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:43 12/1/18 | EPO92 | 5.00" Hg |
| 52 | 8120701-04 | TO-15 2018 | 12/02/18 09:46 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 09:57 12/1/18 | 082 | 4.50" Hg |
| 53 | 8120701-09 | TO-15 2018 | 12/02/18 09:18 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:21 12/1/18 | 101 | 5.50" Hg |
| 54 | 8121130-09 | TO-15 2018 | 12/07/18 10:50 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:26 12/06/18 | 775 | 1.8" Hg |
| 55 | 8121130-07 | TO-15 2018 | 12/07/18 09:51 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:42 12/06/18 Probe #10311 | 077 | 1.3" Hg |
| 56 | 8121130-08 | TO-15 2018 | 12/07/18 10:34 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:15 12/06/18 Probe #10076 | 5076 | 4.00" Hg |
| 57 | 8121130-05 | TO-15 2018 | 12/07/18 10:05 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 09:54 12/06/18 | SAT059 | 2.00" Hg |
| 58 | 8121130-04 | TO-15 2018 | 12/07/18 09:33 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Start 09:31 12/06/18 Probe #10313 | 171 | 1.5" Hg |
| 59 | 8121130-01 | TO-15 2018 | 12/07/18 09:15 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Start 09:20 12/06/18 Probe #10314 | 183 | 2.00" Hg |
| 60 | 8121130-06 | TO-15 2018 | 12/07/18 11:04 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:36 12/06/18 | A21119 | 0.9" Hg |
| 61 | 8121130-03 | TO-15 2018 | 12/07/18 10:21 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:05 12/06/18 | 707 | 1.4" Hg |

| | A | B | C | D | E | F | G | H | I | J |
|---|---|---|---|---|---|---|---|---|---|---|
| 62 | 8121130-02 | TO-15 2018 | 12/07/18 09:19 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 09:21 12/06/18 Probe #10315 | 711 | 2.00" Hg |
| 63 | 8121130-10 | TO-15 2018 | 12/06/18 00:00 | Reported | EtO Region 5 | Trip Blank | Trip Blank | | A22228 | 30" Hg |
| 64 | 8121130-17 | TO-15 2018 | 12/08/18 10:26 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:53 12/07/18 | 0044 | 3.00" Hg |
| 65 | 8121130-15 | TO-15 2018 | 12/08/18 09:20 | Reported | EtO Region 5 | Gower MS | Field Sample | Start 09:54 12/07/18 Probe #10311 | 18870 | 2.1" Hg |
| 66 | 8121130-19 | TO-15 2018 | 12/08/18 10:09 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Start 10:38 12/07/18 Probe #10076 | 19283 | 4.50" Hg |
| 67 | 8121130-18 | TO-15 2018 | 12/08/18 09:39 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:09 12/07/18 | 5067 | 3.50" Hg |
| 68 | 8121130-12 | TO-15 2018 | 12/08/18 09:10 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:39 12/07/18 | 19284 | 2.00" Hg |
| 69 | 8121130-11 | TO-15 2018 | 12/08/18 09:03 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Start 09:23 12/07/18 Probe #10314 | A21012 | 1.00 psi |
| 70 | 8121130-16 | TO-15 2018 | 12/08/18 10:38 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:06 12/07/18 | 19661 | 3.00" Hg |
| 71 | 8121130-14 | TO-15 2018 | 12/08/18 09:55 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:23 12/07/18 | A21033 | 3.00" Hg |
| 72 | 8121130-13 | TO-15 2018 | 12/08/18 09:12 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:39 12/07/18 | SAT101 | 3.00" Hg |
| 73 | 8121220-01 | TO-15 2018 | 12/11/18 09:53 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:42 12/10/18 | A21022 | 4.5" Hg |
| 74 | 8121220-07 | TO-15 2018 | 12/11/18 09:05 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:55 12/10/18 | 050 | 3.0" Hg |
| 75 | 8121220-06 | TO-15 2018 | 12/11/18 09:46 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:30 12/10/18 | SAT020 | 5.00" Hg |
| 76 | 8121220-05 | TO-15 2018 | 12/11/18 09:14 | Reported | EtO Region 5 | Watertower | Field Sample | Probe #10312 Start 10:07 12/10/18 | SAT137 | 3.50" Hg |
| 77 | 8121220-02 | TO-15 2018 | 12/11/18 08:57 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:43 12/10/18 | 5029 | 3.5" Hg |
| 78 | 8121220-08 | TO-15 2018 | 12/11/18 08:52 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Probe #10314 Start 09:32 12/10/18 | 5043 | 4.00" Hg |
| 79 | 8121220-03 | TO-15 2018 | 12/11/18 09:58 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:53 12/10/18 | A21077 | 4.0" Hg |
| 80 | 8121220-04 | TO-15 2018 | 12/11/18 09:22 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:18 12/10/18 | 555 | 4.0" Hg |
| 81 | 8121220-09 | TO-15 2018 | 12/11/18 08:50 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Start 09:32 12/10/18 Probe #10315 | SAT084 | 4.00" Hg |
| 82 | 8121821-05 | TO-15 2018 | 12/14/18 09:50 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:54 12/13/18 | SAT057 | 2.50" Hg |
| 83 | 8121821-06 | TO-15 2018 | 12/14/18 10:23 | Reported | EtO Region 5 | Hindale South HS | Field Sample | Probe # 10076 Start 10:44 12/13/18 | SAT089 | 5.50" Hg |
| 84 | 8121821-02 | TO-15 2018 | 12/14/18 00:00 | Reported | EtO Region 5 | Trip Blank | Trip Blank | Willow Brook | SAT003 | 30" Hg |
| 85 | 8121821-07 | TO-15 2018 | 12/14/18 10:03 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:14 12/13/18 | A21042 | 3.50" Hg |
| 86 | 8121821-03 | TO-15 2018 | 12/14/18 09:37 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:43 12/13/18 | SAT002 | 2.50" Hg |
| 87 | 8121821-08 | TO-15 2018 | 12/14/18 09:29 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Probe # 10314 Start 09:22 12/13/18 | SAT092 | 2.50" Hg |
| 88 | 8121821-09 | TO-15 2018 | 12/14/18 10:45 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:10 12/13/18 | SAT114 | 4.0" Hg |
| 89 | 8121821-01 | TO-15 2018 | 12/14/18 10:12 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:30 12/13/18 | 5080 | 4.50" Hg |
| 90 | 8121821-04 | TO-15 2018 | 12/14/18 09:37 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:43 12/13/18 | SAT085 | 4.00" Hg |
| 91 | 8121821-11 | TO-15 2018 | 12/14/18 10:33 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:59 12/13/18 | A21102 | 4.5" Hg |
| 92 | 8121821-15 | TO-15 2018 | 12/17/18 10:04 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 11:04 12/16/18 | 5103 | 6.00" Hg |
| 93 | 8121821-19 | TO-15 2018 | 12/17/18 09:28 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 10:09 12/16/18 | 18818 | 4.00" Hg |
| 94 | 8121821-12 | TO-15 2018 | 12/17/18 09:57 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:52 12/16/18 | SAT069 | 6.00" Hg |
| 95 | 8121821-13 | TO-15 2018 | 12/17/18 09:33 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:20 12/16/18 | SAT161 | 4.00" Hg |
| 96 | 8121821-16 | TO-15 2018 | 12/17/18 09:22 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:59 12/16/18 | A21100 | 3.00" Hg |
| 97 | 8121821-10 | TO-15 2018 | 12/17/18 09:16 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C2 | Col 1 Probe # 10314 Start 09:46 12/16/18 | 19278 | 4.00" Hg |
| 98 | 8121821-18 | TO-15 2018 | 12/17/18 10:16 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:14 12/16/18 | 18819 | 4.50" Hg |
| 99 | 8121821-14 | TO-15 2018 | 12/17/18 09:39 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:32 12/16/18 | 19294 | 4.50" Hg |
| 100 | 8121821-17 | TO-15 2018 | 12/17/18 09:17 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:48 12/16/18 | SAT044 | 4.50" Hg |
| 101 | 8122101-04 | TO-15 2018 | 12/20/18 10:00 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:52 12/19/18 | 096 | 4.5" Hg |
| 102 | 8122101-06 | TO-15 2018 | 12/20/18 09:26 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:50 12/19/18 | A21006 | 3.50" Hg |
| 103 | 8122101-09 | TO-15 2018 | 12/20/18 09:52 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:35 12/19/18 | A21052 | 5.50" Hg |
| 104 | 8122101-02 | TO-15 2018 | 12/20/18 09:36 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:04 12/19/18 | SAT109 | 4.00" Hg |
| 105 | 8122101-07 | TO-15 2018 | 12/20/18 09:26 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:159 12/19/18 | 5021 | 3.50" Hg |
| 106 | 8122101-03 | TO-15 2018 | 12/20/18 09:07 | Reported | EtO Region 5 | WB Warehouse | Field Sample | Start 09:17 12/19/18 Probe #10314 | 5024 | 4" Hg |
| 107 | 8122101-08 | TO-15 2018 | 12/20/18 10:14 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:03 12/19/18 | 18810 | 4.0" Hg |
| 108 | 8122101-05 | TO-15 2018 | 12/20/18 09:44 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:18 12/19/18 | 19292 | 4.00" Hg |
| 109 | 8122101-01 | TO-15 2018 | 12/20/18 09:17 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe #10315 Start 09:29 12/19/18 | SAT153 | 3.50" Hg |
| 110 | 8122701-05 | TO-15 2018 | 12/23/18 10:18 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:31 12/22/18 | SAT171 | 5.00" Hg |
| 111 | 8122701-02 | TO-15 2018 | 12/23/18 09:11 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:31 12/22/18 | 5065 | 5.50" Hg |
| 112 | 8122701-01 | TO-15 2018 | 12/23/18 10:03 | Reported | EtO Region 5 | Hindale South HS | Field Sample | Probe # 10076 Start 10:17 12/22/18 | SAT123 | 6.00" Hg |
| 113 | 8122701-07 | TO-15 2018 | 12/23/18 09:17 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 09:45 12/22/18 | SAT143 | 3.00" Hg |
| 114 | 8122701-09 | TO-15 2018 | 12/23/18 09:27 | Reported | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:02 12/22/18 | 5146 | 4.00" Hg |
| 115 | 8122701-03 | TO-15 2018 | 12/23/18 08:58 | Reported | EtO Region 5 | WB Warehouse C1 | Collocated - C2 | Col 1 Probe # 10314 Start 08:57 12/22/18 | SAT135 | 3.50" Hg |
| 116 | 8122701-08 | TO-15 2018 | 12/23/18 10:27 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:46 12/22/18 | 18877 | 4.0" Hg |
| 117 | 8122701-06 | TO-15 2018 | 12/23/18 09:46 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 09:59 12/22/18 | 5015 | 5.50" Hg |
| 118 | 8122701-04 | TO-15 2018 | 12/23/18 08:57 | Reported | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10315 Start 08:55 12/16/18 | 5085 | 5.50" Hg |
| 119 | 8122801-01 | TO-15 2018 | 12/27/18 11:00 | Reported | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 11:13 12/26/18 | AZ41 | 4.00" Hg |
| 120 | 8122801-04 | TO-15 2018 | 12/27/18 10:16 | Reported | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 10:26 12/26/18 | 19298 | 3.50" Hg |
| 121 | 8122801-02 | TO-15 2018 | 12/27/18 10:52 | Reported | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:58 12/26/18 | SAT010 | 5.00" Hg |
| 122 | 8122801-03 | TO-15 2018 | 12/27/18 10:22 | Reported | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:26 12/26/18 | 19287 | 3.50" Hg |

| | A | B | C | D | E | F | G | H | I | J |
|---|---|---|---|---|---|---|---|---|---|---|
| 123 | 8122801-08 | TO-15 2018 | 12/27/18 10:07 | Reported | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 10:13 12/26/18 | 5060 | 1.6" Hg |
| 124 | 8122801-06 | TO-15 2018 | 12/27/18 10:02 | Invalid | EtO Region 5 | WB Warehouse | Field Sample | Void - Probe # 10314 Start 10:02 12/26/18 P Diff >3.0 Void? | 19651 | 3.00" Hg |
| 125 | 8122801-05 | TO-15 2018 | 12/27/18 11:07 | Reported | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:24 12/26/18 | A21037 | 3.50" Hg |
| 126 | 8122801-07 | TO-15 2018 | 12/27/18 10:27 | Reported | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:47 12/26/18 | 2243 | 4.50" Hg |
| 127 | 8122801-09 | TO-15 2018 | 12/27/18 10:07 | Reported | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe #10315 Start 10:13 12/26/18 | SAT063 | 4.00" Hg |
| 128 | 8123125-03 | TO-15 2018 | 12/29/18 10:45 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:53 12/28/18 | AZ52 | 4.00" Hg |
| 129 | 8123125-04 | TO-15 2018 | 12/29/18 09:47 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 10:03 12/28/18 | AZ46 | 3.00" Hg |
| 130 | 8123125-01 | TO-15 2018 | 12/29/18 10:28 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:39 12/28/18 | AZ48 | 4.50" Hg |
| 131 | 8123125-09 | TO-15 2018 | 12/29/18 00:00 | Received | EtO Region 5 | Water Tower VOID | Field Sample | Probe # 10312 Start 10:14 12/28/18 | 19646 | 0.0" Hg |
| 132 | 8123125-08 | TO-15 2018 | 12/29/18 09:55 | Received | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:51 12/28/18 | AZ37 | 2.30" Hg |
| 133 | 8123125-05 | TO-15 2018 | 12/29/18 09:40 | Received | EtO Region 5 | WB Warehouse C1 | Collocated - C2 | Col 1 Probe # 10315 Start 09:40 12/28/18 | SAT073 | 3.00" Hg |
| 134 | 8123125-07 | TO-15 2018 | 12/29/18 10:51 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:05 12/28/18 | 18833 | 3.00" Hg |
| 135 | 8123125-02 | TO-15 2018 | 12/29/18 10:17 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:25 12/28/18 | 18834 | 3.00" Hg |
| 136 | 8123125-06 | TO-15 2018 | 12/29/18 09:37 | Received | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10314 Start 09:40 12/28/18 | 19291 | 2.50" Hg |
| 137 | 9010401-06 | TO-15 2019 | 01/03/19 10:56 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:42 1/02/18 | 5059 | 4.00" Hg |
| 138 | 9010401-05 | TO-15 2019 | 01/03/19 09:46 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 9:53 1/02/18 | A21078 | 2.50" Hg |
| 139 | 9010401-08 | TO-15 2019 | 01/03/19 10:34 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:30 1/02/18 | SAT138 | 4.00" Hg |
| 140 | 9010401-03 | TO-15 2019 | 01/03/19 10:02 | Received | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:05 1/02/18 | A21097 | 2.00" Hg |
| 141 | 9010401-07 | TO-15 2019 | 01/03/19 09:27 | Received | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:40 1/02/18 | 5072 | 3.00" Hg |
| 142 | 9010401-09 | TO-15 2019 | 01/03/19 09:17 | Received | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Probe # 10314 Start 09:29 1/02/18 | SAT007 | 2.00" Hg |
| 143 | 9010401-01 | TO-15 2019 | 01/03/19 11:10 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:53 1/02/18 | A21107 | 2.50" Hg |
| 144 | 9010401-02 | TO-15 2019 | 01/03/19 10:20 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:18 1/02/18 | A21067 | 2.50" Hg |
| 145 | 9010401-04 | TO-15 2019 | 01/03/19 09:17 | Received | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:21 1/02/18 | SAT091 | 3.50" Hg |
| 146 | 9010716-03 | TO-15 2019 | 01/04/19 10:52 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 11:04 1/03/19 | 5014 | 4.00" Hg |
| 147 | 9010716-07 | TO-15 2019 | 01/04/19 09:46 | Received | EtO Region 5 | Grover MS | Field Sample | Probe #10311 Start 09:55 1/03/19 | 18873 | 3.50" Hg |
| 148 | 9010716-08 | TO-15 2019 | 01/04/19 10:31 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:41 1/03/19 | SAT173 | 5.50" Hg |
| 149 | 9010716-04 | TO-15 2019 | 01/04/19 09:57 | Received | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 10:12 1/03/19 | 19667 | 4.00" Hg |
| 150 | 9010716-05 | TO-15 2019 | 01/04/19 09:33 | Received | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:37 1/3/19 | SAT077 | 4.5" Hg |
| 151 | 9010716-02 | TO-15 2019 | 01/04/19 09:24 | Received | EtO Region 5 | WB Warehouse | Field Sample | Probe # 10314 Start 09:21 1/3/19 | 18889 | 3.50" Hg |
| 152 | 9010716-06 | TO-15 2019 | 01/04/19 11:00 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:19 1/03/18 | 19654 | 4.00" Hg |
| 153 | 9010716-01 | TO-15 2019 | 01/04/19 10:21 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:28 1/03/19 | 5133 | 5.50" Hg |
| 154 | 9010808-05 | TO-15 2019 | 01/04/19 09:32 | Received | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe # 10313 Start 09:39 1/3/19 | SAT088 | 2.00" Hg |
| 155 | 9010808-08 | TO-15 2019 | 01/07/19 10:08 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:30 1/06/19 | A22244 | 4.00" Hg |
| 156 | 9010808-03 | TO-15 2019 | 01/07/19 09:40 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 9:36 1/06/19 | 161 | 3.50" Hg |
| 157 | 9010808-02 | TO-15 2019 | 01/07/19 10:03 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:17 1/06/19 | 18869 | 5.00" Hg |
| 158 | 9010808-09 | TO-15 2019 | 01/07/19 09:46 | Received | EtO Region 5 | Water Tower | Field Sample | Probe # 10312 Start 9:49 1/06/19 | 406 | 2.50" Hg |
| 159 | 9010808-06 | TO-15 2019 | 01/07/19 09:33 | Received | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 09:25 1/6/19 | 082 | 2.00" Hg |
| 160 | 9010808-01 | TO-15 2019 | 01/07/19 09:29 | Received | EtO Region 5 | WB Warehouse | Field Sample | Start 09:06 1/6/19 Probe #10314 | SAT087 | 2.50" Hg |
| 161 | 9010808-10 | TO-15 2019 | 01/07/19 10:18 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:40 1/06/18 | 061 | 4.00" Hg |
| 162 | 9010808-04 | TO-15 2019 | 01/07/19 09:58 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:00 1/06/19 | 101 | 4.00" Hg |
| 163 | 9010808-07 | TO-15 2019 | 01/07/19 09:33 | Received | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe #10315 Start 9:25 1/6/19 | 5073 | 4.50" Hg |
| 164 | 9011101-05 | TO-15 2019 | 01/10/19 09:08 | Received | EtO Region 5 | Gower ES VOID | Field Sample | Probe # 10293 Start 10:28 1/9/19 Void - canister leaked before sampling | 3639A | 2.20" Hg |
| 165 | 9011101-06 | TO-15 2019 | 01/10/19 09:54 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:38 1/9/19 | AZ47 | 2.50" Hg |
| 166 | 9011101-03 | TO-15 2019 | 01/10/19 10:19 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:13 1/9/19 | SAT037 | 4.00" Hg |
| 167 | 9011101-01 | TO-15 2019 | 01/10/19 10:03 | Received | EtO Region 5 | Watertower | Field Sample | Probe #10312 Start 09:51 1/9/19 | 629 | 1.10" Hg |
| 168 | 9011101-09 | TO-15 2019 | 01/10/19 09:41 | Received | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:28 1/09/19 | 19277 | 1.40" Hg |
| 169 | 9011101-07 | TO-15 2019 | 01/10/19 09:26 | Received | EtO Region 5 | WB Warehouse C1 VOID | Collocated - C1 | Col 1 Probe # 10314 Start 09:18 1/09/19 Void - Pressure loss >3 inches | 5101 | 2.00" Hg |
| 170 | 9011101-04 | TO-15 2019 | 01/10/19 10:29 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:38 1/9/19 | A21011 | 2.50" Hg |
| 171 | 9011101-02 | TO-15 2019 | 01/10/19 10:11 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:02 1/9/19 | 0053 | 2.50" Hg |
| 172 | 9011101-08 | TO-15 2019 | 01/10/19 09:26 | Received | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:19 1/09/19 | A21098 | 2.50" Hg |
| 173 | 9011527-03 | TO-15 2019 | 01/13/19 10:22 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:29 1/12/19 | A21054 | 4.00" Hg |
| 174 | 9011527-04 | TO-15 2019 | 01/13/19 09:38 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 09:39 1/12/19 | 19666 | 3.00" Hg |
| 175 | 9011527-06 | TO-15 2019 | 01/13/19 10:14 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:17 1/12/19 | SAT170 | 3.00" Hg |
| 176 | 9011527-08 | TO-15 2019 | 01/13/19 09:46 | Received | EtO Region 5 | Watertower | Field Sample | Probe #10312 Start 09:52 1/12/19 | SAT012 | 3.00" Hg |
| 177 | 9011527-01 | TO-15 2019 | 01/13/19 09:29 | Received | EtO Region 5 | WB Village Hall C1 | Collocated - C1 | Col 1 Probe # 10313 Start 9:27 1/12/19 | 5142 | 2.50" Hg |
| 178 | 9011527-07 | TO-15 2019 | 01/13/19 09:23 | Received | EtO Region 5 | WB Warehouse | Field Sample | Probe #10314 Start 09:11 1/12/19 | 19665 | 2.50" Hg |
| 179 | 9011527-09 | TO-15 2019 | 01/13/19 10:31 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 10:40 1/12/19 | SAT145 | 3.50" Hg |
| 180 | 9011527-05 | TO-15 2019 | 01/13/19 09:55 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:03 1/12/19 | 19645 | 3.50" Hg |
| 181 | 9011527-02 | TO-15 2019 | 01/13/19 09:29 | Received | EtO Region 5 | WB Village Hall C2 | Collocated - C2 | Col 2 Probe # 10315 Start 9:27 1/12/19 | SAT061 | 3.50" Hg |
| 182 | 9011701-07 | TO-15 2019 | 01/16/19 10:36 | Received | EtO Region 5 | Gower ES | Field Sample | Probe # 10293 Start 10:49 1/15/19 | 077 | 4.00" Hg |
| 183 | 9011701-05 | TO-15 2019 | 01/16/19 09:58 | Received | EtO Region 5 | Gower MS | Field Sample | Probe #10311 Start 10:06 1/15/19 | 555 | 3.50" Hg |

| | A | B | C | D | E | F | G | H | I | J |
|---|---|---|---|---|---|---|---|---|---|---|
| 184 | 9011701-01 | TO-15 2019 | 01/16/19 10:27 | Received | EtO Region 5 | Hinsdale South HS | Field Sample | Probe #10076 Start 10:39 1/15/19 | A21119 | 4.00" Hg |
| 185 | 9011701-02 | TO-15 2019 | 01/16/19 10:07 | Received | EtO Region 5 | Watertower | Field Sample | Probe #10312 Start 10:17 1/15/19 | 171 | 3.50" Hg |
| 186 | 9011701-04 | TO-15 2019 | 01/16/19 09:49 | Received | EtO Region 5 | WB Village Hall | Field Sample | Probe #10313 Start 09:56 1/15/19 | 711 | 1.90" Hg |
| 187 | 9011701-08 | TO-15 2019 | 01/16/19 09:41 | Received | EtO Region 5 | WB Warehouse C1 | Collocated - C1 | Col 1 Probe # 10314 Start 09:47 1/15/19 | A22228 | 5.00" Hg |
| 188 | 9011701-03 | TO-15 2019 | 01/16/19 10:45 | Received | EtO Region 5 | West Neighborhood | Field Sample | Probe # 10310 Start 11:00 1/15/19 | 707 | 2.50" Hg |
| 189 | 9011701-06 | TO-15 2019 | 01/16/19 10:18 | Received | EtO Region 5 | Willow Pond Park | Field Sample | Probe # 10294 Start 10:27 1/15/19 | 050 | 4.00" Hg |
| 190 | 9011701-09 | TO-15 2019 | 01/16/19 09:41 | Received | EtO Region 5 | WB Warehouse C2 | Collocated - C2 | Col 2 Probe # 10315 Start 09:47 1/15/19 | 183 | 4.00" Hg |