	A	B	C	D	E	F	G	H	I	J
1	**LabNumber**	**Analysis**	**Sampled**	**Status**	**Project**	**SampleName**	**SampleType**	**SampleComments**	**Canister ID**	**SampleInfo2**
2	8111508-01	TO-15 2018	11/14/18 10:22	Invalid	EtO Region 5	WB Village Hall C1	Collocated - C1	VOID Col 1 Start 10:22 11/13/18 Probe #10314 - >3" difference from field to lab	5079	3.50" Hg
3	8111508-03	TO-15 2018	11/14/18 10:00	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 10:00 11/13/18 Probe #10315	A21028	2.00" Hg
4	8111508-04	TO-15 2018	11/14/18 10:00	Reported	EtO Region 5	WB Trip Blank	Field Sample	Trip Blank	5037	29.50" Hg
5	8111508-02	TO-15 2018	11/14/18 10:23	Invalid	EtO Region 5	WB Village Hall C2	Collocated - C2	VOID Col 2 Start 10:23 11/13/18 Probe #10313 - >3" difference between field and lab	SAT057	1.00" Hg
6	8112012-01	TO-15 2018	11/17/18 10:07	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 10:24 11/16/18 Probe #10313	A21096	2.00" Hg
7	8112012-02	TO-15 2018	11/17/18 09:57	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 10:09 11/16/18 Probe #10314	SAT085	2.50" Hg
8	8112012-03	TO-15 2018	11/17/18 09:57	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 10:09 11/16/18 Probe #10315	SAT114	3.50" Hg
9	8112113-01	TO-15 2018	11/20/18 09:30	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Start 09:32 11/19/18 Probe #10315	A21102	2.00" Hg
10	8112113-03	TO-15 2018	11/20/18 09:21	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 09:20 11/19/18 Probe #10314	5077	3.50" Hg
11	8112113-04	TO-15 2018	11/20/18 10:36	Reported	EtO Region 5	Gower ES	Field Sample	Start 10:36 11/19/18 Probe #10293	SAT092	3.50" Hg
12	8112113-05	TO-15 2018	11/20/18 09:39	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:46 11/19/18 Probe #10311	18879	2.00" Hg
13	8112113-06	TO-15 2018	11/20/18 10:10	Reported	EtO Region 5	Willow Pond Park	Field Sample	Start 10:10 11/19/18 Probe #10294	SAT089	2.50" Hg
14	8112113-07	TO-15 2018	11/20/18 09:54	Reported	EtO Region 5	Watertower	Field Sample	Start 09:59 11/19/18 Probe #10312	SAT169	2.00" Hg
15	8112113-08	TO-15 2018	11/20/18 10:25	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:25 11/19/18 Probe #10076	A21051	4.00" Hg
16	8112113-09	TO-15 2018	11/20/18 10:45	Reported	EtO Region 5	West Neighborhood	Field Sample	Start 10:45 11/19/18 Probe #10310	SAT025	3.00" Hg
17	8112113-02	TO-15 2018	11/20/18 09:29	Reported	EtO Region 5	WB Village Hall C2	Collocated - C1	Col 2 Start 09:33 11/19/18 Probe #10315	SAT013	3.50" Hg
18	8112702-04	TO-15 2018	11/24/18 10:35	Reported	EtO Region 5	Gower ES	Field Sample	Start 10:35 11/23/18 Probe #10293	SAT097	4.50" Hg
19	8112702-03	TO-15 2018	11/24/18 09:41	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:36 11/23/18 Probe #10311	SAT135	3.00" Hg
20	8112702-08	TO-15 2018	11/24/18 10:23	Invalid	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:23 11/23/18 Probe #10076	SAT143	5.00" Hg
21	8112702-01	TO-15 2018	11/24/18 09:57	Reported	EtO Region 5	Watertower	Field Sample	Start 09:57 11/23/18 Probe #10312	18877	3.50" Hg
22	8112702-06	TO-15 2018	11/24/18 09:34	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 09:34 11/23/18 Probe #10313	5094	4.00" Hg
23	8112702-07	TO-15 2018	11/24/18 09:23	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:21 11/23/18 Probe #10314	22327	3.00" Hg
24	8112702-02	TO-15 2018	11/24/18 10:44	Reported	EtO Region 5	West Neighborhood	Field Sample	Start 10:44 11/23/18 Probe #10310	5015	5.00" Hg
25	8112702-05	TO-15 2018	11/24/18 10:09	Reported	EtO Region 5	Willow Pond Park	Field Sample	Start 10:09 11/23/18 Probe #10294	SAT131	3.50" Hg
26	8112702-09	TO-15 2018	11/24/18 09:25	Invalid	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:25 11/23/18 Probe #10315	3225	4.50" Hg
27	8112702-15	TO-15 2018	11/26/18 10:21	Reported	EtO Region 5	Gower ES	Field Sample	Start 10:15 11/25/18 Probe #10293	5056	4.00" Hg
28	8112702-14	TO-15 2018	11/26/18 09:42	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:27 11/25/18 Probe #10311	5127	2.00" Hg
29	8112702-16	TO-15 2018	11/26/18 10:16	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:14 11/25/18 Probe #10076	5033	5.00" Hg
30	8112702-10	TO-15 2018	11/26/18 09:52	Invalid	EtO Region 5	Watertower VOID	Field Sample	Void per site operator Start 09:39 11/25/18 Probe #10312	SAT004	18.50" Hg
31	8112702-13	TO-15 2018	11/26/18 09:34	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 09:15 11/25/18 Probe #10314	5133	3.00" Hg
32	8112702-11	TO-15 2018	11/26/18 09:27	Invalid	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:04 11/25/18 Probe #10315	SAT123	3.00" Hg
33	8120701-10	TO-15 2018	11/26/18 10:30	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:25 11/25/18	5034	4.50" Hg
34	8112702-17	TO-15 2018	11/26/18 10:03	Reported	EtO Region 5	Willow Pond Park	Field Sample	Start 09:50 11/25/18 Probe #10294	SAT037	1.90" Hg
35	8112702-12	TO-15 2018	11/26/18 09:25	Invalid	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:05 11/25/18 Probe #10313	5146	2.00" Hg
36	8120321-06	TO-15 2018	11/29/18 10:09	Reported	EtO Region 5	Gower ES	Field Sample	Start 10:45 11/28/18 Probe #10293	SAT074	3.00" Hg
37	8120321-08	TO-15 2018	11/29/18 09:27	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:53 11/28/18 Probe #10311	5083	2.00" Hg
38	8120321-03	TO-15 2018	11/29/18 09:59	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:31 11/28/18 Probe #10076	SAT054	4.00" Hg
39	8120321-04	TO-15 2018	11/29/18 09:37	Reported	EtO Region 5	Watertower	Field Sample	Start 10:05 11/28/18 Probe #10312	SAT023	2.50" Hg
40	8120321-09	TO-15 2018	11/29/18 09:18	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 09:40 11/28/18 Probe #10313	18873	2.10" Hg
41	8120321-01	TO-15 2018	11/29/18 09:10	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:29 11/28/18 Probe #10314	5102	2.50" Hg
42	8120321-07	TO-15 2018	11/29/18 10:17	Reported	EtO Region 5	West Neighborhood	Field Sample	Start 10:55 11/28/18 Probe #10310	19654	3.00" Hg
43	8120321-05	TO-15 2018	11/29/18 09:46	Reported	EtO Region 5	Willow Pond Park	Field Sample	Start 10:17 11/28/18 Probe #10294	SAT173	3.00" Hg
44	8120321-02	TO-15 2018	11/29/18 09:09	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:29 11/28/18 Probe #10315	SAT094	3.00" Hg
45	8120701-07	TO-15 2018	12/02/18 10:03	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:31 12/1/18	061	5.50" Hg
46	8120701-01	TO-15 2018	12/02/18 09:29	Reported	EtO Region 5	Grover MS	Field Sample	Probe #10311 Start 09:33 12/01/18	A22244	3.50" Hg
47	8120701-03	TO-15 2018	12/02/18 09:55	Reported	EtO Region 5	Hindale South HS	Field Sample	Probe # 10076 Start 10:18 12/1/18	5135	7.00" Hg
48	8120701-06	TO-15 2018	12/02/18 09:37	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 09:45 12/1/18	406	3.50" Hg
49	8120701-08	TO-15 2018	12/02/18 09:17	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:21 12/1/18	SAT079	3.50" Hg
50	8120701-02	TO-15 2018	12/02/18 09:12	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe # 10314 Start 09:11 12/1/18	161	3.50" Hg
51	8120701-05	TO-15 2018	12/02/18 10:10	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:43 12/1/18	EPO92	5.00" Hg
52	8120701-04	TO-15 2018	12/02/18 09:46	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 09:57 12/1/18	082	4.50" Hg
53	8120701-09	TO-15 2018	12/02/18 09:18	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 09:21 12/1/18	101	5.50" Hg
54	8121130-09	TO-15 2018	12/07/18 10:50	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:26 12/06/18	775	1.8" Hg
55	8121130-07	TO-15 2018	12/07/18 09:51	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:42 12/06/18 Probe #10311	077	1.3" Hg
56	8121130-08	TO-15 2018	12/07/18 10:34	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:15 12/06/18 Probe #10076	5076	4.00" Hg
57	8121130-05	TO-15 2018	12/07/18 10:05	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 09:54 12/06/18	SAT059	2.00" Hg
58	8121130-04	TO-15 2018	12/07/18 09:33	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 09:31 12/06/18 Probe #10313	171	1.5" Hg
59	8121130-01	TO-15 2018	12/07/18 09:15	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:20 12/06/18 Probe #10314	183	2.00" Hg
60	8121130-06	TO-15 2018	12/07/18 11:04	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:36 12/06/18	A21119	0.9" Hg
61	8121130-03	TO-15 2018	12/07/18 10:21	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:05 12/06/18	707	1.4" Hg

	A	B	C	D	E	F	G	H	I	J
62	8121130-02	TO-15 2018	12/07/18 09:19	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:21 12/06/18 Probe #10315	711	2.00" Hg
63	8121130-10	TO-15 2018	12/06/18 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank		A22228	30" Hg
64	8121130-17	TO-15 2018	12/08/18 10:26	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:53 12/07/18	0044	3.00" Hg
65	8121130-15	TO-15 2018	12/08/18 09:20	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:54 12/07/18 Probe #10311	18870	2.1" Hg
66	8121130-19	TO-15 2018	12/08/18 10:09	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:38 12/07/18 Probe #10076	19283	4.50" Hg
67	8121130-18	TO-15 2018	12/08/18 09:39	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:09 12/07/18	5067	3.50" Hg
68	8121130-12	TO-15 2018	12/08/18 09:10	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:39 12/07/18	19284	2.00" Hg
69	8121130-11	TO-15 2018	12/08/18 09:03	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 09:23 12/07/18 Probe #10314	A21012	1.00 psi
70	8121130-16	TO-15 2018	12/08/18 10:38	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:06 12/07/18	19661	3.00" Hg
71	8121130-14	TO-15 2018	12/08/18 09:55	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:23 12/07/18	A21033	3.00" Hg
72	8121130-13	TO-15 2018	12/08/18 09:12	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 09:39 12/07/18	SAT101	3.00" Hg
73	8121220-01	TO-15 2018	12/11/18 09:53	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:42 12/10/18	A21022	4.5" Hg
74	8121220-07	TO-15 2018	12/11/18 09:05	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:55 12/10/18	050	3.0" Hg
75	8121220-06	TO-15 2018	12/11/18 09:46	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:30 12/10/18	SAT020	5.00" Hg
76	8121220-05	TO-15 2018	12/11/18 09:14	Reported	EtO Region 5	Watertower	Field Sample	Probe #10312 Start 10:07 12/10/18	SAT137	3.50" Hg
77	8121220-02	TO-15 2018	12/11/18 08:57	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:43 12/10/18	5029	3.5" Hg
78	8121220-08	TO-15 2018	12/11/18 08:52	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 09:32 12/10/18	5043	4.00" Hg
79	8121220-03	TO-15 2018	12/11/18 09:58	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:53 12/10/18	A21077	4.0" Hg
80	8121220-04	TO-15 2018	12/11/18 09:22	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:18 12/10/18	555	4.0" Hg
81	8121220-09	TO-15 2018	12/11/18 08:50	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:32 12/10/18 Probe #10315	SAT084	4.00" Hg
82	8121821-05	TO-15 2018	12/14/18 09:50	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:54 12/13/18	SAT057	2.50" Hg
83	8121821-06	TO-15 2018	12/14/18 10:23	Reported	EtO Region 5	Hindale South HS	Field Sample	Probe # 10076 Start 10:44 12/13/18	SAT089	5.50" Hg
84	8121821-02	TO-15 2018	12/14/18 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank	Willow Brook	SAT003	30" Hg
85	8121821-07	TO-15 2018	12/14/18 10:03	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:14 12/13/18	A21042	3.50" Hg
86	8121821-03	TO-15 2018	12/14/18 09:37	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:43 12/13/18	SAT002	2.50" Hg
87	8121821-08	TO-15 2018	12/14/18 09:29	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe # 10314 Start 09:22 12/13/18	SAT092	2.50" Hg
88	8121821-09	TO-15 2018	12/14/18 10:45	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:10 12/13/18	SAT114	4.0" Hg
89	8121821-01	TO-15 2018	12/14/18 10:12	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:30 12/13/18	5080	4.50" Hg
90	8121821-04	TO-15 2018	12/14/18 09:37	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 09:43 12/13/18	SAT085	4.00" Hg
91	8121821-11	TO-15 2018	12/14/18 10:33	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:59 12/13/18	A21102	4.5" Hg
92	8121821-15	TO-15 2018	12/17/18 10:04	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:04 12/16/18	5103	6.00" Hg
93	8121821-19	TO-15 2018	12/17/18 09:28	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:09 12/16/18	18818	4.00" Hg
94	8121821-12	TO-15 2018	12/17/18 09:57	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:52 12/16/18	SAT069	6.00" Hg
95	8121821-13	TO-15 2018	12/17/18 09:33	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:20 12/16/18	SAT161	4.00" Hg
96	8121821-16	TO-15 2018	12/17/18 09:22	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:59 12/16/18	A21100	3.00" Hg
97	8121821-10	TO-15 2018	12/17/18 09:16	Reported	EtO Region 5	WB Warehouse C1	Collocated - C2	Col 1 Probe # 10314 Start 09:46 12/16/18	19278	4.00" Hg
98	8121821-18	TO-15 2018	12/17/18 10:16	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:14 12/16/18	18819	4.50" Hg
99	8121821-14	TO-15 2018	12/17/18 09:39	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:32 12/16/18	19294	4.50" Hg
100	8121821-17	TO-15 2018	12/17/18 09:17	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:48 12/16/18	SAT044	4.50" Hg
101	8122101-04	TO-15 2018	12/20/18 10:00	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:52 12/19/18	096	4.5" Hg
102	8122101-06	TO-15 2018	12/20/18 09:26	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:50 12/19/18	A21006	3.50" Hg
103	8122101-09	TO-15 2018	12/20/18 09:52	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:35 12/19/18	A21052	5.50" Hg
104	8122101-02	TO-15 2018	12/20/18 09:36	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:04 12/19/18	SAT109	4.00" Hg
105	8122101-07	TO-15 2018	12/20/18 09:26	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:159 12/19/18	5021	3.50" Hg
106	8122101-03	TO-15 2018	12/20/18 09:07	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 09:17 12/19/18 Probe #10314	5024	4" Hg
107	8122101-08	TO-15 2018	12/20/18 10:14	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:03 12/19/18	18810	4.0" Hg
108	8122101-05	TO-15 2018	12/20/18 09:44	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:18 12/19/18	19292	4.00" Hg
109	8122101-01	TO-15 2018	12/20/18 09:17	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe #10315 Start 09:29 12/19/18	SAT153	3.50" Hg
110	8122701-05	TO-15 2018	12/23/18 10:18	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:31 12/22/18	SAT171	5.00" Hg
111	8122701-02	TO-15 2018	12/23/18 09:11	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:31 12/22/18	5065	5.50" Hg
112	8122701-01	TO-15 2018	12/23/18 10:03	Reported	EtO Region 5	Hindale South HS	Field Sample	Probe # 10076 Start 10:17 12/22/18	SAT123	6.00" Hg
113	8122701-07	TO-15 2018	12/23/18 09:17	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 09:45 12/22/18	SAT143	3.00" Hg
114	8122701-09	TO-15 2018	12/23/18 09:27	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:02 12/22/18	5146	4.00" Hg
115	8122701-03	TO-15 2018	12/23/18 08:58	Reported	EtO Region 5	WB Warehouse C1	Collocated - C2	Col 1 Probe # 10314 Start 08:57 12/22/18	SAT135	3.50" Hg
116	8122701-08	TO-15 2018	12/23/18 10:27	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:46 12/22/18	18877	4.0" Hg
117	8122701-06	TO-15 2018	12/23/18 09:46	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 09:59 12/22/18	5015	5.50" Hg
118	8122701-04	TO-15 2018	12/23/18 08:57	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 08:55 12/16/18	5085	5.50" Hg
119	8122801-01	TO-15 2018	12/27/18 11:00	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:13 12/26/18	AZ41	4.00" Hg
120	8122801-04	TO-15 2018	12/27/18 10:16	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:26 12/26/18	19298	3.50" Hg
121	8122801-02	TO-15 2018	12/27/18 10:52	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:58 12/26/18	SAT010	5.00" Hg
122	8122801-03	TO-15 2018	12/27/18 10:22	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:26 12/26/18	19287	3.50" Hg

	A	B	C	D	E	F	G	H	I	J
123	8122801-08	TO-15 2018	12/27/18 10:07	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 10:13 12/26/18	5060	1.6" Hg
124	8122801-06	TO-15 2018	12/27/18 10:02	Invalid	EtO Region 5	WB Warehouse	Field Sample	Void - Probe # 10314 Start 10:02 12/26/18 P Diff >3.0 Void?	19651	3.00" Hg
125	8122801-05	TO-15 2018	12/27/18 11:07	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:24 12/26/18	A21037	3.50" Hg
126	8122801-07	TO-15 2018	12/27/18 10:27	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:47 12/26/18	2243	4.50" Hg
127	8122801-09	TO-15 2018	12/27/18 10:07	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe #10315 Start 10:13 12/26/18	SAT063	4.00" Hg
128	8123125-03	TO-15 2018	12/29/18 10:45	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:53 12/28/18	AZ52	4.00" Hg
129	8123125-04	TO-15 2018	12/29/18 09:47	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:03 12/28/18	AZ46	3.00" Hg
130	8123125-01	TO-15 2018	12/29/18 10:28	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:39 12/28/18	AZ48	4.50" Hg
131	8123125-09	TO-15 2018	12/29/18 00:00	Reported	EtO Region 5	Water Tower VOID	Field Sample	Probe # 10312 Start 10:14 12/28/18	19646	0.0" Hg
132	8123125-08	TO-15 2018	12/29/18 09:55	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:51 12/28/18	AZ37	2.30" Hg
133	8123125-05	TO-15 2018	12/29/18 09:40	Reported	EtO Region 5	WB Warehouse C1	Collocated - C2	Col 1 Probe # 10315 Start 09:40 12/28/18	SAT073	3.00" Hg
134	8123125-07	TO-15 2018	12/29/18 10:51	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:05 12/28/18	18833	3.00" Hg
135	8123125-02	TO-15 2018	12/29/18 10:17	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:25 12/28/18	18834	3.00" Hg
136	8123125-06	TO-15 2018	12/29/18 09:37	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10314 Start 09:40 12/28/18	19291	2.50" Hg
137	9010401-06	TO-15 2019	01/03/19 10:56	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:42 1/02/18	5059	4.00" Hg
138	9010401-05	TO-15 2019	01/03/19 09:46	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:53 1/02/18	A21078	2.50" Hg
139	9010401-08	TO-15 2019	01/03/19 10:34	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:30 1/02/18	SAT138	4.00" Hg
140	9010401-03	TO-15 2019	01/03/19 10:02	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:05 1/02/18	A21097	2.00" Hg
141	9010401-07	TO-15 2019	01/03/19 09:27	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:40 1/02/18	5072	3.00" Hg
142	9010401-09	TO-15 2019	01/03/19 09:17	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe # 10314 Start 09:29 1/02/18	SAT007	2.00" Hg
143	9010401-01	TO-15 2019	01/03/19 11:10	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:53 1/02/18	A21107	2.50" Hg
144	9010401-02	TO-15 2019	01/03/19 10:20	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:18 1/02/18	A21067	2.50" Hg
145	9010401-04	TO-15 2019	01/03/19 09:17	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:21 1/02/18	SAT091	3.50" Hg
146	9010716-03	TO-15 2019	01/04/19 10:52	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:04 1/03/19	5014	4.00" Hg
147	9010716-07	TO-15 2019	01/04/19 09:46	Reported	EtO Region 5	Grover MS	Field Sample	Probe #10311 Start 09:55 1/03/19	18873	3.50" Hg
148	9010716-08	TO-15 2019	01/04/19 10:31	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:41 1/03/19	SAT173	5.50" Hg
149	9010716-04	TO-15 2019	01/04/19 09:57	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:12 1/03/19	19667	4.00" Hg
150	9010716-05	TO-15 2019	01/04/19 09:33	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:37 1/3/19	SAT077	4.5" Hg
151	9010716-02	TO-15 2019	01/04/19 09:24	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe # 10314 Start 09:21 1/3/19	18889	3.50" Hg
152	9010716-06	TO-15 2019	01/04/19 11:00	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:19 1/03/18	19654	4.00" Hg
153	9010716-01	TO-15 2019	01/04/19 10:21	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:28 1/03/19	5133	5.50" Hg
154	9010808-05	TO-15 2019	01/04/19 09:32	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10313 Start 09:39 1/3/19	SAT088	2.00" Hg
155	9010808-08	TO-15 2019	01/07/19 10:08	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:30 1/06/19	A22244	4.00" Hg
156	9010808-03	TO-15 2019	01/07/19 09:40	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:36 1/06/19	161	3.50" Hg
157	9010808-02	TO-15 2019	01/07/19 10:03	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:17 1/06/19	18869	5.00" Hg
158	9010808-09	TO-15 2019	01/07/19 09:46	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 9:49 1/06/19	406	2.50" Hg
159	9010808-06	TO-15 2019	01/07/19 09:33	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 09:25 1/6/19	082	2.00" Hg
160	9010808-01	TO-15 2019	01/07/19 09:29	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 09:06 1/6/19 Probe #10314	SAT087	2.50" Hg
161	9010808-10	TO-15 2019	01/07/19 10:18	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:40 1/06/18	061	4.00" Hg
162	9010808-04	TO-15 2019	01/07/19 09:58	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:00 1/06/19	101	4.00" Hg
163	9010808-07	TO-15 2019	01/07/19 09:33	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe #10315 Start 9:25 1/6/19	5073	4.50" Hg
164	9011101-05	TO-15 2019	01/10/19 09:08	**Invalid**	EtO Region 5	Gower ES VOID	Field Sample	Probe # 10293 Start 10:28 1/9/19 Void - canister leaked before sampling	3639A	2.20" Hg
165	9011101-06	TO-15 2019	01/10/19 09:54	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:38 1/9/19	AZ47	2.50" Hg
166	9011101-03	TO-15 2019	01/10/19 10:19	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:13 1/9/19	SAT037	4.00" Hg
167	9011101-01	TO-15 2019	01/10/19 10:03	Reported	EtO Region 5	Watertower	Field Sample	Probe #10312 Start 09:51 1/9/19	629	1.10" Hg
168	9011101-09	TO-15 2019	01/10/19 09:41	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:28 1/09/19	19277	1.40" Hg
169	9011101-07	TO-15 2019	01/10/19 09:26	**Invalid**	EtO Region 5	WB Warehouse C1 VOID	Collocated - C1	Col 1 Probe # 10314 Start 09:18 1/09/19 Void - Pressure loss >3 inches	5101	2.00" Hg
170	9011101-04	TO-15 2019	01/10/19 10:29	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:38 1/9/19	A21011	2.50" Hg
171	9011101-02	TO-15 2019	01/10/19 10:11	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:02 1/9/19	0053	2.50" Hg
172	9011101-08	TO-15 2019	01/10/19 09:26	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:19 1/09/19	A21098	2.50" Hg
173	9011527-03	TO-15 2019	01/13/19 10:22	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:29 1/12/19	A21054	4.00" Hg
174	9011527-04	TO-15 2019	01/13/19 09:38	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 09:39 1/12/19	19666	3.00" Hg
175	9011527-06	TO-15 2019	01/13/19 10:14	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:17 1/12/19	SAT170	3.00" Hg
176	9011527-08	TO-15 2019	01/13/19 09:46	Reported	EtO Region 5	Watertower	Field Sample	Probe #10312 Start 09:52 1/12/19	SAT012	3.00" Hg
177	9011527-01	TO-15 2019	01/13/19 09:29	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 9:27 1/12/19	5142	2.50" Hg
178	9011527-07	TO-15 2019	01/13/19 09:23	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 09:11 1/12/19	19665	2.50" Hg
179	9011527-09	TO-15 2019	01/13/19 10:31	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:40 1/12/19	SAT145	3.50" Hg
180	9011527-05	TO-15 2019	01/13/19 09:55	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:03 1/12/19	19645	3.50" Hg
181	9011527-02	TO-15 2019	01/13/19 09:29	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:27 1/12/19	SAT061	3.50" Hg
182	9011701-07	TO-15 2019	01/16/19 10:36	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:49 1/15/19	077	4.00" Hg
183	9011701-05	TO-15 2019	01/16/19 09:58	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:06 1/15/19	555	3.50" Hg

	A	B	C	D	E	F	G	H	I	J
184	9011701-01	TO-15 2019	01/16/19 10:27	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:39 1/15/19	A21119	4.00" Hg
185	9011701-02	TO-15 2019	01/16/19 10:07	Reported	EtO Region 5	Watertower	Field Sample	Probe #10312 Start 10:17 1/15/19	171	3.50" Hg
186	9011701-04	TO-15 2019	01/16/19 09:49	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:56 1/15/19	711	1.90" Hg
187	9011701-08	TO-15 2019	01/16/19 09:41	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe # 10314 Start 09:47 1/15/19	A22228	5.00" Hg
188	9011701-03	TO-15 2019	01/16/19 10:45	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:00 1/15/19	707	2.50" Hg
189	9011701-06	TO-15 2019	01/16/19 10:18	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:27 1/15/19	050	4.00" Hg
190	9011701-09	TO-15 2019	01/16/19 09:41	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:47 1/15/19	183	4.00" Hg
191	9012221-02	TO-15 2019	01/18/19 10:13	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:30 1/17/19	A21034	5.00" Hg
192	9012221-06	TO-15 2019	01/18/19 09:44	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:43 1/17/19	SAT151	4.00" Hg
193	9012221-05	TO-15 2019	01/18/19 10:05	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:17 1/17/19	096	4.50" Hg
194	9012221-03	TO-15 2019	01/18/19 09:51	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 9:54 1/17/19	5026	4.50" Hg
195	9012221-08	TO-15 2019	01/18/19 09:37	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe # 10313 Start 9:31 1/17/19	775	2.30" Hg
196	9012221-01	TO-15 2019	01/18/19 09:30	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 09:21 1/17/19	SAT158	3.50" Hg
197	9012221-07	TO-15 2019	01/18/19 10:26	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:44 1/17/19	SAT029	4.00" Hg
198	9012221-04	TO-15 2019	01/18/19 09:58	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:06 1/17/19	A21109	4.50" Hg
199	9012221-09	TO-15 2019	01/18/19 09:37	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:31 1/17/19	5010	5.50" Hg
200	9012401-02	TO-15 2019	01/23/19 10:40	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:47 1/22/19	SAT159	3.00" Hg
201	9012401-01	TO-15 2019	01/23/19 10:21	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:56 1/22/19	5082	3.50" Hg
202	9012401-07	TO-15 2019	01/23/19 10:35	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:29 1/22/19	18826	3.50" Hg
203	9012401-08	TO-15 2019	01/23/19 10:26	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:09 1/22/19	5069	2.50" Hg
204	9012401-06	TO-15 2019	01/23/19 10:17	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:45 1/22/19	SAT119	1.00" Hg
205	9012401-04	TO-15 2019	01/23/19 09:43	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe # 10314 Start 09:36 1/22/19	A21010	2.00" Hg
206	9012401-09	TO-15 2019	01/23/19 10:44	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:59 1/22/19	A21026	2.50" Hg
207	9012401-03	TO-15 2019	01/23/19 10:31	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:18 1/22/19	19653	3.00" Hg
208	9012401-05	TO-15 2019	01/23/19 09:43	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:35 1/22/19	5118	4.00" Hg
209	9012401-10	TO-15 2019	01/23/19 00:00	Reported	EtO Region 5	WB Trip Blank	Field Sample	Trip Blank	A21074	29.00" Hg
210	9012816-01	TO-15 2019	01/25/19 09:59	Reported	EtO Region 5	EPA WB Warehouse	Field Sample	Probe # 10314 Start 09:20 1/24/19 Remeasured pressure	A21073	2.50" Hg
211	9012816-07	TO-15 2019	01/25/19 10:34	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:39 1/24/19	18874	2.50" Hg
212	9012816-02	TO-15 2019	01/25/19 10:08	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:50 1/24/19 Remeasured pressure	A21039	3.50" Hg
213	9012816-06	TO-15 2019	01/25/19 10:27	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:26 1/24/19	SAT047	3.00" Hg
214	9012816-08	TO-15 2019	01/25/19 10:13	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:00 1/24/19	5099	2.00" Hg
215	9012816-04	TO-15 2019	01/25/19 10:02	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 09:36 1/24/19 Remeasured pressure	5053	3.00" Hg
216	9012816-03	TO-15 2019	01/25/19 10:34	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:52 1/24/19	SAT024	2.50" Hg
217	9012816-09	TO-15 2019	01/25/19 10:18	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:11 1/24/19	A21028	2.50" Hg
218	9012816-05	TO-15 2019	01/25/19 10:02	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:36 1/24/19	A21099	3.30" Hg
219	9013003-01	TO-15 2019	01/28/19 10:29	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:43 1/27/19	5009	4.50" Hg
220	9013003-08	TO-15 2019	01/28/19 10:02	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:57 1/27/19	SAT111	2.00" Hg
221	9013003-04	TO-15 2019	01/28/19 10:23	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:25 1/27/19	19293	4.00" Hg
222	9013003-02	TO-15 2019	01/28/19 10:10	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:08 1/27/19	SAT023	2.00" Hg
223	9013003-05	TO-15 2019	01/28/19 09:55	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 09:46 1/27/19	5056	2.20" Hg
224	9013003-06	TO-15 2019	01/28/19 09:50	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe # 10314 Start 09:36 1/27/19	AZ43	1.70" Hg
225	9013003-09	TO-15 2019	01/28/19 10:35	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:52 1/27/19	SAT181	2.50" Hg
226	9013003-03	TO-15 2019	01/28/19 10:16	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:18 1/27/19	5081	4.00" Hg
227	9013003-07	TO-15 2019	01/28/19 09:50	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:36 1/27/19	SAT178	3.00" Hg
228	9012816-01	TO-15 2019	01/25/19 09:59	Reported	EtO Region 5	EPA WB Warehouse	Field Sample	Probe # 10314 Start 09:20 1/24/19 Remeasured pressure	A21073	2.50" Hg
229	9012816-07	TO-15 2019	01/25/19 10:34	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:39 1/24/19	18874	2.50" Hg
230	9012816-02	TO-15 2019	01/25/19 10:08	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:50 1/24/19 Remeasured pressure	A21039	3.50" Hg
231	9012816-06	TO-15 2019	01/25/19 10:27	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:26 1/24/19	SAT047	3.00" Hg
232	9012816-08	TO-15 2019	01/25/19 10:13	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:00 1/24/19	5099	2.00" Hg
233	9012816-04	TO-15 2019	01/25/19 10:02	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 09:36 1/24/19 Remeasured pressure	5053	3.00" Hg
234	9012816-03	TO-15 2019	01/25/19 10:34	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:52 1/24/19	SAT024	2.50" Hg
235	9012816-09	TO-15 2019	01/25/19 10:18	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:11 1/24/19	A21028	2.50" Hg
236	9012816-05	TO-15 2019	01/25/19 10:02	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:36 1/24/19	A21099	3.30" Hg
237	9020508-01	TO-15 2019	02/02/19 11:38	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:39 2/1/19	SAT021	3.00" Hg
238	9020508-08	TO-15 2019	02/02/19 10:16	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:31 2/1/19	19662	3.00" Hg
239	9020508-09	TO-15 2019	02/02/19 11:17	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 11:26 2/1/19	5046	5.00" Hg
240	9020508-05	TO-15 2019	02/02/19 10:41	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:48 2/1/19	5076	3.50" Hg
241	9020508-03	TO-15 2019	02/02/19 09:36	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 10:16 2/1/19	SAT057	2.00" Hg
242	9020508-02	TO-15 2019	02/02/19 09:44	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 10:03 2/1/19	A21055	2.50" Hg
243	9020508-06	TO-15 2019	02/02/19 11:54	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:49 2/1/19	5079	3.50" Hg
244	9020508-04	TO-15 2019	02/02/19 10:58	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:02 2/1/19	5080	4.50" Hg

	A	B	C	D	E	F	G	H	I	J
245	9020508-19	TO-15 2019	02/02/19 09:36	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 10:16 2/1/19	SAT086	4.50" Hg
246	9020508-07	TO-15 2019	02/02/19 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank	Willow Brook	18831	30" Hg
247	9020508-16	TO-15 2019	02/03/19 11:28	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:46 2/2/19	A21065	4.50" Hg
248	9020508-17	TO-15 2019	02/03/19 10:21	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:35 2/2/19	5115	5.50" Hg
249	9020508-18	TO-15 2019	02/03/19 11:08	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 11:27 2/2/19	18878	5.50" Hg
250	9020508-10	TO-15 2019	02/03/19 10:28	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:50 2/2/19	SAT026	4.00" Hg
251	9020508-11	TO-15 2019	02/03/19 10:13	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 10:07 2/2/19	5130	3.50" Hg
252	9020508-13	TO-15 2019	02/03/19 10:05	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe # 10314 Start 09:56 2/2/19	5136	4.00" Hg
253	9020508-12	TO-15 2019	02/03/19 11:46	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 12:12 2/2/19	2240	4.50" Hg
254	9020508-15	TO-15 2019	02/03/19 10:51	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:10 2/2/19	A21072	5.00" Hg
255	9020508-14	TO-15 2019	02/03/19 10:05	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 09:56 2/2/19	5044	6.00" Hg
256	9021313-08	TO-15 2019	02/09/19 10:40	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:49 2/8/19 received without brass cap	5007	3.00" Hg
257	9021313-01	TO-15 2019	02/09/19 09:51	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:02 2/8/19	SAT172	2.00" Hg
258	9021313-05	TO-15 2019	02/09/19 10:30	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:38 2/8/19	19340	3.50" Hg
259	9021313-03	TO-15 2019	02/09/19 10:05	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:12 2/8/19	19290	1.90" Hg
260	9021313-09	TO-15 2019	02/09/19 09:30	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 9:51 2/8/19	19641	0.90" Hg
261	9021313-06	TO-15 2019	02/09/19 09:20	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 9:40 2/8/19	2527	1.50" Hg
262	9021313-04	TO-15 2019	02/09/19 10:45	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:50 2/8/19	18880	2.20" Hg
263	9021313-02	TO-15 2019	02/09/19 10:15	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:25 2/8/19	5100	4.00" Hg
264	9021313-07	TO-15 2019	02/09/19 09:20	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe # 10315 Start 9:40 2/8/19	SAT164	3.00" Hg
265	9021401-01	TO-15 2019	02/12/19 10:01	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:39 2/11/19	077	4.50" Hg
266	9021401-02	TO-15 2019	02/12/19 09:32	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:52 2/11/19	707	2.50" Hg
267	9021401-08	TO-15 2019	02/12/19 09:54	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:28 2/11/19	A21119	4.00" Hg
268	9021401-06	TO-15 2019	02/12/19 09:40	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:04 2/11/19	061	3.50" Hg
269	9021401-03	TO-15 2019	02/12/19 09:24	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 9:29 2/11/19	3639A	4.50" Hg
270	9021401-09	TO-15 2019	02/12/19 09:17	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 9:18 2/11/19	629	2.40" Hg
271	9021401-07	TO-15 2019	02/12/19 10:06	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:48 2/11/19	171	4.50" Hg
272	9021401-05	TO-15 2019	02/12/19 09:48	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:16 2/11/19	711	4.00" Hg
273	9021401-04	TO-15 2019	02/12/19 09:24	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:29 2/11/19 3 inch Hg difference from field once warm	A22228	2.00" Hg
274	9022025-02	TO-15 2019	02/15/19 11:10	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 11:42 2/14/19	EP092	5.00" Hg
275	9022025-06	TO-15 2019	02/15/19 10:49	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:49 2/14/19	5135	5.50" Hg
276	9022025-04	TO-15 2019	02/15/19 11:05	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 11:30 2/14/19	SAT176	6.00" Hg
277	9022025-05	TO-15 2019	02/15/19 10:54	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 11:01 2/14/19	183	3.50" Hg
278	9022025-01	TO-15 2019	02/15/19 10:44	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 10:38 2/14/19	5091	4.00" Hg
279	9022025-07	TO-15 2019	02/15/19 10:39	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10315 Start 10:27 2/14/19	SAT151	4.50" Hg
280	9022025-09	TO-15 2019	02/15/19 11:14	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:53 2/14/19	19280	4.00" Hg
281	9022025-03	TO-15 2019	02/15/19 10:59	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:13 2/14/19	050	5.50" Hg
282	9022025-08	TO-15 2019	02/15/19 10:39	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10077 Start 10:27 2/14/19	SAT147	5.50" Hg
283	9022202-07	TO-15 2019	02/20/19 10:53	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:48 2/19/19	A21022	3.50" Hg
284	9022202-01	TO-15 2019	02/20/19 09:55	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:05 2/19/19	5034	4.50" Hg
285	9022202-06	TO-15 2019	02/20/19 10:40	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:37 2/19/19	SAT047	5.50" Hg
286	9022202-05	TO-15 2019	02/20/19 10:10	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:16 2/19/19	SAT161	3.00" Hg
287	9022202-10	TO-15 2019	02/20/19 00:00	Reported	EtO Region 5	WB Trip Blank	Field Sample	Trip Blank	SAT163	30.00" Hg
288	9022202-02	TO-15 2019	02/20/19 09:23	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 9:53 2/19/19	5114	3.50" Hg
289	9022202-08	TO-15 2019	02/20/19 09:37	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 9:35 2/19/19	5063	3.50" Hg
290	9022202-09	TO-15 2019	02/20/19 11:06	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:57 2/19/19	5050	4.00" Hg
291	9022202-04	TO-15 2019	02/20/19 10:26	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:27 2/19/19	555	4.50" Hg
292	9022202-03	TO-15 2019	02/20/19 09:23	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:44 2/19/19	A22329	5.00" Hg
293	9022202-12	TO-15 2019	02/21/19 10:26	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10293 Start 10:02 2/20/19	SAT166	4.50" Hg
294	9022202-11	TO-15 2019	02/21/19 10:09	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:04 2/20/19	A21039	4.00" Hg
295	9022202-13	TO-15 2019	02/21/19 10:21	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 10:46 2/20/19	A21044	5.50" Hg
296	9022202-16	TO-15 2019	02/21/19 11:35	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 11:45 2/20/19	5015	4.50" Hg
297	9022202-17	TO-15 2019	02/21/19 10:03	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 9:33 2/20/19	5051	2.50" Hg
298	9022202-18	TO-15 2019	02/21/19 09:58	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10315 Start 9:50 2/20/19	5017	5.00" Hg
299	9022202-14	TO-15 2019	02/21/19 10:30	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:14 2/20/19	18873	4.00" Hg
300	9022202-15	TO-15 2019	02/21/19 10:15	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:33 2/20/19	SAT096	5.00" Hg
301	9022202-19	TO-15 2019	02/21/19 09:57	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10314 Start 9:48 2/20/19	SAT007	3.00" Hg
302	9022616-03	TO-15 2019	02/22/19 11:21	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 11:31 2/21/19	A21106	2.00" Hg
303	9022616-01	TO-15 2019	02/22/19 11:15	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 11:21 2/21/19	SAT178	3.00" Hg
304	9022616-02	TO-15 2019	02/22/19 11:15	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 11:20 2/21/19	5009	6.00" Hg
305	9022616-04	TO-15 2019	02/23/19 11:26	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 12:12 2/22/19	5114	3.50" Hg

	A	B	C	D	E	F	G	H	I	J
306	9022616-05	TO-15 2019	02/23/19 11:26	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 12:12 2/22/19	A22329	5.00" Hg
307	9022616-06	TO-15 2019	02/23/19 11:36	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10313 Start 11:54 2/22/19	096	3.00" Hg
308	9022616-15	TO-15 2019	02/24/19 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank	Trip Blank	18874	30" Hg
309			2/24/2019 0:00	Reported		Gower ES	Field Sample	VOID - CAN FAILED LEAK CHECK		
310	9022616-12	TO-15 2019	02/24/19 10:31	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:19 2/23/19	SAT114	4.50" Hg
311	9022616-13	TO-15 2019	02/24/19 10:45	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10076 Start 11:00 2/23/19	SAT049	6.00" Hg
312	9022616-08	TO-15 2019	02/24/19 10:35	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:31 2/23/19	5043	3.50" Hg
313	9022616-14	TO-15 2019	02/24/19 11:21	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10314 Start 11:36 2/23/19	18872	4.00" Hg
314	9022616-09	TO-15 2019	02/24/19 11:53	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10313 Start 11:49 2/23/19	5067	4.00" Hg
315	9022616-07	TO-15 2019	02/24/19 11:05	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:23 2/23/19	SAT111	3.00" Hg
316	9022616-11	TO-15 2019	02/24/19 10:40	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:47 2/23/19	A21006	5.00" Hg
317	9022616-10	TO-15 2019	02/24/19 11:53	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 11:52 2/23/19	775	4.50" Hg
318	9030101-05	TO-15 2019	02/27/19 10:53	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 11:53 2/26/19	19657	6.00" Hg
319	9030101-06	TO-15 2019	02/27/19 10:01	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:30 2/26/19	SAT084	4.00" Hg
320	9030101-09	TO-15 2019	02/27/19 10:26	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe #10294 Start 11:13 2/26/19	5089	5.50" Hg
321	9030101-04	TO-15 2019	02/27/19 10:06	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:41 2/26/19	SAT120	3.00" Hg
322	9030101-07	TO-15 2019	02/27/19 09:16	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 10:18 2/26/19	5074	4.00" Hg
323	9030101-03	TO-15 2019	02/27/19 09:12	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 10:03 2/26/19	SAT046	3.50" Hg
324	9030101-01	TO-15 2019	02/27/19 10:34	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:32 2/26/19	5058	4.50" Hg
325	9030101-02	TO-15 2019	02/27/19 10:11	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10076 Start 10:52 2/26/19	A21042	5.00" Hg
326	9030101-08	TO-15 2019	02/27/19 09:16	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 10:12 2/26/19	SAT067	5.50" Hg
327	9030101-10	TO-15 2019	02/26/19 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank	Trip Blank	A21033	30" Hg
328	9030524-06	TO-15 2019	03/02/19 10:04	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 10:38 3/1/19	SAT171	6.50" Hg
329	9030524-05	TO-15 2019	03/02/19 09:46	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:51 3/1/19	SAT106	4.00" Hg
330	9030524-01	TO-15 2019	03/02/19 09:59	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 10:27 3/1/19	5143	6.50" Hg
331	9030524-09	TO-15 2019	03/02/19 09:50	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:01 3/1/19	SAT059	3.00" Hg
332	9030524-04	TO-15 2019	03/02/19 09:42	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 9:40 3/1/19	5005	3.00" Hg
333	9030524-07	TO-15 2019	03/02/19 09:38	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 9:31 3/1/19	SAT117	3.00" Hg
334	9030524-03	TO-15 2019	03/02/19 10:07	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:47 3/1/19	18884	4.00" Hg
335	9030524-02	TO-15 2019	03/02/19 09:55	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:11 3/1/19	SAT129	5.00" Hg
336	9030524-08	TO-15 2019	03/02/19 09:38	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 9:31 3/1/19	5076	5.50" Hg
337	9030618-08	TO-15 2019	03/05/19 11:34	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 12:13 3/4/19	A21051	6.50" Hg
338	9030618-06	TO-15 2019	03/05/19 10:35	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:52 3/4/19	A21055	3.50" Hg
339	9030618-09	TO-15 2019	03/05/19 11:27	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 11:58 3/4/19	ER025	4.50" Hg
340	9030618-03	TO-15 2019	03/05/19 10:44	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 11:18 3/4/19	SAT026	2.00" Hg
341	9030618-04	TO-15 2019	03/05/19 10:24	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 10:37 3/4/19	A22228	2.30" Hg
342	9030618-07	TO-15 2019	03/05/19 10:17	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 10:21 3/4/19	707	1.60" Hg
343	9030618-02	TO-15 2019	03/05/19 11:41	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 12:27 3/4/19	5046	4.00" Hg
344	9030618-01	TO-15 2019	03/05/19 10:51	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:33 3/4/19	A21013	4.50" Hg
345	9030618-05	TO-15 2019	03/05/19 10:24	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 10:37 3/4/19	3639A	4.50" Hg
346	9031131-01	TO-15 2019	03/08/19 00:00	Reported	EtO Region 5	Trip Blank	Trip Blank	Trip Blank	SAT141	30" Hg
347	9031131-07	TO-15 2019	03/08/19 10:45	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 11:35 3/7/19	18834	7.50" Hg
348	9031131-09	TO-15 2019	03/08/19 10:16	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:37 3/7/19	161	4.50" Hg
349	9031131-08	TO-15 2019	03/08/19 10:38	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 11:23 3/7/19	101	5.00" Hg
350	9031131-05	TO-15 2019	03/08/19 10:21	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:49 3/7/19	A21094	3.00" Hg
351	9031131-06	TO-15 2019	03/08/19 10:09	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 10:24 3/7/19	A22244	2.00" Hg
352	9031131-03	TO-15 2019	03/08/19 10:04	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 10:13 3/7/19	SAT086	2.50" Hg
353	9031131-10	TO-15 2019	03/08/19 10:51	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:47 3/7/19	A21001	4.00" Hg
354	9031131-02	TO-15 2019	03/08/19 10:27	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:02 3/7/19	5103	5.50" Hg
355	9031131-04	TO-15 2019	03/08/19 10:04	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 10:14 3/7/19	077	5.00" Hg
356	9031220-05	TO-15 2019	03/11/19 10:05	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 10:37 3/10/19	061	7.00" Hg
357	9031220-09	TO-15 2019	03/11/19 09:22	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:51 3/10/19	A21119	3.50" Hg
358	9031220-01	TO-15 2019	03/11/19 09:56	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 10:25 3/10/19	629	4.00" Hg
359	9031220-04	TO-15 2019	03/11/19 09:28	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:02 3/10/19	711	7.50" Hg
360	9031220-02	TO-15 2019	03/11/19 09:12	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 9:40 3/10/19 Pressure Dif >3 inches	5019	3.50" Hg
361	9031220-08	TO-15 2019	03/11/19 09:07	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 9:31 3/10/19	171	3.50" Hg
362	9031220-06	TO-15 2019	03/11/19 10:11	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:46 3/10/19	SAT029	4.00" Hg
363	9031220-07	TO-15 2019	03/11/19 09:36	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:14 3/10/19	SAT088	4.50" Hg
364	9031220-03	TO-15 2019	03/11/19 09:12	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:40 3/10/19	A22304	5.00" Hg
365	9031501-02	TO-15 2019	03/14/19 10:55	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 11:11 3/13/19	A21067	8.50" Hg
366	9031501-03	TO-15 2019	03/14/19 10:29	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:26 3/13/19	SAT173	5.50" Hg

	A	B	C	D	E	F	G	H	I	J
367	9031501-07	TO-15 2019	03/14/19 10:49	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 11:00 3/13/19	19647	6.50" Hg
368	9031501-06	TO-15 2019	03/14/19 10:34	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:38 3/13/19	SAT077	5.00" Hg
369	9031501-08	TO-15 2019	03/14/19 10:24	Reported	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 10:14 3/13/19	5013	4.50" Hg
370	9031501-04	TO-15 2019	03/14/19 10:20	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 10:06 3/13/19	18869	4.00" Hg
371	9031501-01	TO-15 2019	03/14/19 10:59	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 11:22 3/13/19	SAT150	5.00" Hg
372	9031501-09	TO-15 2019	03/14/19 10:45	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:48 3/13/19	19654	6.00" Hg
373	9031501-05	TO-15 2019	03/14/19 10:20	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 10:06 3/13/19	SAT107	6.50" Hg
374	9032522-04	TO-15 2019	03/17/19 09:52	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 10:00 3/16/19	50	7.00" Hg
375	9032522-05	TO-15 2019	03/17/19 09:28	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 9:19 3/16/19	5029	4.50" Hg
376	9032522-02	TO-15 2019	03/17/19 09:44	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 9:49 3/16/19	A210369	5.00" Hg
377	9032522-09	TO-15 2019	03/17/19 09:32	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 9:29 3/16/19	775	2.00" Hg
378	9032522-07	TO-15 2019	03/17/19 09:22	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 9:09 3/16/19	5051	2.50" Hg
379	9032522-03	TO-15 2019	03/17/19 09:19	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 9:00 3/16/19	AZ41	2.50" Hg
380	9032522-06	TO-15 2019	03/17/19 09:55	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:10 3/16/19	555	3.00" Hg
381	9032522-01	TO-15 2019	03/17/19 09:37	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 9:39 3/16/19	5050	5.50" Hg
382	9032522-08	TO-15 2019	03/17/19 09:23	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 9:09 3/16/19	18873	4.50" Hg
383	9032106-03	TO-15 2019	03/20/19 00:00	Received	EtO Region 5	Trip Blank	Trip Blank	Trip Blank	SAT120	29.50" Hg
384	9032106-04	TO-15 2019	03/20/19 10:51	Reported	EtO Region 5	Gower ES	Field Sample	Probe # 10077 Start 11:50 3/19/19	A21084	8.00" Hg
385	9032106-10	TO-15 2019	03/20/19 10:05	Reported	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:29 3/19/19	18872	4.50" Hg
386	9032106-06	TO-15 2019	03/20/19 10:38	Reported	EtO Region 5	Hindale South HS	Field Sample	Probe # 10076 Start 11:34 3/19/19	SAT100	6.00" Hg
387	9032106-02	TO-15 2019	03/20/19 10:12	Reported	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:50 3/19/19	18877	4.50" Hg
388	9032106-08	TO-15 2019	03/20/19 09:58	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Probe #10313 Start 10:05 3/19/19	5043	4.50" Hg
389	9032106-07	TO-15 2019	03/20/19 09:54	Reported	EtO Region 5	WB Warehouse	Field Sample	Probe #10314 Start 9:52 3/19/19	18874	3.50" Hg
390	9032106-01	TO-15 2019	03/20/19 11:07	Reported	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 12:03 3/19/19	19649	4.50" Hg
391	9032106-05	TO-15 2019	03/20/19 10:18	Reported	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 11:07 3/19/19	3256	6.00" Hg
392	9032106-09	TO-15 2019	03/20/19 09:58	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	Col 2 Probe # 10315 Start 10:05 3/19/19	19279	5.50" Hg
393	9032613-07	TO-15 2019	03/23/19 10:26	Received	EtO Region 5	Gower ES	Field Sample	Probe # 10076 Start 10:47 3/22/19	A21081	7.50" Hg
394	9032613-09	TO-15 2019	03/23/19 09:58	Received	EtO Region 5	Gower MS	Field Sample	Probe #10311 Start 10:01 3/22/19	18828	4.50" Hg
395	9032613-01	TO-15 2019	03/23/19 10:19	Received	EtO Region 5	Hinsdale South HS	Field Sample	Probe 10076 Start 10:37 3/22/19	5054	6.50" Hg
396	9032613-04	TO-15 2019	03/23/19 10:02	Received	EtO Region 5	Water Tower	Field Sample	Probe # 10312 Start 10:12 3/22/19	SAT054	3.50" Hg
397	9032613-02	TO-15 2019	03/23/19 09:53	Received	EtO Region 5	WB Village Hall	Field Sample	Probe #10313 Start 9:50 3/22/19	96	3.00" Hg
398	9032613-05	TO-15 2019	03/23/19 09:50	Received	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Probe #10314 Start 9:41 3/22/19	SAT111	3.50" Hg
399	9032613-03	TO-15 2019	03/23/19 10:42	Received	EtO Region 5	West Neighborhood	Field Sample	Probe # 10310 Start 10:57 3/22/19	SAT067	3.50" Hg
400	9032613-08	TO-15 2019	03/23/19 10:07	Received	EtO Region 5	Willow Pond Park	Field Sample	Probe # 10294 Start 10:26 3/22/19	5058	6.50" Hg
401	9032613-06	TO-15 2019	03/23/19 09:50	Received	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Probe #10315 Start 9:41 3/22/19	SAT114	5.50" Hg