United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

November 22, 2010

Mr. Ed Peresie
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 10-0537
ACHD Reference Number: 13240; 13241
#2 Control Room
USS Clairton Works

Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler
Plant Manager
Clairton Works

RECEIVED
NOV 30 2010
3AP20

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. **USS Reference Number:** 10-0537
   ACHD Reference Number: 13240; 13241

2. **Date & Time of Breakdown:** Date: 11/19/10 Time: 1100 hours

3. **Company Name:** U.S. Steel Corporation - USS Clairton Works

4. **Specific Equipment Involved or Affected:** #2 Control Room

5. **BAPC Permit Number (if applicable):**

6. **Location:** Clairton, PA

7. **Nature and cause of breakdown:** A H_2S analyzer instrument failure at the #2 C.R. resulted in false momentary exceedance readings of the 40 grain H_2S limit.

8. **Identification of Emissions:**

   A. **Type(s) (CO, NOX, SO_2, Particulates, Hydrocarbons, etc.)** N/A.

   B. **Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality).** N/A

   C. **Amount of each type emitted (or likely to be emitted).** N/A

9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**
   The analyzer problem was resolved.

10. **Facility back in operation** - Date: 11/20/10 Time: 1110 hours

Signature Coleen M. Davis Date 11-23-10
Coleen M. Davis
Senior Environmental Control Engineer Phone: 412-233-1015