One of community alliance requests: Move Monitor closer to St. where Ms. Moore lives. (7)

- Construction company has two wind measuring monitors
  - ↳ site dvlpr. now has grind up & recycle materials. Have specific reqmnts for moving materials. Standards for construction processes.
- Dust & asbestos requires 2 diff monitors
  - Cardiotick & Alice Griffin's monitors
    - ↳ data posted on website of OCII
      - ↳ & explanation of data
  - frustrating: revision of dust plan has taken 2 months
    - → Wind speed issue heard & put into revised plan.
    - → report issue to IVAN aut. soil for lamar
      - ↳ soil brought by indiv. vendors following CalTrans requirements for melting dirt.
- Ms. Moore saw coated & uncoated surcharge piles. Should be dyed Green to alert community members that piles have been sealed.
  - ↳ The piles she saw were [redacted] not