Message

From: Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]
Sent: 1/25/2017 3:47:42 PM
To: Beslow, Mike [beslow.mike@epa.gov]
Subject: RE: 009

#1169453

Thomas Barnett | Manager, Environmental Technology
ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001
East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

-----Original Message-----
From: Beslow, Mike [mailto:beslow.mike@epa.gov]
Sent: Wednesday, January 25, 2017 9:44 AM
To: Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>; sean.f.fitzgerald@uscg.mil
Subject: RE: 009

Can you please provide the NRC number?

Mike Beslow
On-Scene Coordinator
US EPA, Region 5
77 W Jackson (SE-5J)
Chicago, IL 60604
voice: (312)353-8678
fax: (312)582-5139

-----Original Message-----
From: Barnett, Thomas R [mailto:Thomas.Barnett@arcelormittal.com]
Sent: Wednesday, January 25, 2017 9:40 AM
To: sean.f.fitzgerald@uscg.mil
Cc: Beslow, Mike <beslow.mike@epa.gov>
Subject: FW: 009

This morning about 8:45. We had a small discharge at 8:13 (National was on scene), collected it in the booms.

Sheen does not show up well in the picture, but there is a band of it inside the booms. National is picking it up this morning.

Sump inspection was done at the Power house and the Blast furnace this morning, no oil. We will start sending an every turn check list of these sumps later today.

This was called into the NRC about 20 minutes ago.

Thomas Barnett | Manager, Environmental Technology ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

-----Original Message-----
From: Barnett, Thomas R
Sent: Wednesday, January 25, 2017 9:30 AM
To: Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>
Subject: 009