Nameplate on the panel is incorrect; this is actually for C-103 (not C-104).

C-103



C-104