United States Environmental Protection Agency
Washington, D.C. 20460

Water Compliance Inspection Report

Section A: National Data System Coding (i.e., PCS)

Transaction Code	NPDES	yr/mo/day	Inspection Type	Inspector	Fac Type
1 N 2 5	3 CAU000000 11	12 17	18 =	19 J	20 3

Remarks

21 65

Inspection Work Days	Facility Self-Monitoring Evaluation Rating	BI	QA	Reserved
67 2 0 0 69	70 2	71 N	72 N	73 74 / 75 80

Section B: Facility Data

Name and Location of Facility Inspected *(For industrial users discharging to POTW, also include POTW name and NPDES permit number)*	Entry Time/Date	Permit Effective Date
ARMSTRONG EGG FARMS Ex. 6 Personal Privacy (PP) D	1:25 PM-3/26/14	N/A
	Exit Time/Date	Permit Expiration Date
	3:30 PM-3/26/14	N/A

Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)

RYAN ARMSTRONG, VP OPERATIONS, (OFC)
Ex. 6 Personal Privacy (PP)

Other Facility Data *(e.g., SIC NAICS, and other descriptive information)*

SIC CODE:

Name, Address of Responsible Official/Title/Phone and Fax Number

SAME AS ABOVE

Contacted ☐ Yes ☐ No

Section C: Areas Evaluated During Inspection *(Check only those areas evaluated)*

☐ Permit	☐ Self-Monitoring Program	☐ Pretreatment	☐ MS4
☐ **Records/Reports**	☐ Compliance Schedules	☐ Pollution Prevention	
☐ Facility Site Review	☐ Laboratory	☐ Storm Water	
☐ Effluent/Receiving Waters	☐ Operations & Maintenance	☐ Combined Sewer Overflow	
☐ Flow Measurement	☐ Sludge Handling/Disposal	☐ Sanitary Sewer Overflow	

Section D: Summary of Findings/Comments

(Attach additional sheets of narrative and checklists, including Single Event Violation codes, as necessary)

SEV Codes	SEV Description
☐☐☐☐☐	
☐☐☐☐☐	
☐☐☐☐☐	
☐☐☐☐☐	

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Phone and Fax Numbers	Date
KRISTINE KARLSON *Kristine Karlson*	EPA R9/ENF 3-1/415-947-4297	6/20/14
MICHELLE MATA AND DAT QUACH		
Signature of Management Q A Reviewer	Agency/Office/Phone and Fax Numbers	Date

EPA Form 3560-3 (Rev 1-06) Previous editions are obsolete.

INSTRUCTIONS

Section A: National Data System Coding *(i.e., PCS)*

Column 1: Transaction Code: Use N, C, or D for New, Change, or Delete. All inspections will be *new* unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc.. *(Use the Remarks columns to record the State permit number, if necessary.)*

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

A Performance Audit
B Compliance Biomonitoring
C Compliance Evaluation (non-sampling)
D Diagnostic
F Pretreatment (Follow-up)
G Pretreatment (Audit)
I Industrial User (IU) Inspection
J Complaints
M Multimedia
N Spill
O Compliance Evaluation (Oversight)
P Pretreatment Compliance Inspection
R Reconnaissance
S Compliance Sampling

U IU Inspection with Pretreatment Audit
X Toxics Inspection
Z Sludge - Biosolids
Combined Sewer Overflow-Sampling
$ Combined Sewer Overflow-Non-Sampling
+ Sanitary Sewer Overflow-Sampling
& Sanitary Sewer Overflow-Non-Sampling
\ CAFO-Sampling
= CAFO-Non-Sampling
2 IU Sampling Inspection
3 IU Non-Sampling Inspection
4 IU Toxics Inspection
5 IU Sampling Inspection with Pretreatment
6 IU Non-Sampling Inspection with Pretreatment
7 IU Toxics with Pretreatment

! Pretreatment Compliance (Oversight)
@ Follow-up (enforcement)
{ Storm Water-Construction-Sampling
} Storm Water-Construction-Non-Sampling
: Storm Water-Non-Construction-Sampling
~ Storm Water-Non-Construction-Non-Sampling
< Storm Water-MS4-Sampling
- Storm Water-MS4-Non-Sampling
> Storm Water-MS4-Audit

Column 19: Inspector Code. Use one of the codes listed below to describe the *lead agency* in the inspection.

A — State (Contractor)
B ---- EPA (Contractor)
E — Corps of Engineers
J — Joint EPA/State Inspectors—EPA Lead
L ---- Local Health Department (State)
N — NEIC Inspectors

O— Other Inspectors, Federal/EPA (Specify in Remarks columns)
P— Other Inspectors, State (Specify in Remarks columns)
R — EPA Regional Inspector
S — State Inspector
T — Joint State/EPA Inspectors—State lead

Column 20: Facility Type. Use one of the codes below to describe the facility.

1 — Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
2 — Industrial. Other than municipal, agricultural, and Federal facilities.
3 — Agricultural. Facilities classified with 1987 SIC 0111 to 0971.
4 — Federal. Facilities identified as Federal by the EPA Regional Office.
5 — Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columns 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed documentation.

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise.

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection

Check only those areas evaluated by marking the appropriate box. Use Section D and additional sheets as necessary. Support the findings, as necessary, in a brief narrative report. Use the headings given on the report form (e.g., Permit, Records/Reports) when discussing the areas evaluated during the inspection.

Section D: Summary of Findings/Comments

Briefly summarize the inspection findings. This summary should abstract the pertinent inspection findings, not replace the narrative report. Reference a list of attachments, such as completed checklists taken from the NPDES Compliance Inspection Manuals and pretreatment guidance documents, including effluent data when sampling has been done. Use extra sheets as necessary.

*Footnote: In addition to the inspection types listed above under column 18, a state may continue to use the following wet weather and CAFO inspection types until the state is brought into ICIS-NPDES: K: CAFO, V: SSO, Y: CSO, W: Storm Water 9: MS4. States may also use the new wet weather, CAFO and MS4 inspections types shown in column 18 of this form. The EPA regions are required to use the new wet weather, CAFO, and MS4 inspection types for inspections with an inspection date (DTIN) on or after July 1, 2005.