Message

From: d'Almeida, Carolyn K. [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=9EC4401AFA1846DD93D52A0DDA973581-CDALMEID]
Sent: 12/4/2018 10:03:38 PM
To: Davis, Eva [Davis.Eva@epa.gov]; 'Brasaemle, Karla' [KBrasaemle@TechLawInc.com]
Subject: FW: 2018-12-4 - WAFB - FYI - ST012 GW Pumping wells 11-26-2018 - pre-EBR sulfate- sw uxo

FYI

Carolyn d'Almeida
Remedial Project Manager
Federal Facilities Branch (SFD 8-1)
US EPA Region 9 Laboratory
1337 South 46th Street, Building 201
Richmond, CA 94804
(415) 972-3150

"We can evade reality, but we cannot evade the consequences of evading reality." - Ayn Rand

---

From: Wayne Miller <Miller.Wayne@azdeq.gov>
Sent: Tuesday, December 4, 2018 1:25 PM
To: d'Almeida, Carolyn K. <dAlmeida.Carolyn@epa.gov>
Subject: 2018-12-4 - WAFB - FYI - ST012 GW Pumping wells 11-26-2018 - pre-EBR sulfate- sw uxo

FYI - UXO Pro, Inc. received a list of ST012 groundwater wells pumping/not pumping (work week of Nov. 26, 2018):

CZ07 7.6 gpm T = 149 F

CZ18 7.4 gpm T = 130 F

CZ-19 down

CZ-21 down

UWBZ-21 down

UWBZ-22 pumping but flow meter not working

UWBZ-26 pumping but flow meter not working T = 122 F

UWBZ-27 down

UWBZ-30 down

UWBZ-28/LSZ-51 down

LSZ-09 5.9 gpm T = 129

LSZ-11 pumping but meter not working T = 98 F

LSZ-12 3.8 gpm T = 114 F

LSZ-23 2.8 gpm T = 101 F

LSZ-28 down

LSZ-29 down

LSZ-37 3.6 gpm T = 88 F

LSZ-38 1.2 gpm T = 92 F

LSZ-39 3.0 gpm T = 80 F

Wells listed as "down" have a pump, but the pump is being repaired.

Thanks.

Wayne Miller
Waste Programs Division,
Remedial Projects Section,
Federal Projects Unit

Arizona Department of Environmental Quality
1110 West Washington Street
Phoenix, AZ 85007

Direct Line: 602.771.4121
Email: miller.wayne@azdeq.gov