Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: NYD055865125
2. Page 1 of 1
3. Emergency Response Phone: 1 800 274 5263
4. Manifest Tracking Number: 002661047 FLE

5. Generator's Name and Mailing Address
SYRACUSE CHINA CORP
2801 COURT STREET
SYRACUSE NY 13208

Generator's Site Address (if different than mailing address)
SYRACUSE CHINA COMPANY
2801 COURT ST
SYRACUSE NY 13208

Generator's Phone: (315) 455-4534 ATTN: PAULA DESTEFANO

6. Transporter 1 Company Name: FREEHOLD CARTAGE, INC.
U.S. EPA ID Number: NJD054126164

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address
CWM CHEMICAL SERVICES L.L.C.
1550 BALMER ROAD
MODEL CITY NY 14107
U.S. EPA ID Number: NYD049836679
Facility's Phone: (716)754-8231 AC 2/17/09 ~~(800) 457-4762~~

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. UN3432, POLYCHLORINATED BIPHENYLS, SOLID, 9, II RQ(POLYCHLORINATED BIPHENYLS (PCBS)), 03-5796 LIGHT BALLASTS, MDC#035796	001	DM	0153	K	B007	~~NONE~~	L
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
2043187
Omitted out of service date as required by 40 CFR 761.207.
81632764

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: PAULA J DESTEFANO
Signature: Paula J DeSt
Month 01 Day 23 Year 09

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Robert Fruin
Signature:
Month 01 Day 23 Year 09
Transporter 2 Printed/Typed Name
Signature
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Angela Cadualadr
Signature: Angela Cadualadr
Month 2 Day 17 Year 09

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)