CX507 ENE 1/2-1 0.787 mi. 4157 ft. | **OCEAN PARKWAY 365" SOUTH OF AVE Z BROOKLYN, NY** | **NY Spills** | **S104505856 N/A**

Site 2 of 2 in cluster CX

Relative: Higher

Actual: 9 ft.

SPILLS:

Name:	OCEAN PARKWAY 365" SOUTH
Address:	OF AVE Z
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9808460 / 2002-10-25
Facility ID:	9808460
Facility Type:	ER
DER Facility ID:	135927
Site ID:	161001
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-10-08
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1998-10-08
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-08
Spill Record Last Update:	2002-10-25
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #120404: V.VAVALLO #57666 OS NETWORK REPORTS IN V6609 E/S OCEAN PKWY 365' S/O AVE Z HE FOUND THAT A TRANSF (TRANSF INSTALLED FEB 1969) WAS LEAKING FROM SECONDARY BUSHING (HE VISUALLY SEES IT LEAKING AT PHASE NO#1). HE ESTIMATES APPROX UNDER 2 GAL OF TRANSF OIL LEAKED INTO SEWERS VIA A SUMP PUMP THAT WAS RUNNING. PUMP WAS DISCONNECTED. APPROX 2 GAL OF TRANSF OIL IS IN VAULT ON TOP OF AN UNKNOWN AMOUNT OF WATER AT THIS TIME. SAMPLE WAS TAKEN (4-6 HRS PRIORITY FOR SAMPLE RESULTS) AND E.S.TAG #08545 WAS PLACED. ENVIR MGR ZALLOUGHI WAS NOTIFIED AND IS GOING TO LOCATION AS OF 1210 HRS. (OLD RECORD OF TRANSF SHOW IT TO BE 26 PPM) CIG MURPHY NOTIFIED 1230 HRS. UPDATE 10/8/98 1400HRS pressure tested unit- found it did not leak --mr. zalloughi and mr. vavallo determined that unit leaks when under load. UPDATE 10-8-98 1555 HRS V.VAVALLO OS REPORTS AT 1315 HRS HE WAS CALLED BACK BY THE UG ON LOCATION . DEP (OLUREMI FATIMILEHIN) WAS ON LOCATION AND REQUEST A SAMPLE (FROM TRANSF) TO BE TAKEN TO BE SENT TO A OUTSIDE VENDOR FOR TESTING. SIGNED THE CHAIN OF CUSTODY. SECONDARY WAS CUT BY UG SPLICER 1552 HRS. NOTE CIG MURPHY REPORTS WAS UNABLE TO TAKE INCINDENT AT 1230HRS.HE NOTIFIED ERT SHAH. 1300HRS-EVIR.MGT ZALLOUGHI ARRIVED ON LOC ,CALLED MR SHAH ERT ADVISED

HIM REPORT IS CORRECT UNDER 2-GALLONS ESCAPED. NO REGULATORY AGENCY ON LOCATION. SHAH RELEASED ZALLOUGHI FROM LOCATION. UPDATE 10-28-98 N.SAVOCA FLUSH REPORTS CLEANUP COMPLETED AND E.S.TAG #08545 WAS REMOVED 29 PPM. LAB RESULT RECEIVED FROM CHEM LAB 10/8/98 - 2015. 98-10813. 29 PPM. STILL AWAITING RESULT FROM OUTSIDE LAB. UPDATE 10/9/98 JOB TO BE TREATED AS 50-499 TANKER ORDERED AND EPA#NYP004018834. UPDATE: 10/9/98 - 0730 R. DONOVAN CALLED DEP, WAS TRANSFERRED TO 595-4718 AND SPOKE TO ALBERT. HE WAS TOLD BY ALBERT TO SPEAK TO HAZMAT AT 595-4646. HE WAS ALSO TOLD NOONE WOULD BE THERE UNTIL 0900. AT 8 A.M., V. VAVALLO - O.S. - EQUIP GP, CALLED DEP AND WAS TOLD SAME THING. AT 0910 R. DONOVAN CALLED DEP AND SPOKE TO E. CATANZARO. MR CATANZARO EXPLAINED THAT THEY DO NOT TAKE SAMPLES FOR US TO USE AS A COMPARISON TO OUR CHEM LAB. IF WE WANT TO GET RESULTS OF THIER SAMPLING, WE HAVE TO WRITE TO THE DEP UNDER THE FREEDOM OF KNOWLEDGE ACT. AT THIS PARTICULAR TIME OUR CLEANUP WILL BE DONE AS 29 PPM BASED ON OUR CHEM LAB RESULT. UPDATE: 10/9/98 - 1415 AS PER PHONE CONVERSATION BETWEEN TOM MIMNAGH, STEVE ZALLOUGHI AND MR. SHAH (ERT), IT HAS BEEN DECIDED THAT THE UNIT WILL BE DRAINED AS 50-499. THE CLOCK STOPS WITH THE 29 PPM RESULT. THE UNIT WILL BE REMOVED AND THE CLEANUP COMPLETED AT THE CONVENIENCE OF THE EQUIP. GROUP. UPDATE 10-09-98 21:04HRS S. FULLER REPORTS, OIL WAS DRAINED FROM V 6609 CLEANUP STILL PENDING. UPDATE: 10/28/98 - 1700 N. SAVOCA - 17932 - ENV. OPS., REPORTS 29 PPM CLEANUP COMPLETE AND TAG #08545 REMOVED. INCIDENT IS CLOSED. UPDATE 5/14/02 @ 1315 HRS. -- VERIFIED WITH NETWORKS THAT THIS DEFECTIVE TRANSFORMER WAS REMOVED 10/28/98. "

Remarks: "leaking transformer in a vault about 2 galls went into sewer vault #6609 ass. pcb court is 50-499 ref #120404"

All Materials:

Site ID:	161001
Operable Unit ID:	1069653
Operable Unit:	01
Material ID:	315967
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported