BR350 NE 1/2-1 0.575 mi. 3035 ft. | **TM# 2464 NORTHSIDE AVE Z/WEST 2ND BROOKLYN, NY** | **NY Spills** | **S104510391 N/A**

Site 2 of 2 in cluster BR

Relative: Higher

Actual: 14 ft.

SPILLS:

Name:	TM# 2464
Address:	NORTHSIDE AVE Z/WEST 2ND
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9913568 / 2001-12-21
Facility ID:	9913568
Facility Type:	ER
DER Facility ID:	109523
Site ID:	126771
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-03-01
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-03-01
CID:	366
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-03-01
Spill Record Last Update:	2001-12-21
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis notes: 5 gallons transformer oil on 10 gallons water in tm2464. Transformer to be condemned. Sample and cleanup pending de-energization. 3/2/00: Lab results 41 ppm PCB. Clean up completed, transformer replaced, sump cemented."
Remarks:	"CALLER REPORTING THAT 5 GALS SPILLED ONTO WATER IN MANHOLE. THE TRANSFORMER HAS BEEN CONDEMMED AND WILL BE REMOVED. SAMPLES TO BE TAKEN LATER AND CLEAN UP FOLLOWING. A 1981 PCB TEST RESULT 35 PPM."

All Materials:

Site ID:	126771
Operable Unit ID:	1088105
Operable Unit:	01
Material ID:	295406
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G

Recovered: .00
Oxygenate: Not reported