LE1527 ENE > 1 1.914 mi. 10107 ft. | **POLE 11109 BEDFORD AVE AND AVE Z BROOKLYN, NY** | **NY Spills** | **S113915837 N/A**

Site 1 of 2 in cluster LE

Relative: Higher

Actual: 10 ft.

SPILLS:

Name:	POLE 11109
Address:	BEDFORD AVE AND AVE Z
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1306046 / 2013-11-20
Facility ID:	1306046
Facility Type:	ER
DER Facility ID:	441734
Site ID:	486636
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2013-09-09
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2013-09-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-09
Spill Record Last Update:	2013-11-20
Spiller Name:	ERT
Spiller Company:	CONEDISON
Spiller Address:	4 IRVING PL
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"Emis#: 234953 9/9/2013 - Spoke to Dennis Michaelides of ERT Hotline (212-580-8383). Transformer Pole leak on the concrete. It is 3 quarts of dielectric fluid. The crew is onsite and cleanup is taking in place. 11/20/13 - Austin - 3 quart pole transformer spill, from leaking bushing onto pavement - Con Ed contained and cleaned up the spill, and removed the transformer - See eDocs files for further information - Spill closed - end"
Remarks:	"2 Quarts spilled to concrete. Clean up is pending crew arrival."

All Materials:

Site ID:	486636
Operable Unit ID:	1236283
Operable Unit:	01
Material ID:	2235650
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G

Recovered: Not reported
Oxygenate: Not reported