To: KHanson@ldftribe.com[KHanson@ldftribe.com]; Olson, Erik[olson.erik@epa.gov]; rdubey@scblaw.com[rdubey@scblaw.com]; Dee.allen@ldftribe.com[Dee.allen@ldftribe.com]; lwawronowicz@ldftribe.com[lwawronowicz@ldftribe.com]; Kamke, Sherry[Kamke.Sherry@epa.gov]
From: Egan, Robert
Sent: Tue 5/24/2016 2:58:31 PM
Subject: revised summary of EPA-funded work at Tower Standard/Haskell Lake
Tower Standard Summary 5-24-2016.pdf

All,

Please see the attached revised summary. After speaking to one of our risk assessors, I have dropped out the sub-slab screening level exceedances. Using the attenuation factor of 0.03 for soil gas, all compounds were well below the levels listed in our RSL Table. Also, the only indoor air exceedances are for compounds which are most likely not related to the UST release at the site.

Please let me know if you have any questions.

Bob Egan
Corrective Action Manager
Underground Storage Tanks Section
RCRA Branch
EPA Region 5
(312) 886-6212
(312) 692-2911 (fax)