To: Micham, Ross[micham.ross@epa.gov]
From: Manville, Jennifer
Sent: Tue 8/9/2016 5:01:26 PM
Subject: RE: Haskell Lake Lodge -- Lac du Flambeau Reservation

Thanks Ross. Perhaps you will have some time to discuss next week.

From: Micham, Ross
Sent: Monday, August 08, 2016 5:20 PM
To: Manville, Jennifer <manville.jennifer@epa.gov>
Cc: KHanson@ldftribe.com; Greenwater, Anthony <greenwater.anthony@epa.gov>; Hansen, Janette <hansen.janette@epa.gov>; Shoven, Heather <shoven.heather@epa.gov>
Subject: RE: Haskell Lake Lodge -- Lac du Flambeau Reservation

Hi Jenny,

The facility appears large enough to have a septic system that is federally regulated by the underground injection control program under the Safe Drinking Water Act. Our database lacks information for this facility indicating that the required inventory information has not been provided.

Generally, to be in compliance with the UIC requirements, the owner/operator of this septic system would need to provide EPA with inventory information and the treated sanitary wastewater discharges cannot contaminate the underground aquifer.

We can discuss UIC program options for follow-up.

Ross Micham, Geologist

Underground Injection Control Branch

U.S. EPA, Region 5

312-886-4237

From: Manville, Jennifer
Sent: Monday, August 08, 2016 3:27 PM
To: Hansen, Janette <hansen.janette@epa.gov>; Shoven, Heather <shoven.heather@epa.gov>; Micham, Ross <micham.ross@epa.gov>
Cc: KHanson@ldftribe.com; Greenwater, Anthony <greenwater.anthony@epa.gov>
Subject: Haskell Lake Lodge -- Lac du Flambeau Reservation

Hello all,

Kristen Hanson, environmental staff person with the Lac du Flambeau Band, contacted me recently about the Haskell Lake Lodge located at 14277 State Hwy 70 in Lac du Flambeau, Wisconsin. The property is located on non-member fee land within the boundaries of the Lac du Flambeau Reservation.

The hotel has approximately 25 rooms and some are occupied for an extended period of time. The facility has its own drinking water well and septic system. The state of Wisconsin recently indicated that it is not regulating the facility and advised the owner that either the federal and/or tribal government is responsible for overseeing the drinking water system. The facility is experiencing water contamination issues, possibly related to an adjacent leaking underground storage tank.

Does this facility meet the threshold requirement of connections/population to trigger regulation under the Safe Drinking Water Act under the public water supply supervision program and/or the underground injection control program?

Thanks,

Jenny

Jennifer Manville, Tribal Liaison

U.S. EPA Region 5

Tribal and International Affairs Office

Office: (231) 941-0237

Cell: (231) 633-2725