Message

From: Dickens, Brian [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=416CD582A67D44AAB91D3BEFF56B892D-BDICKENS]
Sent: 10/23/2018 3:57:08 PM
To: Marceillars, Rochelle [Marceillars.Rochelle@epa.gov]; Johnson, Lashana [Johnson.Lashana@epa.gov]; King-Hackney, Ashadee [King-Hackney.Ashadee@epa.gov]
CC: Harrison, Gina [harrison.gina@epa.gov]; St. Peter, Marie [StPeter.Marie@epa.gov]; Miller, Patrick [miller.patrick@epa.gov]
Subject: FW: NOV response
Attachments: AK Response_Sep2018NOV.pdf; 101218 Addendum to PMMAP.pdf

For edms

Here's the response from AK steel to "our" NOV (via Ohio)
There's also an explanation of bleeder openings due to a trial pellet.

From: Castlen, Kerri [mailto:Kerri.Castlen@hamilton-co.org]
Sent: Monday, October 15, 2018 6:40 AM
To: Dickens, Brian <dickens.brian@epa.gov>
Cc: Kramer, Mike <Mike.Kramer@hamilton-co.org>
Subject: FW: NOV response

Response from AK Steen on NOV dated 9/13/18.

From: Chris.Potts@aksteel.com [mailto:Chris.Potts@aksteel.com]
Sent: Friday, October 12, 2018 4:15 PM
To: Castlen, Kerri
Cc: Miller, Brad; Pat.Gallo@aksteel.com
Subject: NOV response

Chris Potts
Senior Environmental Engineer
AK Steel Middletown Works
office: (513) 425-3239
cell: (513) 594-2939
fax: (513) 425-3079

Confidentiality Notice
This message is intended exclusively for the individual or entity to which it is addressed and may contain privileged, proprietary, or otherwise private information.
If you are not the named addressee, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you have received this message in error, please notify the sender immediately by e-mail and delete all copies of the message.