type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

FORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	TXD000835215		1 800 274 5263	002302617 FLE

5. Generator's Name and Mailing Address
RESCAR - ORANGE
1993 FOREMAN RD.
ORANGE TX 77630

Generator's Site Address (if different than mailing address)
RESCAR
1993 FOREMAN RD
ORANGE TX 77630

Generator's Phone: (409) 883-0393 ATTN: ROBERT CASKEY

6. Transporter 1 Company Name: Bayducity Environmental — U.S. EPA ID Number: TXR000[illegible]

7. Transporter 2 Company Name: — U.S. EPA ID Number:

8. Designated Facility Name and Site Address
LIQUID ENVIRONMENTAL SOLUTIONS OF TEXAS
250 GELLHORN
HOUSTON TX 77013

U.S. EPA ID Number: TXR000057500 0

Facility's Phone: 713-671-4800

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NON DOT REGULATED MATERIAL, 27-37712 NON HAZ WASTE WATER, 136926		TT	5000	G	16511021 NONE
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information
1

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: [illegible] — Signature: [illegible] — Month: [illegible] Day: 2 Year: 09

16. International Shipments: ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: [illegible] — Signature: [illegible] — Month: [illegible] Day: [illegible] Year: [illegible]
Transporter 2 Printed/Typed Name: — Signature: — Month: Day: Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: [illegible] — Signature: [illegible] — Month: 1 Day: 12 Year: 09

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY'S COPY

TRK-717 - TANK 433

Print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number TXD000655215	2. Page 1 of	3. Emergency Response Phone 1 800 274 5263	4. Manifest Tracking Number 002302616 FLE

5. Generator's Name and Mailing Address
RESCAR - ORANGE
1993 FOREMAN RD.
ORANGE TX 77630
Generator's Phone: (409) 883-0293 ATTN: ROBERT CASKEY

Generator's Site Address (if different than mailing address)
RESCAR
1993 FOREMAN RD
ORANGE TX 77630

6. Transporter 1 Company Name: Bass City Ewn — U.S. EPA ID Number: TXR000320 45

7. Transporter 2 Company Name — U.S. EPA ID Number

8. Designated Facility Name and Site Address: LEGACY ENVIRONMENTAL SOLUTIONS OF TEXAS US. D. Tac
250 GELLHORN
HOUSTON TX 77013
Baytown TX 77566
Facility's Phone: 713-671-4000 — U.S. EPA ID Number: TXR000 [illegible] 000

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Units Wt/Vol.	13. Waste Codes
	1. NON DOT REGULATED MATERIAL, 27-97712 NON RRR WASTE WATER, 196525		TT	500	BL	16511021 NONE
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information
1

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Patrick Lovett — Signature: Patrick Lovett — Month 1 Day 12 Year 09

16. International Shipments: ☐ Import to U.S. ☐ Export from U.S. — Port of entry/exit: — Date leaving U.S.:
Transporter signature (for exports only):

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Larry Murphy — Signature: Larry Murphy — Month 1 Day 12 Year 09
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:
18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. Baytown TX 77566 | 2. | 3. | 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Jim Harris — Signature — Month 1 Day 12 Year 09

GENERATOR

Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY'S COPY

TXD 000835215

Type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

FORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number TXD000835215	2. Page 1 of	3. Emergency Response Phone 1 800 274 5263	4. Manifest Tracking Number 002302618 FLE

5. Generator's Name and Mailing Address
RESCAR - ORANGE
1993 FOREMAN RD.
ORANGE TX 77630

Generator's Site Address (if different than mailing address)
RESCAR
1993 FOREMAN RD
ORANGE TX 77630

Generator's Phone: (409) 882-0393 ATTN: ROBERT CASKEY

6. Transporter 1 Company Name: BRYAN CRETO ENVIRONMENTAL — U.S. EPA ID Number: TXR000032045

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ~~LIQUID ENVIRONMENTAL SOLUTIONS OF TEXAS~~ US OTC BRIDTPY, ~~250 GENOLAN~~ 1100 W. ROCKY RD, ~~HOUSTON TX 77012~~ — U.S. EPA ID Number: ~~TXR000057000~~

Facility's Phone: ~~713-671-4800~~

9a. HM	9b. U.S. DOT Description (Including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NON DOT REGULATED MATERIAL, 27-37/13 NON HAZ WASTE WATER, 196926		T T	500	G	16511021 NONE
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Patrick Curtis — Signature: Patrick Curtis — Month 1 Day 12 Year 09

16. International Shipments: [ ] Import to U.S. [X] Export from U.S. — Port of entry/exit: — Date leaving U.S.:
Transporter signature (for exports only):

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: SHANE WOODS — Signature: [signature] — Month 1 Day 12 Year 09
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space: [ ] Quantity [ ] Type [ ] Residue [ ] Partial Rejection [ ] Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Luis Garcia — Signature: [signature] — Month 01 Day 12 Year 09

GENERATOR — INTL — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY'S COPY