A1/A1/CO
vol. 39720

1100021295 35

A752
VS
720

February 25, 2006

RECEIVE
MAR 2 - 2006
Air/Toxics & Inspection
Coordination Branch
6EN-A

Mr. Robert Todd
US EPA Region 6
Air Enforcement Section (6EN-AA)
1445 Ross Avenue
Dallas, Texas 75202-2733

Re: Annual Compliance Certification for Weyerhaeuser – Dierks Mill, AFIN 31-00016

Dear Mr. Todd:

Enclosed is a signed copy of the Title V Annual Compliance Certification (ACC) for the Weyerhaeuser mill located in Dierks, Arkansas. The Mill operated under two permits during the applicable reporting period: Permit No. 0023-AOP-R2 from February 1, 2005 through May 18, 2005, and Permit No. 0023-AOP-R3 from May 19, 2005 through January 31, 2006. Therefore, two sets of ACC forms, one for each permit, are submitted with this letter. The signed original was submitted to ADEQ.

If you have any questions about the enclosed reports, please contact me at (870) 286-4380 or Mr. Jeremy Jewell of Trinity Consultants at (501) 225-6400.

Sincerely,

WEYERHAEUSER COMPANY

Larry Huntsberger

Larry Huntsberger
Environmental Manager

Enclosures

cc: Jeremy Jewell – Trinity Consultants

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to davidsonp@adeq.state.ar.us, or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **12/26/2005** Duration: **42min., 132 min.**

Time of Upset (starting & ending): **8:54-9:36, 11:06-13:18**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **80.0**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Start-up after scheduled shutdown**

Corrective Actions Taken: **Returned ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to davidsonp@adeq.state.ar.us, or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **12/23/2005** Duration: **42 min.**

Time of Upset (starting & ending): **18:06-18:48**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **68.8**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Scheduled shutdown**

Corrective Actions Taken: **After start-up, return ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to* davidsonp@adeq.state.ar.us, *or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **11/27/2005** Duration: **282 min.**

Time of Upset (starting & ending): **8:00-11:18, 11:24-12:48**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **80.0**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Start-up after scheduled shutdown**

Corrective Actions Taken: **After start-up, returned ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

CORRECTED

ADEQ
ARKANSAS
Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to davidsonp@adeq.state.ar.us, or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **11/23/2005** Duration: **120 min.**

Time of Upset (starting & ending): **21:00-23:00**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **70.8**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Scheduled shutdown**

Corrective Actions Taken: **After start-up, return ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to* davidsonp@adeq.state.ar.us, *or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **9/10/2005** Duration: **360 min.**

Time of Upset (starting & ending): **7:24-11:48, 11:54-12:36, 1:42-2:36**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **80**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Start-up after planned maintenance shutdown**

Corrective Actions Taken: **After boiler start-up, return ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to davidsonp@adeq.state.ar.us, or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **8/31/2005** Duration: **42**

Time of Upset (starting & ending): **11:06-11:48**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **35.4**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Scheduled Shutdown for maintenance**

Corrective Actions Taken: **ESP will be returned to normal operating condition after boiler started up and proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to Phyllis Davidson at (501) 682-0059, email it to* davidsonp@adeq.state.ar.us, *or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R2** CSN: **31-0016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **6/12/2005** Duration: **180 min.**

Time of Upset (starting & ending): **11:48-14:48**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **78.2**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **planned Shutdown/Startup for maintenance**

Corrective Actions Taken: **After boiler startup, return ESP to normal operating condition when proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870-286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 8/00