EPA United States Environmental Protection Agency

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	October 5, 2016		
Media:	Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	No-Name Osage County (SE 11-25-11)		
Facility Name:	Unknown and Blackland Lease (Bird Creek)		
Facility Physical Location:	SE/4, Sec. 11, T , R		
(city, state, zip code)	Pawhuska, OK		
Mailing Address:	Unknown		
(city, state, zip code)	Unknown		
County/Parish:	Osage		
Facility Contact	N/A		N/A
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	Kent W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2016.11.07 14:56:02 -06'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=WILLIE LANE, dnQualifier=0000007235 Date: 2016.11.21 13:10:05 -06'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Kent W. Sanborn visited the No-Name Osage County (SE 11-25-11) oil production facility located in the Latitude: 36.8322, Longitude: -96.4984 near Pawhuska, Oklahoma on October 5, 2016. No representative of No-Name Osage County (SE 11-25-11) was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

Bird Creek at Blackland Waterflood Lease.

Section II - OBSERVATIONS

At the time of the inspection, I took five water samples for analysis to the Oklahoma State University (OSU) in Stillwater, Oklahoma. I also met with the landowner, an Oklahoma Department or Environmental Quality (ODEQ), and representatives from Jireh Operating, LLC. and Grayhorse Operating, Inc. The meeting discussed the inspections.

Section III - AREAS OF CONCERN

At the time of the inspection, brine continues to affect the creek from an unknown source

Section IV - FOLLOW UP

Conduct a follow up inspection weekly to monitor the site and the creek.

Section V - LIST OF APPENDICES

There are no attachments to this report.