EPA United States Environmental Protection Agency

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	September 13, 2016		
Media:	brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	No-Name Osage County (SE 11-25-11)		
Facility Name:	Bird Creek Spill		
Facility Physical Location:	/4, Sec. , T , R		
(city, state, zip code)	Pawhuska, Oklahoma		
Mailing Address:	Unknown		
(city, state, zip code)	Unknown		
County/Parish:	Osage		
Facility Contact	N/A		N/A
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	Kent W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2016.09.29 18:08:09 -05'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=WILLIE LANE, dnQualifier=0000007235 Date: 2016.09.30 10:33:51 -05'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Kent W. Sanborn visited the No-Name Osage County (SE 11-25-11) oil production facility located in the Latitude: 36.832308, Longitude: -96.49798 near Pawhuska, on September 13, 2016. No representative of No-Name Osage County (SE 11-25-11) was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

A follow up inspection of the Bird Creek area was conducted to document changes to Bird Creek in salinity levels, and to document the source of the containments in the creek.

Section II - OBSERVATIONS

At the time of the inspection, Bird Creek still had brine fluids that measured over 80,000 parts-per-million (ppm) in Total Soluble Salts (TSS) at the County Road 4550 bridge. There were other inspectors on site utilizing the Ohm-mapper tool to track the sources of the contaminates in the area, please refer to that inspection report for the documented observations that occurred during that inspection. At the time of the inspection, the source of the brine in Bird Creek was unknown.

Section III - AREAS OF CONCERN

There continue to be over 80,000 ppm TSS readings in Bird Creek and there was not a known point of discharge at the time of the inspection.

Section IV - FOLLOW UP

Conduct follow up inspections weekly.

Section V - LIST OF APPENDICES

There are no attachments to this report.