EPA United States Environmental Protection Agency

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	November 9, 2016		
Media:	Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	No-Name Osage County (SE 11-25-11)		
Facility Name:	Unknown (Bird Creek)		
Facility Physical Location:	/4, Sec. , T , R		
(city, state, zip code)	Pawhuska, Oklahoma		
Mailing Address:	Unknown		
(city, state, zip code)	Unknown		
County/Parish:	Osage		
Facility Contact	N/A		N/A
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	K.W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2016.12.19 18:11:25 -06'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE Date: 2016.12.22 12:11:34 -06'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the No-Name Osage County (SE 11-25-11) oil production facility located in the Latitude: 36.8323, Longitude: -96.4985 near Pawhuska, on November 9, 2016. No representative of No-Name Osage County (SE 11-25-11) was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

A creek survey of Bird Creek was conducted. The point of entry location was not leased for oil production at the time of the inspection.

Section II - OBSERVATIONS

During the creek survey and monitoring, I measured salinity of Bird Creek with a calibrated YSI 30 Conductivity Meter. I measured Total Soluble Salts (TSS) in Bird Creek and found measurements ranging up to 65,000 parts-per-million (ppm) in Bird Creek at the time of the inspection.

Section III - AREAS OF CONCERN

At the time of the inspection, brine was still present in Bird Creek. The TSS concentrations varied by location and distance from the apparent discharge point of entry into Bird Creek. The

Section IV - FOLLOW UP

Conduct a follow up inspection in approximately one month.

Section V - LIST OF APPENDICES

There are no attachments to this report.