EPA United States Environmental Protection Agency

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	March 31, 2017		
Media:	Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	David Sell, LLC		
Facility Name:	Ward		
Facility Physical Location:	SE /4, Sec. 31, T , R		
(city, state, zip code)	Pawhuska, Oklahoma		
Mailing Address:	1617 Revard		
(city, state, zip code)	Pawhuska, OK 74056		
County/Parish:	Osage		
Facility Contact	N/A		N/A
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	K.W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2017.04.24 10:51:50 -05'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	Lane, Willie Digitally signed by Lane, Willie Date: 2017.05.12 15:59:56 -05'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the David Sell, LLC oil production facility located in the Latitude: 36.8543, Longitude: -96.2618 near Pawhuska, on March 31, 2017. No representative of David Sell, LLC was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The inspection consisted of a creek survey and associated follow up to previous inspection observations at the site. The creek survey was conducted near the Ward Number 10 and Ward Number 9 facilities.

Section II - OBSERVATIONS

At the time of the inspection, I took readings with a YSI 30 conductivity meter at two areas in the nearby creek. The salinity ranged from 200 parts-per-million (ppm) to 300 ppm in the creek survey. I did not observe oil sheen on the surface of the creek at the time of the inspection. There were several agencies present during the inspection, including Oklahoma Department of Environmental Quality (ODEQ), Bureau of Indian Affairs (BIA), and Oklahoma State Bureau of Investigation (OSBI). ODEQ was present and took samples from two dumping locations near the two creek locations, which were inspected during my creek survey.

Section III - AREAS OF CONCERN

None at the time of the inspection.

Section IV - FOLLOW UP

Conduct follow up inspections as needed.

Section V - LIST OF APPENDICES

There are no attachments to this report.