Message

From: Brown, Jamesr [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=6F64739EE90E4087B2A77B32C4E4549F-BROWN, JAMESR]
Sent: 10/19/2018 2:25:54 PM
To: Gray, David [gray.david@epa.gov]
CC: Maguire, Charles [maguire.charles@epa.gov]; David Garcia (garcia.david@epa.gov) [garcia.david@epa.gov]; Edlund, Carl [edlund.carl@epa.gov]; Crossland, Ronnie [Crossland.Ronnie@epa.gov]; Delgado, Paige [Delgado.Paige@epa.gov]; Rhotenberry, William [Rhotenberry.William@epa.gov]; Smalley, Bryant [smalley.bryant@epa.gov]; Smith, Monica [smith.monica@epa.gov]; Ngo, Kim [Ngo.Kim@epa.gov]; Taheri, Diane [Taheri.Diane@epa.gov]
Subject: Craft-Turney Water Supply Corporation Update, October 18, 2018
Attachments: Craft-Turney Oct 18 2018.docx

Update

TCEQ reported on Oct. 18, 2018, that the **do not use order** remains in effect for the original 11 connections served by the Craft-Turney Water Supply Corporation in Jacksonville, TX. Flushing continued through last weekend for this hydraulically isolated part of the distribution system. A preliminary review of the results from samples taken this area on October 16, 2018, still indicates the presence of low levels of Chlorothalonil (keep in mind this compound is insoluble in water). The concentrations are below the health advisory level for this contaminant, and further review is being conducted by the TCEQ's Toxicology Division.

Four quality control samples were also taken on October 18, 2018. Bottled water is still being provided to these 11 service connections and a local church continues to offer these residents their facilities for showering and washing.

James R. Brown, P.G.
Associate Director
Safe Drinking Water Branch
Water Division
U.S. EPA Region 6
1445 Ross Avenue (Mail Code: 6WQ-S)
Dallas, Texas 75202-2733
Phone: (214) 665-3175

https://www.epa.gov/