From: Boykin, Michael
To: "Marty Burck"
Cc: THOMS Bryn; Leefers, Kristin
Subject: RE: Triangle Oil
Date: Thursday, October 08, 2015 11:33:00 AM

Hi Marty,
EPA and our START contractor did not collect soil vapor samples, we conducted a geoprobe investigation and collected soil samples from the sample sleeve (depending on recovery) and groundwater samples if present. We followed SOPs on geoprobing, soil and water sample collection, among others. The SOPs are attached to our Draft sampling plan that is being finalized as we speak.

I can arrange to forward the relevant SOPs if you wish to review and possibly emulate, otherwise we can send you the whole sampling plan with all attachments once it is final, probably early next week.

Sincerely,
Mike

Michael Boykin
Federal On-Scene Coordinator (FOSC)
US EPA Region 10
Emergency Management Program
1200 Sixth Avenue, Suite 900
ECL-133
Seattle, WA 98101
boykin.michael@epa.gov
Office 206.553.6362
Fax 206.553.0175

From: Marty Burck [mailto:mburck-msba@gorge.net]
Sent: Tuesday, October 06, 2015 9:53 AM
To: Boykin, Michael
Subject: Triangle Oil

Michael,
I am seeking information regarding the protocol that was utilized for the soil vapor sampling conducted by EPA in John Day Oregon this past June/July. More specifically, I am looking for sample depth, screen interval, purge volume, etc… In other words, basic information regarding the configuration of the vapor sample probes and collection methodology.

I am preparing to conduct vapor sampling at the site in the near future (beginning Oct 18th) and would like to have this information as a reference for comparison and/or emulation. Due to the short period time between now and the scheduled sampling, your prompt attention to this matter is greatly appreciated.

Thank you for your assistance.

Marty Burck

Licensed Geologist OR, CA, WA

Martin S. Burck Associates, Inc.
Geologic and Environmental Consulting Services

200 North Wasco Court
Hood River, Oregon 97031
Phone: 541 387 4422
Fax: 541 387 4813
Email: mburck-msba@gorge.net