From: Donaldson, Guy
To: "Keith Sheedy"
Subject: RE: March 23rd ambient lead data
Date: Wednesday, April 03, 2013 8:57:00 AM

Thanks

From: Keith Sheedy [mailto:keith.sheedy@tceq.texas.gov]
Sent: Wednesday, April 03, 2013 8:50 AM
To: Donaldson, Guy
Cc: Johnson, Terry
Subject: RE: March 23rd ambient lead data

One area of the report just states "no work was performed after 7:50 a.m. due to weather conditions." Another area of the report states: 7:50 – stop work – data failure – stop work communication failure – downwind devise G4607 - "all demolition activities ceased at this time, Radio/Gateway issue". So I'm guessing that the weather knocked out one of the monitors.

From: Donaldson, Guy [mailto:Donaldson.Guy@epa.gov]
Sent: Wednesday, April 03, 2013 8:35 AM
To: Keith Sheedy
Cc: Johnson, Terry
Subject: RE: March 23rd ambient lead data

Just curious Keith.

Was it wind speed or was it storms that shut them down?

From: Keith Sheedy [mailto:keith.sheedy@tceq.texas.gov]
Sent: Tuesday, April 02, 2013 9:38 AM
To: Alyssa Taylor; Amy Browning; Bill Shafford; Brian Foster; Chance Goodin; Daphne McMurrer; David Brymer; Dois Webb; Donna Huff; Eddy Lin; Kim Herndon; Lindley Anderson; Luke Jones; Margaret Earnest; Margaret Ligarde; Robert Opiela; Stephanie Shirley; Tony Walker; Walker Williamson; David (Frisco) MCKERCHER; Frank Clark; gpurefoy@friscotexas.gov; Donaldson, Guy; Mack Borchardt; Nally, Bill; Ron Patterson; Johnson, Terry; Vanessa.coleman@exide.com
Subject: March 23rd ambient lead data

Attached is the March 23rd ambient lead monitoring data for the Frisco area. The monitor with the highest reading was the Stonebrook monitor, with a reading of 0.00574 micrograms per cubic meter. The wind speed was between 2.0 to 11.0 miles per hour, with a maximum wind gust of 21.7 mph. The wind direction was mainly from the North-by-east to East-by-south, with a few hourly spikes with the wind direction coming from the North.

On March 23rd, Exide and its contractors were conducting decontamination and demolition activities at the site. However, due to weather conditions the work hours were from 7:00 a.m. to 7:50 a.m. Lead/cadmium sampling was not conducted on this day.

Keith