To: Hoppe, Michael[Hoppe.Michael@epa.gov]; Vaughn, Stephanie[Vaughn.Stephanie@epa.gov]
Cc: Gary.Foster@CH2M.com[Gary.Foster@CH2M.com]; Roger.McCready@CH2M.com[Roger.McCready@CH2M.com]; John Rolfe[jrolfe@demaximis.com]; Willard Potter[otto@demaximis.com]; Robert Law[rlaw@demaximis.com]
From: Stan Kaczmarek
Sent: Thur 8/15/2013 9:21:29 PM
Subject: Turbidity Monitoring

The data logger from Buoy 1 that transmits and logs data from the WQ instruments went out of service earlier today. The logger from Buoy 5 was removed and installed in Buoy 1 to allow real-time monitoring at this compliance point to continue. The buoy itself, the sonde, and monitoring instruments in Buoy 1 remain unchanged.

The malfunctioning logger has been sent out for repairs and will be reinstalled at the earliest opportunity. In the meantime, the Removal Action will be without the service of data logging at Buoy 5, the mobile turbidity buoy. I will inform you when it is again able to log and transmit turbidity data.

Stan Kaczmarek, PE
de maximis, inc.
186 Center Street, Suite 290
Clinton, NJ 08809
(O) (908) 735-9315
(C) (973) 978-9621