Legend

- Soil Boring Location with Exceedances
- Soil Boring Location with No Exceedances
- Fence Boundary
- 41 Sample Result Exceeding NJDEP RDCSRS

Notes

1. All results compared against the 2008 NJDEP Residential Direct Contact Soil Remediation Standards (RDCSRS).
2. The RDCSRS for arsenic is 19 MG/KG
3. The RDCSRS for lead is 400 MG/KG
4. All results are in MG/KG
5. U – Undetected Value
6. J – Estimated Value
7. R – Rejected Result

100 50 0 100 200
Graphic Scale In Feet

Location ID — Collection Depth
Analytical Flag
Analytical Parameter — Concentration (mg/kg)

WESTON SOLUTIONS SM

Weston Solutions, Inc.
205 Campus Drive Edison, New Jersey 08837-3939
TEL: (732) 417-5800 Fax: (732) 417-5801
http://www.westonsolutions.com

SHERWIN Williams

REPORT DATE: MARCH 2011	PROJECT MANAGER: S. Jones	CLIENT NAME: The Sherwin-Williams Company	DRAWING TITLE: FORMER MANUFACTURING PLANT SOIL SAMPLES ARSENIC AND LEAD RESULTS ONLY [NJDEP RESIDENTIAL DIRECT CONTACT SOIL REMEDIATION STANDARDS]
DRAWING PATH: 09016_FMP_Soil_Pb_As.mxd L:/SHERWIN/GIS/MXD /2011_03_FMP_Site_Eval/	CHECKED BY: A. Fischer		
REVISION No. 0	CONTRACT No. / DELIVERY ORDER NO.	PROJECT NAME: Former Manufacturing Plant Remedial Investigation	
WORK ORDER No. 20076.022.079.0005	DRAWN/MODIFIED BY: J. Lynes / DATE CREATED: 02/23/2011		FIGURE: 8 / SCALE: 1" = 100' / DATE: MARCH 2011