SFUND RECORDS CTR
2389872

714-383-3354
x3354

Waste oil tank
— sump in maintenance area.

leach or clarifier system?
— not certain.

Sampling: requested
— cooling tower water
— dross
— sludge from cooling tower.

why? (transported to BKK)
→ as non-hazardous.

corrosion inhibitor?
— not known.

→ adjust pH for brine line treatment

S.B. County — want analysis of water.
— above sampling has not been done as of 6/27/84. → will be notified by Ron Ripley (SB county) when it is done.