1/29/01

- Extraction placement -
  effect on boiler Q
- wheel power ?? Test too diff.
  By mutual agreement !!!
- Bowl pressure tap -
  Bob Brown - Phil Tearny

IP Sta

RH ΔP ~ 7%
creep limited
HP ex P
RH ΔP
HARP ext pt ??

DESK LINED PAGES ©1992, 1996, DAY-TIMERS, Inc. ALLENTOWN, PA 18195-1551 • PRINTED IN USA

IP7006796