2/1/01

1/29-30/01 mtg with Phill Kearney &

Bob Brown

Concerns

- Location of IP Cooling steam supply they are assuming it is HP 2nd stg unless we tell them different
- Our HBD's & pepse models in error if this is the case.
- Is IP cooling steam valve fully open?
- Can we measure IP cooling steam @ 2" orifice? They need P's & T's + flow
- Location of HP turbine inlet P taps on MS leads (2 lines) above turbine @ flange. – JN has WO??
- Need to brief AEN

IP7006811