Turbine Testing
NOTES:

Inspect Basket tips - take pictures

LP Bowl press - explain GE terminology
in calcs

Materials Needed
Swagelock fittings
Stainless steel tubing

IP7010724