design costs

24 left hand
24 right hand ① allow entry into ~~both~~ surface area

prefab. w/ ~~scan~~ lighter and scanner cutouts
② easy of installation

2 price ?

[installation by IPSC or

outside (inner air sleeve attachment)
to facilitate burner nozzle removal and replacement

~~3 holes~~ ~~4th~~

conditions improve flame stability
brightness
shape
controlled reinforcement

1
2 maintain existing performance

provide technical support for installation

3 If they don't work, will reimburse cost of flame stablizers

life - will not warp functionality
will not plug up
will not burnup
perform

Drawing existing burner configuration

attach 2 quotes

sole source

Delivery by October
Outage Installation Date