Econ Gas Out Temps

before / after

Heat absorption not changed
(no heat absorption area affected
no new / or removed surface area
no new SB's

SB erosion shield

Recommend T/C's