RJM Corporation

Richard Monroe
Robert Monroe

Clean Air / Dirty

MassFlow
- PC tubes

instr. sensitivity +/- 3%
good +/- 5%

combustion air flow +/- 5%

2 days on-site
$3500+ expenses

Outline Objects

* On-site Diagnostics Work
→ evaluation

coal distribution
air "

Action Plan

Swirl · incorrectly set

65% → throttling

Justification

Combustion Dynamics

on-line