Flame Concerns

Low flows outside

U1 1+6 burners
fanned out

darker in corners

U2