4/29/04
@ 14:56
Bumped air up

4/30/04
915 H O/S

Investigate

Problems ↑E / ↓W ↑CO 1200+

Surging $2\%O_2$
Why cause need to stop / is it pulv + ΔP
FD fans

Pulv
U2 Eoff / A on

Options PA fan - high speed
↑PA duct press

C
D
E
A