WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO.....	Description.....	Crew No
02-60456-34	UNIT 1 "E" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-35	UNIT 1 "H" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-36	UNIT 1 "A" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-37	UNIT 1 "B" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-38	UNIT 1 "C" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-39	UNIT 1 "D" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-40	UNIT 1 "F" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-41	UNIT 1 "G" MILL, INSTALL (6 ea) BOILER COAL FEED LINE RESTRICTORS IN SUPPLY PIPES.	47
02-60456-42	PROVIDE PAINT SUPPORT TO CREW 47 AT THE COMPLETION OF BOILER FEED PIPE FLOW RESTRICTORS IN ALL UNIT ONE BURNER LINES.	33
02-60456-43	UNIT 1 "H" BURNER LINES, PROVIDE SCAFFOLD SUPPORT AS NEEDED.	97
02-60456-44	UNIT 1 "D" BURNER LINES, PROVIDE SCAFFOLD SUPPORT AS NEEDED.	97
02-60456-45	UNIT 1 BURNER LINES, PROVIDE SCAFFOLD SUPPORT AS NEEDED.	97
02-60456-46	INSULATION SUPPORT WITH REPLACEMENT OF UNIT-1 OVER FIRE AIR 1/3 DAMPER DRIVES AND SUPPORTS.	97
02-60456-47	TIME EXPENDED FOR GARY SPERRY TO MOVE SB STARTER CABINET FOR OVER-FIRE AIR INSTALLATION.	57
02-60456-48	ELECTRICAL SUPPORT DURING THE OUTAGE FOR OVER-FIRE AIR INSTALLATION ON BOILER 9TH & 14TH FLOORS.	61
02-60456-49	UNIT 2 "CONTRACTOR COST TRACKER" (FOR DEAN WOOD) FOR STEAM DRUM MODIFICATIONS DURING OUTAGE.	81
02-60456-50	REPLACE THE PILLOWBLOCK BEARING INSERTS FOR THE OVERFIRE AIR DAMPER LINKAGE	157
02-60456-51	TIME EXPENDED FOR GARY SPERRY AND RON WINTERS TO REMOVE 9TH FLOOR WALL BLOWERS FOR TEI.	157
02-60456-52	ELECTRICAL PREOUTAGE WORK FOR OVER-FIRE AIR INSTALLATION ON BOILER 9TH & 14TH FLOORS.	62

Unit 2

IP7_039424